





report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX 250 4WD EX MWB P/U
Colour	Black
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	999 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

_		•		_	-
-	n	т	rv	,	

LIICI Y I	
Date	2021-06-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/14



GL05UYG
report date: 2024-03-29

MOT history

MOT expiry date	2024-08-19
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	39
Total items failed	4

MOT #18		2023-07-20 13:00
MOT test	number	266344646070
Result		✓ Passed
Next exp	iry date	2024-08-19
Advice	Nearside Rear Leaf spring anchor bracket corroded but not seriously weak	ened (5.3.1 (b) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteri	iorated (6.1.7 (g) (i))
Advice (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not signi	ficantly reduced (6.1.1
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.	.11 (c))
Advice excessive	Offside Rear Suspension component mounting prescribed area is corroded (5.3.6 (a) (i))	but not considered
Advice	Offside Rear Leaf spring anchor bracket corroded but not seriously weaken	ed (5.3.1 (b) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice (6.1.1 (c)	Nearside Rear Vehicle structure is corroded but structural rigidity is not sig (i))	nificantly reduced
Advice excessive	Nearside Rear Suspension component mounting prescribed area is corrode (5.3.6 (a) (i))	ed but not considered

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #17 2023-07-19 12:45

MOT test number 797985084023

Result X Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Rear Leaf spring anchor bracket corroded but not seriously weakened (5.3.1 (b) (i))

Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Rear Leaf spring anchor bracket corroded but not seriously weakened (5.3.1 (b) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1

(c) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2022-07-27 14:04

MOT test number 635915814143

Result
✓ Passed

MOT #15 2022-07-26 13:45

MOT test number 776630214808

Result × Failed

Fail Offside Rear Rear reflector missing (4.8.2 (a) (ii))

Fail Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Fail Rear fog lamp not working (4.5.1 (a) (ii))

CarCheck.co.uk page 4/14



MOT #14

GL05UYG
report date: 2024-03-29

2021-07-22 10:55

MOT test number 164631722594

Result ✓ Passed

Advice Both offside front and nearside front cv gaiters starting to perish

MOT #13 2020-08-17 09:24

MOT test number 998729362162

Advice Nearside rear leaf spring rubber bush deteriorated but not resulting in excessive movement

MOT #12 2019-08-15 09:14

MOT test number 485298903116

Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice Nearside rear leaf spring rubber bush deteriorated but not resulting in excessive movement

MOT #11 2018-07-27 09:41

MOT test number 477902297634

Advice Nearside rear leaf spring shackle bush perished but no movement at time of test

MOT #10 2017-08-17 09:15

MOT test number 779141109193

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #9

MOT test number

540373720360

Result

Advice

Offside Front Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)

MOT #8 2015-08-07 10:20 **MOT** test number 358459215215 Result ✓ Passed MOT #7 2014-08-20 12:50 **MOT** test number 375602134496 Result ✓ Passed MOT #6 2013-08-06 14:02 666158113232 **MOT** test number Result Passed **Notice** Nearside front cv gaiter weeping

MOT test number

Result

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Notice Drivers wiper blade is split

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #4		2011-07-22 09:52
MOT test	number	768173201205
Result		✓ Passed
Advice	Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)	
Notice	O/s/f CV gaiter has a slight seepage of grease from inner clip	
Advice	Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)	

MOT #3	2010-07-30 10:03
MOT test number	144951710237
Result	✓ Passed
MOT #2	2009-07-09 16:38
MOT test number	842210899106
Result	✓ Passed
MOT #1	2008-06-28 08:42
MOT test number	661950788181
Result	√ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29





Days left154MOT expiry date19 August 2024

Full MOT history

See MOT history

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of sisters	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



GL05UYG
report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-06
Last registration	2023-07-20
Complete history	See info



Registration #1	2005-07-06	15 mi
Registration #2	2008-06-28	44.408 mi
Registration #3	2009-07-09	48.379 mi
Registration #4	2010-07-30	52.273 mi
Registration #5	2011-07-22	55.152 mi
Registration #6	2012-07-20	58.308 mi
Registration #7	2013-08-06	61.880 mi
Registration #8	2014-08-20	65.294 mi
Registration #9	2015-08-07	68.559 mi
Registration #10	2016-08-11	72.405 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 au

More info >

CarCheck.co.uk page 13/14



GL05UYG
report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1465 mm
Height	1745 mm
Length	4915 mm
Kerb weight	1615 kg
Max. allowed weight	2515 kg

Additional information

Fuel tank capacity	77 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	2KD1282893

CarCheck.co.uk page 14/14