



report date: 2024-03-29

General information

Make	NISSAN
Model	CABSTAR 35.14 SHR C/C DROPSIDE
Colour	Blue
Year of manufacture	2013
Top speed	84 mph
0 - 60 mph	20.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	270 Nm at 3.200 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.6 mpg
Consumption extra urban	34.9 mpg
Consumption combined	31.4 mpg
CO2 emission	249 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-02-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-04
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	56
Total items failed	1

MOT #14	2023-09-05 12:44
MOT test number	253892052927
Result	✓ Passed
Next expiry date	2024-09-04

MOT #13	2023-08-29 09:08
MOT test number	560184251772
Result	✗ Failed

- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Nearside Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Offside Body mounting fixings missing centre (6.2.2 (c) (i))
- MAJOR** Offside Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Parking brake inoperative on one side low effort (1.4.1 (a))

**MOT #12** 2023-04-11 11:31**MOT test number** 642316246109**Result** ✓ Passed**MOT #11** 2022-04-22 14:19**MOT test number** 793963983997**Result** ✓ Passed**MOT #10** 2021-12-01 12:54**MOT test number** 283410518617**Result** ✓ Passed**MOT #9** 2020-07-21 13:23**MOT test number** 760194920723**Result** ✓ Passed**MOT #8** 2020-06-25 15:29**MOT test number** 838622760431**Result** ✗ Failed**Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Outer Nail in tyre**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-07-02 16:18**MOT test number** 382973574312**Result** ✓ Passed**MOT #6** 2019-06-18 10:09**MOT test number** 672934641576**Result** ✗ Failed

- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- MAJOR** Offside Side repeater missing (4.4.1 (a) (ii))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))
- Advice** Offside Rear Inner tyre flat
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))

**MOT #5** 2018-07-03 11:57**MOT test number** 616510771596**Result** ✓ Passed

- Advice** Various body fixings loose n/s & o/s
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4**

2018-06-26 09:21

**MOT test number**

931829086684

**Result****✗ Failed****DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))**Advice** NSR light cluster broken**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Nearside Side repeater incorrect colour not working but has broken lens (4.4.3 (a))**Advice** Offside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #3**

2017-06-27 08:51

**MOT test number**

183606266101

**Result****✓ Passed****Advice** Shock absorber has a light misting of oil ALL FOUR SHOCKS..... (2.7.3)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #2**

2016-06-17 12:05

**MOT test number**

817612059991

**Result**

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #1**

2016-06-17 12:04

**MOT test number**

910600340775

**Result**

✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Pass with rectification** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
4 September 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	4 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>YJ13CXG</b>
Plate since	2019-09-29
Current registration	<b>YJ13CXG</b>
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-06-19
Last registration	2023-09-05
Complete history	<a href="#">See info</a>



Registration #1	2013-06-19	29 mi
Registration #2	2016-06-17	39.385 mi
Registration #3	2016-06-17	39.385 mi
Registration #4	2017-06-27	46.859 mi
Registration #5	2018-06-26	54.246 mi
Registration #6	2018-07-03	54.272 mi
Registration #7	2019-06-18	63.388 mi
Registration #8	2019-07-02	63.399 mi
Registration #9	2019-09-05	63.399 mi
Registration #10	2019-09-05	63.399 mi
Registration #11	2019-09-05	63.399 mi
Registration #12	2019-09-05	63.399 mi
Registration #13	2019-09-05	63.399 mi
Registration #14	2019-09-05	63.399 mi
Registration #15	2019-09-05	63.399 mi
Registration #16	2019-09-05	63.399 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2265 mm
Height	2122 mm
Length	4909 mm
Kerb weight	1952 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	YD25-28242B