





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|----------------|
| Model | KA ZETEC |
| Colour | Green |
| Year of manufacture | 2009 |
| Top speed | 99 mph |
| 0 - 60 mph | 13.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 68 BHP |
|-------------------------|---------------------|
| Max. torque | 102 Nm at 3.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/13



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-01-14 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 42 |
| Total items failed | 2 |

| MOT #15 | | 2024-01-15 10:04 |
|------------------------|--|--------------------|
| MOT test | number | 938419978970 |
| Result | | ✓ Passed |
| Next exp | iry date | 2025-01-14 |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Front Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |
| Advice adjustme | Rear Parking brake efficiency only just met. It would appear that the brakint or repair. (1.4.2 (a) (i)) | ng system requires |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Minor | Front Windscreen damaged but not adversely affecting driver's view (3.2 (a | a) (i)) |
| Advice | Offside Front Coil spring corroded (5.3.1 (b) (i)) | |

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT #14 2023-01-13 09:57 **MOT** test number 201935316886 Result ✓ Passed **Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2021-01-06 11:59 **MOT** test number 825226966172 ✓ Passed Result Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Items removed from driver's view prior to test Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT test number

Result

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT test number

Result

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #8 | | 2019-01-07 12:14 |
|----------|--|------------------|
| MOT test | number | 729370421348 |
| Result | | ✓ Passed |
| Advice | Exhaust system corroded | |
| Advice | Both front ball joint dust covers deteriorated | |
| Advice | Both rear shock absorbers corroded | |

| MOT #7 | 2018-01-09 16:54 |
|--|------------------|
| MOT test number | 164769957790 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2017-04-20 10:18 |
| MOT test number | 890246769432 |
| Result | ✓ Passed |
| Advice Nearside Rear Shock absorber has a slightly worn bush (2.7.4) | |

| MOT #5 | | 2016-04-21 11:58 |
|----------|-------------------------------|------------------|
| MOT test | number | 388977216001 |
| Result | | ✓ Passed |
| Advice | Wipers are smearing slightly. | |
| Advice | 3tyres cracking. | |

| MOT #4 | | 2015-04-09 15:39 |
|----------|--------------------------------|------------------|
| MOT test | number | 319299995053 |
| Result | | ✓ Passed |
| Notice | Offside rear tyre is perished. | |
| Notice | Rear silencer casing corroded. | |
| Notice | Rear coil spring is corroded. | |

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3

MOT test number

Result

Notice Rear exhaust section slightly corroded

2014-04-23 12:45

308903714179

✓ Passed

MOT test number
915808803127

Result

Advice Offside Rear Shock absorber has a slightly worn bush (2.7.4)

Notice Rear exhaust corroding

Advice Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

Notice N/s/f tyre wearing low on edge

| MOT #1 | 2012-04-27 13:08 |
|-----------------|------------------|
| MOT test number | 517428512146 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 14 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
|--|---|
| | |
| manus . | |
| *************************************** | |
| *************************************** | |
| | |
| manus . | |
| *************************************** | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| parameter parame | |
| | |
| Number of plates | |
| Current registration | SIES UK |
| | UK (|
| Plate since | |
| Current registration | NIE AND |
| Plate since | |
| | |
| | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2009-04-17 |
| Last registration | 2024-01-15 |
| Complete history | See info |



| Registration #1 | 2009-04-17 | 18 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-04-27 | 27.400 mi |
| Registration #3 | 2013-04-18 | 31.255 mi |
| Registration #4 | 2014-04-23 | 35.644 mi |
| Registration #5 | 2015-04-09 | 41.685 mi |
| Registration #6 | 2016-04-21 | 45.873 mi |
| Registration #7 | 2017-04-20 | 48.852 mi |
| Registration #8 | 2018-01-09 | 50.882 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 10.700 au |
| | | |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1702 mm |
|---------------------|---------|
| Height | 1505 mm |
| Length | 3620 mm |
| Wheel base | 2300 mm |
| Kerb weight | 940 kg |
| Max. allowed weight | 1320 kg |

Additional information

| Fuel tank capacity | 35 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 13/13 |

Number of axles2Engine number5187434