



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA BREEZE HI-TORQ
Colour	Blue
Year of manufacture	-
Top speed	90 mph
0 - 60 mph	14.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	59 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.1 mpg
Consumption extra urban	42.2 mpg
Consumption combined	33.2 mpg






LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-28
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #21**

2021-10-27 13:13

MOT test number

945322990854

Result**✗ Failed**

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits lambda reading incorrect (8.2.1.2 (c))

Advice Cooling system expansion bottle empty of water / topped up cooling system

Advice Signs of water leaking from engine / signs of coming from back of front engine mount / poss core bung

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits co reading incorrect (8.2.1.2 (a))

Advice Engine oil very low / topped up 2lts

Advice Signs of blue smoke being emitted from exhaust

Advice Brake load sensor valve lever sticking slightly / advise to free off / lube up

MOT #20

2020-11-17 17:06

MOT test number

361739961207

Result**✓ Passed**

Advice Washers slightly weak

Advice Underside / components showing general surface corrosion

Advice Front brake discs becoming slightly surface corroded on edges / starting to encroach on to braking surface

**MOT #19**

2020-10-29 10:10

MOT test number

776539671696

Result

✗ Failed

Fail

Nearside Front Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect limited damping effect (5.3.2 (b))

MOT #18

2019-11-22 08:24

MOT test number

574799520246

Result

✓ Passed

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #17

2019-11-12 14:14

MOT test number

871198135801

Result

✗ Failed

Fail

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #16**

2018-10-24 09:55

MOT test number

461971494351

Result

✓ Passed

Advice Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #15

2018-10-12 08:07

MOT test number

794445921546

Result

✗ Failed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Rear Brake load sensing valve linkage defective and function impaired (1.1.17 (a))

Advice Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))



MOT #142015-03-06 11:19

MOT test number177355965468

Result

✓ Passed

- Advice

Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Notice

Oil leak
- Advice

Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice

Tyre worn close to the legal limit (4.1.E.1)
- Notice

Nail in rear tyre
- Advice

Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice

Offside Rear wheel bearing has slight play (2.6.2)
- Advice

Body has slight corrosion (6.1.B.2)

**MOT #13**

2015-03-03 15:10

MOT test number

458032065005

Result**✗ Failed**

- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Oil leak
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Rear wheel bearing has excessive play (2.6.2)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Nail in rear tyre
- Advice** Offside Rear wheel bearing has slight play (2.6.2)
- Advice** Body has slight corrosion (6.1.B.2)

MOT #12

2014-03-04 12:22

MOT test number

599403364005

Result**✓ Passed**

- Advice** Rear wheel bearing has slight play (2.6.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear ends of both inner sills weak
- Notice** Oil leak

**MOT #11** 2014-03-04 09:44**MOT test number** 129663664041**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear wheel bearing has slight play (2.6.2)**Notice** Oil leak**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear ends of both inner sills weak**MOT #10** 2013-03-04 10:14**MOT test number** 448783763091**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2012-03-05 12:36**MOT test number** 698925062098**Result** ✓ Passed**Notice** Slight corrosion rear end of both inner sills**MOT #8** 2012-03-05 08:39**MOT test number** 235045962066**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Slight corrosion rear end of both inner sills**Fail** Registration plate lamp not working (1.1.C.1d)



MOT #7	2011-03-07 09:42
MOT test number	315746461003
Result	✓ Passed

MOT #6	2010-03-08 16:44
MOT test number	492457060047
Result	✓ Passed
<div>Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)</div>	

MOT #5	2009-02-26 16:33
MOT test number	882217959090
Result	✓ Passed

MOT #4	2008-03-05 11:23
MOT test number	952815268046
Result	✓ Passed



MOT #3	2008-02-27 10:08
MOT test number	422188358070
Result	✗ Failed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
Fail	Nearside Headlamp aim too low (1.8)
Notice	Rear tyres perrished.
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Offside Headlamp aim too low (1.8)
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2	2007-03-01 15:55
MOT test number	102220967052
Result	✓ Passed

MOT #1	2006-02-22 09:08
MOT test number	240123756099
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 R102EBH
Plate since	2015-01-01
Current registration	 R102EBH
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	1998-02-26
Last registration	2021-10-27
Complete history	See info



Registration #1	1998-02-26	25 mi
Registration #2	2006-02-22	24.948 mi
Registration #3	2007-03-01	31.883 mi
Registration #4	2008-02-27	34.935 mi
Registration #5	2008-03-05	34.952 mi
Registration #6	2009-02-26	41.682 mi
Registration #7	2010-03-08	48.801 mi
Registration #8	2011-03-07	54.530 mi
Registration #9	2012-03-05	60.060 mi
Registration #10	2012-03-05	60.060 mi
Registration #11	2013-03-04	66.796 mi
Registration #12	2014-03-04	73.311 mi
Registration #13	2015-03-04	79.826 mi
Registration #14	2016-03-04	86.341 mi
Registration #15	2017-03-04	92.856 mi
Registration #16	2018-03-04	99.371 mi
Registration #17	2019-03-04	105.886 mi
Registration #18	2020-03-04	112.401 mi
Registration #19	2021-03-04	118.916 mi
Registration #20	2022-03-04	125.431 mi
Registration #21	2023-03-04	131.946 mi
Registration #22	2024-03-04	138.461 mi
Registration #23	2025-03-04	144.976 mi

More info >



Safety ratings

NCAP rating	★ ★ ★ ★ ★
Video	see crash video



Dimensions & weight

Width	1768 mm
Height	1420 mm
Length	3741 mm
Wheel base	2491 mm
Kerb weight	895 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Single-Point Injection
Number of doors	5
Number of axles	2
Engine number	02HY2027