



N719XFJ

report date: 2024-03-28

General information

Make	MAZDA
Model	BONGO
Colour	Black
Year of manufacture	1995
Gearbox	-

Engine & fuel consumption

Engine capacity	2.490 cc
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-02-18
MOT pass rate	56 %
MOT passed	15
Failed MOT tests	12
Total advice items	41
Total items failed	44

MOT #27 2020-02-19 10:48

MOT test number 111558613962

Result ✓ Passed

Next expiry date 2021-02-18

- Advice** Anti-roll bar linkage ball joint has slight play both front (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Fluid leak, but not excessive power steering (8.4.1 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #26 2020-02-10 14:37

MOT test number 535911377591

Result ✗ Failed

- Advice** Anti-roll bar linkage ball joint has slight play both front (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Fluid leak, but not excessive power steering (8.4.1 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Emissions not tested due to excessive black smoke being emitted (8.2.2.2 (e))

**MOT #25** 2018-09-14 14:30**MOT test number** 682065581652**Result** ✓ Passed**MOT #24** 2018-09-14 10:17**MOT test number** 324075251687**Result** ✗ Failed**Fail** Offside Rear Vehicle structure is deformed and structural rigidity is significantly reduced (6.1.1 (a) (i))**MOT #23** 2017-08-21 14:43**MOT test number** 209256586476**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #22** 2017-08-21 08:57**MOT test number** 369716227816**Result** ✗ Failed**Fail** Offside Rear Inner Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Inner Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement D bush (2.4.G.2)**Fail** Rear fog lamp not working (1.3.2b)**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded inner sill (2.4.A.3)**Advice** Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #21	2016-09-09 16:33
MOT test number	997107578957
Result	✓ Passed

MOT #20	2016-09-06 11:16
MOT test number	746316423859
Result	✗ Failed

Fail Emissions not tested exhaust leak (7.4.B.1)

Fail Nearside Front Suspension component mounting prescribed area is excessively corroded cross member (2.4.A.3)

Fail Offside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)

Fail Exhaust has a major leak of exhaust gases (7.1.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension component mounting prescribed area is excessively corroded cross member (2.4.A.3)

Advice Slight binding front brakes

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #19**

2016-03-18 08:04

MOT test number

868010016163

Result**✗ Failed**

Fail Offside Front Suspension component mounting prescribed area is excessively corroded cross member (2.4.A.3)

Fail Rear fog lamp not working (1.3.2b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Nearside Front Suspension component mounting prescribed area is excessively corroded cross member (2.4.A.3)

Fail Offside Headlamp not working on main beam (1.7.5a)

Advice Offside Power steering component(s) has slight seepage from a component steering rack (2.3.3b)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Rear Outer Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)

MOT #18

2015-03-19 12:47

MOT test number

445198575024

Result**✓ Passed**

Advice Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #17**

2015-03-16 16:10

MOT test number

138365475497

Result

✗ Failed

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on main beam (1.7.5a)**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Advice** Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)**MOT #16**

2014-03-19 10:55

MOT test number

587668074083

Result

✓ Passed

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**MOT #15**

2014-03-18 11:13

MOT test number

656377374040

Result

✗ Failed

Fail Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Horn not working (1.6.2a)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**MOT #14**

2013-06-14 16:10

MOT test number

858915863159

Result

✓ Passed

**MOT #13**

2013-06-14 12:51

MOT test number

738925063140

Result**✗ Failed**

Fail Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Offside Inner Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

Fail Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Inner Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #12

2013-01-15 11:57

MOT test number

507975413063

Result**✓ Passed**

Advice Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Outer Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #11

2013-01-15 11:57

MOT test number

856115413093

Result**✗ Failed**

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Advice Nearside Front Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Outer Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #10**

2012-01-24 10:45

MOT test number

968524622017

Result

✓ Passed

Notice Slight dampness around steering rack pinion**Notice** O/s/f inner sill surface corrosion**MOT #9**

2012-01-20 12:26

MOT test number

599030722065

Result

✗ Failed

Fail Nearside Rear Stop lamp not working (1.2.1b)**Notice** Slight dampness around steering rack pinion**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Front Lower Ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Notice** O/s/f inner sill surface corrosion**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Lower Ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**MOT #8**

2011-01-25 12:54

MOT test number

307645921049

Result

✓ Passed

Notice Suspension joint nearside lower dust cover split/missing**Notice** Front discs starting to wear**Notice** Slight fluid leak from steering rack

**MOT #7** 2010-01-19 08:20**MOT test number** 770699410083**Result** ✓ Passed**Notice** Suspension joint nearside lower dust cover split/missing**Notice** Slight leak from injection pump**Notice** Slight fluid leak from power steering**MOT #6** 2009-01-23 12:05**MOT test number** 623833129043**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #5** 2009-01-23 07:32**MOT test number** 163363729017**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Rear fog lamp missing (1.3.2a)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2008-01-21 08:11**MOT test number** 114131328488**Result** ✓ Passed**MOT #3** 2007-01-17 08:34**MOT test number** 122697517019**Result** ✓ Passed



MOT #2	2007-01-17 08:34
MOT test number	841777217026
Result	✗ Failed
<div>Pass with rectification</div> Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #1	2006-01-26 08:31
MOT test number	800396826066
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	26
First mileage registration	2004-02-01
Last registration	2020-02-19
Complete history	See info



Registration #1	2004-02-01	17 mi
Registration #2	2006-01-26	77.475 mi
Registration #3	2007-01-17	137.748 mi
Registration #4	2008-01-21	148.646 mi
Registration #5	2009-01-23	100.002 mi
Registration #6	2009-01-23	100.002 mi
Registration #7	2010-01-19	108.531 mi
Registration #8	2011-01-25	114.538 mi
Registration #9	2012-01-20	192.011 mi
Registration #10	2012-01-24	119.344 mi
Registration #11	2013-01-15	124.689 mi
Registration #12	2013-06-14	126.599 mi
Registration #13	2013-06-14	126.599 mi
Registration #14	2013-06-14	126.599 mi
Registration #15	2013-06-14	126.599 mi
Registration #16	2013-06-14	126.599 mi
Registration #17	2013-06-14	126.599 mi
Registration #18	2013-06-14	126.599 mi
Registration #19	2013-06-14	126.599 mi
Registration #20	2013-06-14	126.599 mi
Registration #21	2013-06-14	126.599 mi
Registration #22	2013-06-14	126.599 mi
Registration #23	2013-06-14	126.599 mi
Registration #24	2013-06-14	126.599 mi
Registration #25	2013-06-14	126.599 mi
Registration #26	2013-06-14	126.599 mi

More info >



Additional information

Engine number	NOT KNOWN
---------------	-----------