





report date: 2024-03-29

General information

Make	KIA
Model	CARENS GS5 CRDI
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/14



YS08EFW report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-21

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT #18 2020-12-21 16:05

MOT test number 297329213176

Result
✓ Passed

Next expiry date 2021-12-20

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice EML Illuminated

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 205 60 R16 (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 205 60 R16 (5.2.3 (e))

MOT #17 2020-12-18 09:25

MOT test number 738302457074

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 205 60 R16 (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 205 60 R16 (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice EML Illuminated

Fail Offside Front Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16 2019-06-13 14:32 790350510211 **MOT** test number Result ✓ Passed **MOT #15** 2019-06-13 10:32 **MOT test number** 467802258510 Result × Failed Nearside Parking brake inoperative on one side (1.4.1 (a)) Fail Fail Offside Front Position lamp not working (4.2.1 (a)) Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #14

MOT test number

Result

Advice

Offside Parking brake inoperative on one side (1.4.1 (a))

2019-03-29 12:48

181926748819

✓ Passed

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))


Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29



MOT #12		2017-05-20 09:28
MOT test	number	825731660275
Result		✓ Passed
Advice Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear vi Front Brake pad(s) wearing thin (3.5.1g)	ew (8.1.2a)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #11 2017-05-20 09:28

MOT test number 565573724466

Result X Failed

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Pass with rectification Nearside Headlamp not working on main beam (1.7.5a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #10 2016-05-18 15:37

MOT test number 244004253602

Result ✓ Passed

MOT #9 2016-05-06 09:53

MOT test number 274616328999

Result X Failed

Fail Parking brake lever has no reserve travel (3.1.6b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #8 2015-04-20 10:33

MOT test number 496800315161

Result
✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

Notice Rear brake pads look low

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #7 2015-04-20 10:33 277470615454 **MOT** test number Result **X** Failed **Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Parking brake lever has little reserve travel (3.1.6b) Notice Rear brake pads look low Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

 MOT #6
 2014-04-25 15:29

 MOT test number
 289965314454

 Result
 ✓ Passed

MOT test number

Result

Pass with rectification

Offside Front coil spring broken (2.4.C.1a)

Pass with rectification

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification

Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #4

MOT test number

Result

Advice Front brake drum worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Headlamp aim too low (1.8)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1	2011-04-11 11:49
MOT test number	187481101164
Result	✓ Passed
Notice Front and rear number plates peeling	

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

YS08EFW

report date: 2024-03-29

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-30
Last registration	2020-12-21
Complete history	See info



Registration #1	2008-05-30	23 mi
Registration #2	2011-04-11	47.222 mi
Registration #3	2012-05-08	55.665 mi
Registration #4	2013-05-01	61.426 mi
Registration #5	2013-05-01	61.426 mi
Registration #6	2014-04-25	67.668 mi
Registration #7	2015-04-20	74.517 mi
Registration #8	2016-05-06	79.202 mi
Registration #9	2016-05-18	79.202 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1631 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number D4EA8H382090