



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA LS 16V
Colour	Silver
Year of manufacture	2004
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	170 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.2 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-12
Pictures	3
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-12
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

**MOT history**

MOT expiry date	2023-02-21
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	59
Total items failed	18

MOT #24 2022-02-22 13:46**MOT test number** 253638913266**Result** Passed**Next expiry date** 2023-02-21

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #23 2021-01-21 16:08**MOT test number** 325515124886**Result** Passed

- Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22**

2021-01-15 10:49

MOT test number

149265355518

Result**✗ Failed****Fail** Offside Headlamp light intensity severely reduced no image (4.1.4 (a))**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp light intensity severely reduced no image (4.1.4 (a))**Fail** Oil leaking excessively from engine from oil pressure switch (8.4.1 (a) (i))**Fail** Emissions not tested vehicle not able to maintain fast idle speed (8.2.1.2 (d))**MOT #21**

2019-12-19 15:55

MOT test number

855843600184

Result**✓ Passed****MOT #20**

2019-12-19 09:26

MOT test number

377925309081

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19**

2019-01-14 16:52

MOT test number

786087281249

Result**✓ Passed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Both front headlamp lenses deteriorating

**MOT #18**

2019-01-12 11:32

MOT test number

615108066919

Result**✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Brake pipe excessively corroded both front to rear (1.1.11 (c))**Advice** Both front headlamp lenses deteriorating**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #17**

2018-01-13 11:57

MOT test number

974914860051

Result**✓ Passed****Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Headlamp damaged but light output not reduced (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #16**

2018-01-13 10:26

MOT test number

596071883434

Result**✗ Failed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Headlamp damaged but light output not reduced (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #15** 2017-01-14 10:54**MOT test number** 687792116218**Result** ✓ Passed**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #14** 2016-01-16 09:08**MOT test number** 525468443926**Result** ✓ Passed**MOT #13** 2016-01-09 09:34**MOT test number** 176305003201**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #12** 2015-01-17 10:29**MOT test number** 308837115048**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Tyre size 215/55x16

**MOT #11**

2015-01-10 11:56

MOT test number

888240415097

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Tyre size 215/55x16**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2014-01-13 12:57

MOT test number

825733914053

Result**✓ Passed****Advice** Offside Front Upper Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2013-01-04 12:04

MOT test number

249774303029

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)

**MOT #8** 2012-01-06 12:22**MOT test number** 335996902077**Result** ✓ Passed

- Advice** Centre Brake pipe slightly corroded (3.6.B.2c)
- Notice** Rear exhaust corroded
- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-01-07 11:08**MOT test number** 349397101063**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Brake pipe slightly corroded (3.6.B.2c)

MOT #6 2011-01-07 11:08**MOT test number** 917627901057**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Brake pipe slightly corroded (3.6.B.2c)

**MOT #5** 2010-01-11 16:46**MOT test number** 213821710047**Result** ✓ Passed**Notice** Non obligatory mirror damaged**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2010-01-11 12:45**MOT test number** 544481910013**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has negligible damping effect (2.7.5)**Notice** Non obligatory mirror damaged**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #3** 2009-01-12 09:14**MOT test number** 120922919481**Result** ✓ Passed**Notice** Non obligatory mirror damaged**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2008-01-17 12:15**MOT test number** 193557218083**Result** ✓ Passed**MOT #1** 2007-03-12 10:53**MOT test number** 630401477019**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
18 October 2022

✕
MOT

Expired:
21 February 2023

Tax status	Expired at 18 October 2022
Days left	559 days too late
MOT expiry date	21 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KB53FKF
Plate since	2024-03-29
Current registration	 KB53FKF
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-02-23
Last registration	2022-02-22
Complete history	See info



Registration #1	2004-02-23	9 mi
Registration #2	2007-03-12	24.990 mi
Registration #3	2008-01-17	28.477 mi
Registration #4	2009-01-12	33.693 mi
Registration #5	2010-01-11	39.839 mi
Registration #6	2010-01-11	39.839 mi
Registration #7	2011-01-07	45.923 mi
Registration #8	2012-01-06	52.514 mi
Registration #9	2013-01-04	59.580 mi
Registration #10	2014-01-13	65.616 mi
Registration #11	2015-01-10	72.241 mi
Registration #12	2015-01-17	72.413 mi
Registration #13	2016-01-09	80.178 mi
Registration #14	2016-01-09	80.178 mi
Registration #15	2016-01-09	80.178 mi
Registration #16	2016-01-09	80.178 mi
Registration #17	2016-01-09	80.178 mi
Registration #18	2016-01-09	80.178 mi
Registration #19	2016-01-09	80.178 mi
Registration #20	2016-01-09	80.178 mi
Registration #21	2016-01-09	80.178 mi
Registration #22	2016-01-09	80.178 mi
Registration #23	2016-01-09	80.178 mi
Registration #24	2016-01-09	80.178 mi
Registration #25	2016-01-09	80.178 mi
Registration #26	2016-01-09	80.178 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1845 mm
Height	1425 mm
Length	4495 mm
Wheel base	2700 mm
Kerb weight	1357 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	20CS8463