



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE ATLANTIC
Colour	Red
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-27
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-02-22
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	53
Total items failed	33

**MOT #22**

2023-04-06 10:52

MOT test number

769044337236

Result**✗ Failed****Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened /suspension corroded (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Windscreen washer not working (3.5 (a))**Advice** Body corroded**Fail** Nearside Front Sub-frame damaged and seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Fail** Emissions unable to be completed due to exhaust condition (8.2.1.2 (d))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #21** 2022-02-23 17:47**MOT test number** 110574424895**Result** ✓ Passed**MOT #20** 2022-02-07 16:59**MOT test number** 842833609317**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #19** 2021-02-01 10:45**MOT test number** 585162074822**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #18** 2021-01-26 09:42**MOT test number** 492277758649**Result** ✗ Failed**Fail** Offside Front Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #17** 2020-01-22 17:22**MOT test number** 605716230963**Result** ✓ Passed**Advice** Offside Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #16	2019-02-20 16:07
MOT test number	992369708894
Result	✓ Passed

MOT #15	2019-02-18 16:25
MOT test number	141022118026
Result	✗ Failed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Offside Rear Brake pipe excessively corroded to flex hose (1.1.11 (c))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Anti-roll bar linkage insecurely attached adrift (5.3.3 (a) (i))
- Fail** Nearside Rear Brake pipe excessively corroded to flex hose (1.1.11 (c))
- Advice** Offside Power steering pipe/hose has slight seepage (2.1.5 (a))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2018-06-29 09:41

MOT test number

280924319833

Result

✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Macpherson strut corroded but not seriously weakened both (5.3.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Macpherson strut corroded but not seriously weakened both front (5.3.3 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13**

2018-06-27 11:23

MOT test number

272141951990

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Macpherson strut corroded but not seriously weakened both (5.3.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Macpherson strut corroded but not seriously weakened both front (5.3.3 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2018-06-20 13:03

MOT test number

144321459845

Result

✗ Failed

- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Macpherson strut corroded but not seriously weakened all four ,change asap (5.3.3 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

2017-06-20 08:17

MOT test number

759262326949

Result

✓ Passed

- Advice** Rear exhaust connecting section corroded
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10

2016-06-25 10:37

MOT test number

266999438116

Result

✓ Passed

**MOT #9** 2015-07-01 11:23**MOT test number** 117802685158**Result** ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #8 2014-06-16 15:44**MOT test number** 208207064474**Result** ✓ Passed

Notice Slightly poor output on nearside headlight beam

Notice Corrosion build up on fuel filler neck and breather pipes

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

MOT #7 2014-06-12 09:39**MOT test number** 829663164139**Result** ✗ Failed

Notice Fuel tank filler/overflow pipes badly corroded.

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #6 2013-06-11 16:42**MOT test number** 286902863417**Result** ✓ Passed

**MOT #5** 2012-06-20 09:25**MOT test number** 909832672130**Result** ✓ Passed**Notice** Fuel filler neck protection plate at exhaust corroded.**MOT #4** 2011-07-06 15:41**MOT test number** 329587981136**Result** ✓ Passed**MOT #3** 2011-07-04 14:35**MOT test number** 198865481172**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2010-06-15 12:23**MOT test number** 584876760113**Result** ✓ Passed**MOT #1** 2009-06-11 14:37**MOT test number** 781182569122**Result** ✓ Passed**Notice** High level brake light has elements not working, but over 50% are working.



Tax & MOT check

X

Untaxed

Tax expired:
30 April 2023

X

MOT

Expired:
22 February 2023

Tax status	Expired at 30 April 2023
Days left	366 days too late
MOT expiry date	22 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-07-04
Last registration	2023-04-06
Complete history	See info



Registration #1	2006-07-04	24 mi
Registration #2	2009-06-11	27.470 mi
Registration #3	2010-06-15	33.580 mi
Registration #4	2011-07-04	42.303 mi
Registration #5	2011-07-06	42.299 mi
Registration #6	2012-06-20	45.569 mi
Registration #7	2013-06-11	49.314 mi
Registration #8	2014-06-12	54.659 mi
Registration #9	2014-06-16	54.711 mi
Registration #10	2015-07-01	59.079 mi
Registration #11	2016-06-25	61.055 mi
Registration #12	2017-06-20	62.360 mi
Registration #13	2018-06-20	63.377 mi
Registration #14	2019-06-20	64.394 mi
Registration #15	2020-06-20	65.411 mi
Registration #16	2021-06-20	66.428 mi
Registration #17	2022-06-20	67.445 mi
Registration #18	2023-04-06	68.462 mi
Registration #19	2023-04-06	68.462 mi
Registration #20	2023-04-06	68.462 mi
Registration #21	2023-04-06	68.462 mi
Registration #22	2023-04-06	68.462 mi
Registration #23	2023-04-06	68.462 mi
Registration #24	2023-04-06	68.462 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1382 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6670361