





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | COUPE V6 |
| Colour | Black |
| Year of manufacture | 2006 |
| Top speed | 135 mph |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| Power | 165 BHP |
|-------------------------|---------------------|
| Max. torque | 245 Nm at 4.000 rpm |
| Engine capacity | 2.656 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 19.9 mpg |
| Consumption extra urban | 35.3 mpg |
| Consumption combined | 27.4 mpg |
| CO2 emission | 247 g/km |
| CO2 label | L |



CarCheck.co.uk page 1/17



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-06

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-01-21 |
|--------------------|------------|
| MOT pass rate | 65 % |
| MOT passed | 15 |
| Failed MOT tests | 8 |
| Total advice items | 61 |
| Total items failed | 24 |

| MOT #23 | | 2024-01-22 15:20 |
|---------------------------|--|------------------|
| MOT test number 732432351 | | 732432351741 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-21 |
| Advice | Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) | |
| Advice | Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) | |
| Advice | Nearside Front Coil spring corroded (5.3.1 (b) (i)) | |

CarCheck.co.uk page 3/17



(b) (ii))

NU06XTC

report date: 2024-03-28

MOT #22 2024-01-22 15:20 **MOT** test number 939025478294 Result **X** Failed **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Pass with rectification Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii)) Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #21

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/17



Fail

NU06XTC

report date: 2024-03-28

MOT #20 2022-12-07 10:03 **MOT** test number 132343560616 Result × Failed Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Windscreen wiper not working (3.4 (a)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Electronic stability control warning lamp indicates a fault (7.12 (e)) Fail **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

| MOT #19 | | 2021-10-08 15:32 |
|------------|--|--------------------|
| MOT test | number | 481232763002 |
| Result | | ✓ Passed |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or light | sources (4.7.1 (b) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e)) | |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii)) | |

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

CarCheck.co.uk page 5/17



report date: 2024-03-28

291477322920

MOT #18 2021-10-02 07:51

MOT test number 484755878347

Result × Failed

Fail Offside Front Driver's door does not latch securely closed (6.2.3 (a))

Advice Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Electrical wiring inadequately secured battery clamp (4.11 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Fail Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))

Fail Front Position lamp light intensity significantly reduced both flashing (4.2.3 (a) (ii))

Fail Nearside Windscreen wiper not working (3.4 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #17 2020-10-03 08:13

Advice Nearside Front Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Extra mirrors fitted in side car

MOT test number

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))

Advice Offside Front Side repeater slightly discoloured (4.4.3 (a))

Advice Offside Front Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Nearside Front Side repeater slightly discoloured (4.4.3 (a))

CarCheck.co.uk page 6/17



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Nail in tyre

Advice Oil leak, but not excessive sump pan (8.4.1 (a) (i))

Advice Exhaust has a minor leak of exhaust gases front flexi joint (6.1.2 (a))

MOT test number

Result

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a))

Advice

Oil leak, but not excessive sump pan (8.4.1 (a) (i))

Advice

Exhaust has a minor leak of exhaust gases front flexi joint (6.1.2 (a))

Advice

Offside Rear Nail in tyre

MOT #14

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #13

MOT test number

449590180844

Result

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 7/17



(2.5.C.1a)

Advice

NU06XTC

report date: 2024-03-28

MOT #12 2017-04-25 09:03

MOT test number 208790132961

Result × Failed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Front brake application uneven (3.7.B.2)

Nearside Registration plate lamp not working (1.1.C.1d) Fail

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail

Front registration plate deteriorated (6.3.1d) Fail

2016-04-23 08:57 **MOT #11**

841430461638 **MOT** test number

Result ✓ Passed

Advice Handbrake performance close to minimum requirement.

Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt Advice

2016-04-16 08:54 **MOT #10**

MOT test number 790297725121

Result × Failed

Advice Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit 215/45x17 (4.1.E.1) Handbrake performance close to minimum requirement.

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 215/45x17 (4.1.E.1)

CarCheck.co.uk page 8/17



Result

NU06XTC

report date: 2024-03-28

Passed

MOT #9 2015-05-09 10:47
MOT test number 968819725175
Result ✓ Passed

Notice Heavey surface corrosion noted to centre exhaust.

MOT #8 2014-04-24 09:50

MOT test number 415474714115

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2014-04-24 09:50

MOT test number 735574814174

Result X Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2013-05-11 09:01

MOT test number 415301733164

Result ★ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Front position lamp(s) not working (1.1.A.3b)

MOT #5 2013-05-11 09:01

MOT test number 217131133408

Result

Passed

CarCheck.co.uk page 9/17



report date: 2024-03-28

| MOT #4 | | 2012-04-14 08:30 |
|----------|-----------------------------------|------------------|
| MOT test | number | 339485402129 |
| Result | | ✓ Passed |
| Notice | 1 bulb out in centre stop lamp | |
| Notice | Front and rear brake discs lipped | |

| MOT #3 | | 2011-04-04 10:03 |
|----------|---|------------------|
| MOT test | number | 857434291069 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Power steering pipe(s) or hose(s) has slight seepage (2.3.3b) | |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) | |

| MOT #2 | 2010-04-16 10:05 |
|-----------------|------------------|
| MOT test number | 993346700140 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2009-04-09 16:55 |
| MOT test number | 260909999087 |
| Result | ✓ Passed |

CarCheck.co.uk page 10/17



NU06XTC report date: 2024-03-28

Tax & MOT check



✓ MOT

Tax expired:

10 January 2024

Expires:
21 January 2025

Expired at 10 January 2024

Days left 109 days too late

MOT expiry date 21 January 2025

Full MOT history See MOT history

Tax calculation

Tax status

| Vehicle class | 48 |
|---|------------|
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 11/17



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r | |
|--|-------------|
| | |
| MARKET CONTRACTOR CONT | |
| | |
| | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | UK AIS |
| Flate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 14/17



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 23 |
| First mileage registration | 2006-04-20 |
| Last registration | 2024-01-22 |
| Complete history | See info |



| Registration #1 | 2006-04-20 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2009-04-09 | 32.058 mi |
| Registration #3 | 2010-04-16 | 46.782 mi |
| Registration #4 | 2011-04-04 | 61.438 mi |
| Registration #5 | 2012-04-14 | 63.198 mi |
| Registration #6 | 2013-05-11 | 65.832 mi |
| Registration #7 | 2014-04-24 | 68.932 mi |
| Registration #8 | 2015-05-09 | 73.882 mi |
| Registration #9 | 2016-04-16 | 78.207 mi |
| Registration #10 | 2016-04-23 | 78.302 mi |
| Registration #11 | 2017-04-25 | 82.503 mi |
| Registration #12 | 2017-04-26 | 82.517 mi |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.177 ea |
| Registration #15 | | 11.177 es |
| Registration #16 | | 11.117 es |
| Registration #17 | | 11.177 es |
| Registration #18 | | 11.117 es |
| Registration #19 | | 11.177 es |
| Registration #20 | | 11.177 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.117 es |
| Registration #23 | | 70.777 mg |

More info >

CarCheck.co.uk page 16/17



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| S0569 | |

Dimensions & weight

| Width | 1760 mm |
|---------------------|---------|
| Height | 1330 mm |
| Length | 4395 mm |
| Wheel base | 2530 mm |
| Kerb weight | 1335 kg |
| Max. allowed weight | 1760 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | G6BA5354638 |

CarCheck.co.uk page 17/17