



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2006
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-09-23
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-12
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	36
Total items failed	23

MOT #23	2024-04-13 14:43
MOT test number	630890118051
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

MOT #22	2024-04-13 11:51
MOT test number	463667932091
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
Fail	Windscreen washer not working (3.5 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Front Position lamp not working (4.2.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21** 2023-04-12 13:59**MOT test number** 563845370092**Result** ✓ Passed**MOT #20** 2023-04-11 12:28**MOT test number** 855793521454**Result** ✗ Failed

- Fail** Emissions unable to be completed (8.2.1.2 (d))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases down pipe (6.1.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #19** 2021-12-16 16:25**MOT test number** 967897770646**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #18**

2020-12-11 12:49

**MOT test number**

102023058801

**Result**

✓ Passed

**Advice** Nearside Rear Inner Suspension arm attachment bracket/mounting damaged but its strength is not seriously reduced (5.3.3 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Lower Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #17**

2020-12-11 12:49

**MOT test number**

364591543602

**Result**

✗ Failed

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Lower Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Rear Inner Suspension arm attachment bracket/mounting damaged but its strength is not seriously reduced (5.3.3 (b) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #16**

2019-12-11 12:28

**MOT test number**

944298015754

**Result**

✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2018-12-10 10:19**MOT test number** 915383840263**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2017-12-05 11:56**MOT test number** 794816875632**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit BOTH TYRES INNER EDGES (4.1.E.1)**MOT #13** 2017-12-05 11:56**MOT test number** 758440446183**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear Tyre worn close to the legal limit BOTH TYRES INNER EDGES (4.1.E.1)**MOT #12** 2016-12-12 15:57**MOT test number** 428645954418**Result** ✓ Passed

**MOT #11** 2016-12-09 14:38**MOT test number** 529588645453**Result** ✗ Failed

- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Nearside Front Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #10** 2015-11-21 15:09**MOT test number** 532166342608**Result** ✓ Passed**MOT #9** 2015-11-21 10:53**MOT test number** 252189403116**Result** ✗ Failed

- Fail** Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #8** 2014-12-10 14:33**MOT test number** 138834744312**Result** ✓ Passed

**MOT #7**

2014-12-06 09:25

**MOT test number**

799610044378

**Result**

✗ Failed

**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Both front tyres worn on edges**Fail** Nearside Headlamp aim too low (1.8)**Notice** Both rear tyres perishing**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #6**

2013-12-12 10:23

**MOT test number**

327816543368

**Result**

✓ Passed

**Notice** Exhaust Flexi Pipe is deteriorating.**Notice** Front Discs are worn, replace in 3,000 miles.**MOT #5**

2012-11-18 10:54

**MOT test number**

597003922346

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4**

2011-12-10 10:36

**MOT test number**

538924041383

**Result**

✓ Passed





MOT #3	2010-11-26 11:17
MOT test number	200540730368
Result	✓ Passed
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #2	2010-11-26 11:17
MOT test number	881650730336
Result	✗ Failed
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #1	2009-12-12 11:29
MOT test number	680606249313
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
12 April 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	12 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK56XMG
Plate since	2019-09-28
Current registration	EK56XMG
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-25
Last registration	2024-04-13
Complete history	<a href="#">See info</a>



Registration #1	2006-09-25	14 mi
Registration #2	2009-12-12	25.974 mi
Registration #3	2010-11-26	36.051 mi
Registration #4	2011-12-10	42.101 mi
Registration #5	2012-11-18	48.995 mi
Registration #6	2013-12-12	57.212 mi
Registration #7	2014-12-06	62.965 mi
Registration #8	2014-12-10	63.002 mi
Registration #9	2015-11-21	71.474 mi
Registration #10	2015-11-21	71.474 mi
Registration #11	2016-12-09	77.792 mi
Registration #12	2016-12-12	77.817 mi
Registration #13	2017-01-01	78.000 mi
Registration #14	2017-01-01	78.000 mi
Registration #15	2017-01-01	78.000 mi
Registration #16	2017-01-01	78.000 mi
Registration #17	2017-01-01	78.000 mi
Registration #18	2017-01-01	78.000 mi
Registration #19	2017-01-01	78.000 mi
Registration #20	2017-01-01	78.000 mi
Registration #21	2017-01-01	78.000 mi
Registration #22	2017-01-01	78.000 mi
Registration #23	2017-01-01	78.000 mi
Registration #24	2017-01-01	78.000 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	G4HG6096333