



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SE
Colour	Red
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	10.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	181 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	31.0 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2021-09-15
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-09
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #21	2020-11-17 12:08
MOT test number	910304489543
Result	✓ Passed
Next expiry date	2021-11-16
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases exhaust repaired with paste (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2020-11-10 15:38
MOT test number	865451566161
Result	✗ Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-11-03 14:26

MOT test number

480973225943

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18

2019-10-29 18:51

MOT test number

828905796350

Result**✓ Passed**

- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust mounting defective centre (6.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Suspension arms corroded and rear subframe

**MOT #17**

2018-06-14 15:58

MOT test number

871673766425

Result**✗ Failed**

- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Front Registration plate insecure (0.1 (a))
- Advice** Nearside Front Tyre heavily perished and cracked.
- Fail** Nearside Headlamp light intensity severely reduced Headlamp deteriorated. no beam pattern. (4.1.4 (a))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Exhaust system deteriorated.
- Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted/corroded. (1.1.14 (a) (ii))
- Advice** Various suspension and chassis components corroded/deteriorated.
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre heavily perished and cracked.
- Fail** Offside Headlamp light intensity severely reduced Headlamp deteriorated no beam pattern (4.1.4 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** General under body corrosion.
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 1.6mm and HEAVILY worn on edges. (5.2.3 (e))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #16** 2017-04-14 12:21**MOT test number** 659936242268**Result** ✓ Passed**Advice** All four discs corroding**Advice** All four tyres perishing**MOT #15** 2017-04-14 12:21**MOT test number** 778633928236**Result** ✗ Failed**Advice** All four discs corroding**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** All four tyres perishing**MOT #14** 2016-03-17 10:06**MOT test number** 515787346433**Result** ✓ Passed**MOT #13** 2015-03-27 09:54**MOT test number** 727126885051**Result** ✓ Passed**MOT #12** 2014-04-05 09:30**MOT test number** 647535994088**Result** ✓ Passed**MOT #11** 2013-03-18 09:39**MOT test number** 178337173415**Result** ✓ Passed

**MOT #10** 2013-03-18 08:55**MOT test number** 847057373031**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2012-04-16 13:58**MOT test number** 967137702167**Result** ✓ Passed**MOT #8** 2011-04-09 09:49**MOT test number** 749719391084**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2010-04-16 15:56**MOT test number** 262296500187**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #6** 2010-04-12 12:52**MOT test number** 141532100155**Result** ✗ Failed**Fail** Parking brake is not capable of being maintained in operation by direct mechanical action only (3.1.2)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2009-04-14 14:34**MOT test number** 314684809126**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2008-04-16 12:29**MOT test number** 621547808159**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2008-04-15 13:34
MOT test number	811166308123
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	All tyres cracking
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2007-02-22 10:28
MOT test number	284243057032
Result	✓ Passed

MOT #1	2006-02-03 12:26
MOT test number	820064836089
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YP52AZX
Plate since	2019-03-28
Current registration	YP52AZX
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-09-13
Last registration	2020-11-17
Complete history	See info



Registration #1	2002-09-13	23 mi
Registration #2	2006-02-03	11.781 mi
Registration #3	2007-02-22	17.330 mi
Registration #4	2008-04-15	22.976 mi
Registration #5	2008-04-16	22.982 mi
Registration #6	2009-04-14	26.338 mi
Registration #7	2010-04-12	29.956 mi
Registration #8	2010-04-16	30.000 mi
Registration #9	2011-04-09	33.856 mi
Registration #10	2012-04-16	39.055 mi
Registration #11	2013-03-18	46.853 mi
Registration #12	2013-03-18	46.853 mi
Registration #13	2013-03-18	46.853 mi
Registration #14	2013-03-18	46.853 mi
Registration #15	2013-03-18	46.853 mi
Registration #16	2013-03-18	46.853 mi
Registration #17	2013-03-18	46.853 mi
Registration #18	2013-03-18	46.853 mi
Registration #19	2013-03-18	46.853 mi
Registration #20	2013-03-18	46.853 mi
Registration #21	2013-03-18	46.853 mi
Registration #22	2013-03-18	46.853 mi
Registration #23	2013-03-18	46.853 mi
Registration #24	2013-03-18	46.853 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1306 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	G4GC1174663