





## General information

Make	MAZDA
Model 5	5 TS2
Colour	Blue
Year of manufacture -	-
Top speed	113 mph
<b>0 - 60 mph</b>	11.3 seconds
Gearbox 5	5 speed Manual

# Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg





# Internet history

Entry 2	
Date	2021-08-08
Pictures	8
Listing price	View report



source: yesauto.com

### Entry 1

Date

Pictures

Listing price

2021-08-06

View report

8

source: cargurus.co.uk









# MOT history

MOT #14	2022-07-19 14:15
MOT test number	514547536262
Result	✓ Passed
Next expiry date	2023-07-25
Advice Rear Anti-roll bar corroded but not seriously weakened Both sides. (5.3.3 (b) (i	i))
Advice Nearside Front Door has damage.	
Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Suspension arm corroded but not seriously weakened Both sides. (5.3.3 (	(b) (i))
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly red	duced (6.1.1 (c) (i))

MOT #13	2022-07-16 16:03
MOT test number	233119779257
Result	🗙 Failed
<b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Rear Anti-roll bar corroded but not seriously weakened Both sides. (5.3.3 (b) (i)	))
Advice Nearside Front Door has damage.	
Advice Rear Suspension arm corroded but not seriously weakened Both sides. (5.3.3 (	b) (i))
Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly red	uced (6.1.1 (c) (i))

MOT #12	2021-07-26 14	4:45
MOT test	<b>number</b> 601347104	228
Result	V Pas	sed
Advice Rear Inner Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))		
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))		)
Advice Front Inner Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))		





MOT #11	2020-10-15 14:31
MOT test	number 314764471142
Result	✓ Passed
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #10	2019-10-08 10:06
MOT test number	568808473263
Result	✓ Passed

MOT #9	20	018-10-15 10:09
MOT test	number	417957593594
Result		✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.	3.2 (b))

MOT #8	2017-10-10 13:05
MOT test number	655682941000
Result	✓ Passed
Advice Nearside Rear coil spring worn (2.4.C.1b)	
<b>Advice</b> Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	





MOT #7	2016-08-10 10:46
MOT test number	858266071757
Result	✓ Passed
Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not result movement (2.4.G.2)	ing in excessive
Advice Offside Rear tyre cracking	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resume movement (2.4.G.2)	ulting in excessive
Advice Nearside Rear tyre cracking	

MOT #6		2015-08-13 09:48
MOT test	number	427905325289
Result		✓ Passed
Notice Notice	Front and rear brake discs corroded	
Notice	N/s/r tyre side wall perished O/s/r tyre low tread	

MOT #5	2014-04-16 15:48
MOT test number	506076904160
Result	✓ Passed
<b>Notice</b> Front discs and pads worn and brake fluid slightly low	





MOT #4	2014-04-16 10:43
MOT test number	119776704118
Result	🗙 Failed
<b>Fail</b> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail         Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
<b>Notice</b> Front discs and pads worn and brake fluid slightly low	
Fail         Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail         Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	!)

MOT #3		2013-03-01 09:41
MOT test	number	368990763036
Result		✓ Passed
Notice	Offside front tyre tread getting low and bald on outer edge	
Notice	Offside rear anti roll bar link arm is very slightly worn	
Notice	Offside rear tyre tread is low on 1.6mm limit	
Notice	Child seat fitted to nearside and centre seat belts unable to test seatbelts	

MOT #2	2012-03-09 09:30
MOT test number	427829862079
Result	✓ Passed

MOT #1	2011-02-16 10:38
MOT test number	467147841082
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		ASMPL
Date		
Category	10000000	AMPL
Туре		

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
**********	
********	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
See in this check if this MAZDA had different number plates.	,
See in this check if this MAZDA had different number plates.	
See in this check if this MAZDA had different number plates.	
See in this check if this MAZDA had different number plates.	
See in this check if this MAZDA had different number plates.	1000-01-01





#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-04
Last registration	2022-07-19
Complete history	See info



Registration #1	2008-03-04	21 mi
Registration #2	2011-02-16	14.461 mi
Registration #3	2012-03-09	20.904 mi
Registration #4	2013-03-01	26.049 mi
Registration #5	2014-04-16	32.472 mi
Registration #6	2014-04-16	32.472 mi
Registration #7	2015-08-13	39.732 mi
Registration #8	2016-08-10	43.682 mi
Registration #9	2017-10-10	48.631 mi
Registration #10		11.777 est
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi



LTO8VJX report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5