




report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Orange
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-07
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-11
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	45
Total items failed	40

MOT #21	2023-05-24 16:07
MOT test number	971444023484
Result	✓ Passed
Next expiry date	2024-06-11
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2023-05-23 14:52
MOT test number	782603426693
Result	✗ Failed
Fail	Brake fluid significantly below minimum mark (1.1.10 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Offside Rear Other passenger door does not latch securely closed (6.2.3 (a))

**MOT #19** 2022-05-20 13:23**MOT test number** 692713345862**Result** ✓ Passed**MOT #18** 2022-05-16 08:26**MOT test number** 681235565667**Result** ✗ Failed

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 2056016V (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #17 2021-06-12 09:19**MOT test number** 140488871713**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2021-06-10 16:57**MOT test number** 630386228143**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Emissions not tested back box major leak (8.2.1.2 (d))**MOT #15** 2020-05-26 12:26**MOT test number** 120532323799**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-05-25 10:17**MOT test number** 387543412193**Result** ✗ Failed**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2019-05-28 14:30**MOT test number** 656726595801**Result** ✓ Passed**Advice** Front Brake pipe corroded, covered in grease or other material BOTH COVERED IN RUST TREATMENT (1.1.11 (c))

**MOT #12**

2018-08-17 13:17

MOT test number

553533496225

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11

2018-08-14 16:48

MOT test number

813751226007

Result

✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10**

2017-11-01 12:06

MOT test number

376069506974

Result**✗ Failed****Fail** Offside front brake binding (3.7.B.1)**Advice** Windscreen scratched .**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside front brake binding (3.7.B.1)**Advice** Offside Rear Exhaust mounting broken .**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9**

2016-10-05 09:20

MOT test number

835652667408

Result**✓ Passed****Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2016-10-03 10:57**MOT test number** 984955411071**Result** ✗ Failed

- Fail** Offside Rear Inner Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Rear Outer Brake pipe excessively corroded (3.6.B.2c)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Rear Inner Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside Rear Outer Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nails in osr tyre
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #7 2015-10-28 09:58**MOT test number** 853587822969**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-02-07 17:06**MOT test number** 595178534027**Result** ✓ Passed

**MOT #5** 2013-09-09 10:39**MOT test number** 319952253445**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2013-09-09 10:39**MOT test number** 598032053203**Result** ✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2012-09-28 17:01**MOT test number** 466522172267**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2012-01-11 14:08**MOT test number** 927861812060**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2011-03-01 11:38
MOT test number	529080561082
Result	✓ Passed
<div><div>Advice</div>Front Brake pad(s) wearing thin (3.5.1g)</div>	
<div><div>Advice</div>Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
11 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	11 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-09-29
Current registration	 XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-01
Last registration	2023-05-24
Complete history	See info



Registration #1	2008-03-01	18 mi
Registration #2	2011-03-01	29.896 mi
Registration #3	2012-01-11	36.455 mi
Registration #4	2012-09-28	36.834 mi
Registration #5	2013-09-09	44.040 mi
Registration #6	2014-02-07	47.052 mi
Registration #7	2015-10-28	71.991 mi
Registration #8	2016-10-03	83.301 mi
Registration #9	2016-10-05	83.301 mi
Registration #10	2017-11-01	90.291 mi
Registration #11	2018-08-14	90.299 mi
Registration #12	2019-05-29	91.377 mi
Registration #13	2019-05-29	91.377 mi
Registration #14	2019-05-29	91.377 mi
Registration #15	2019-05-29	91.377 mi
Registration #16	2019-05-29	91.377 mi
Registration #17	2019-05-29	91.377 mi
Registration #18	2019-05-29	91.377 mi
Registration #19	2019-05-29	91.377 mi
Registration #20	2019-05-29	91.377 mi
Registration #21	2019-05-29	91.377 mi
Registration #22	2019-05-29	91.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-8024559