



SP09UAW

report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Grey
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg



**MOT history****MOT #12**

2020-11-23 16:16

**MOT test number**

425541586378

**Result****✗ Failed**

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**DANGEROUS** Nearside Front Lower Suspension component ball joint likely to become detached split pin missing (5.3.4 (a) (ii))

**MAJOR** Nearside Front Steering locking device missing ball joint split pin missing (2.1.3 (d))

**MAJOR** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

**MOT #11**

2019-06-11 08:55

**MOT test number**

860369467931

**Result****✓ Passed**

**Advice** Brake pipe corroded, covered in grease or other material Both rear(flexi to wheel cylinder) pipes (1.1.11 (c))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to limit (5.2.3 (e))

**Advice** Exhaust mounting defective Hanger missing behind front subframe (6.1.2 (a))

**Advice** Tyre slightly damaged/cracking or perishing All 4 tyres cracked (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Close to limit and worn on outer shoulder (5.2.3 (e))

**MOT #10** 2019-06-11 08:55**MOT test number** 316841847150**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps Both not working (4.7.1 (b) (ii))**Advice** Tyre slightly damaged/cracking or perishing All 4 tyres cracked (5.2.3 (d) (ii))**Advice** Brake pipe corroded, covered in grease or other material Both rear(flexi to wheel cylinder) pipes (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Close to limit and worn on outer shoulder (5.2.3 (e))**Advice** Exhaust mounting defective Hanger missing behind front subframe (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to limit (5.2.3 (e))**MOT #9** 2018-06-11 14:06**MOT test number** 261958705706**Result** ✓ Passed**MOT #8** 2017-03-10 11:11**MOT test number** 425740297455**Result** ✓ Passed**Advice** Both rear tyres showing signs of deterioration**Advice** Items removed from driver's view prior to test**MOT #7** 2017-03-10 11:11**MOT test number** 769489840931**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Items removed from driver's view prior to test**Advice** Both rear tyres showing signs of deterioration

**MOT #6** 2016-03-02 17:15**MOT test number** 860381775533**Result** ✓ Passed**MOT #5** 2015-03-06 14:53**MOT test number** 995315365024**Result** ✓ Passed**MOT #4** 2015-03-06 09:46**MOT test number** 719845465092**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**MOT #3** 2014-03-07 10:14**MOT test number** 367586564011**Result** ✓ Passed**MOT #2** 2013-03-18 14:56**MOT test number** 228257773010**Result** ✓ Passed**MOT #1** 2012-03-08 12:17**MOT test number** 306788162018**Result** ✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>SP09UAW</b>
Plate since	2019-03-28
Current registration	<b>SP09UAW</b>
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-03-31
Last registration	2020-11-23
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	8 mi
Registration #2	2012-03-08	33.792 mi
Registration #3	2013-03-18	46.232 mi
Registration #4	2014-03-07	59.522 mi
Registration #5	2015-03-06	70.313 mi
Registration #6	2015-03-06	70.313 mi
Registration #7	2016-03-02	80.738 mi
Registration #8	2016-03-02	80.738 mi
Registration #9	2016-03-02	80.738 mi
Registration #10	2016-03-02	80.738 mi
Registration #11	2016-03-02	80.738 mi
Registration #12	2016-03-02	80.738 mi
Registration #13	2016-03-02	80.738 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612