




report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Blue
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	154 Nm at 4.800 rpm
Engine capacity	1.668 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-07
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	79
Total items failed	4

MOT #21	2023-10-07 12:28
MOT test number	860928792663
Result	✓ Passed
Next expiry date	2024-10-10

**MOT #20**

2022-10-11 07:30

MOT test number

349925188054

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive near lower bush (5.3.6 (a) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive near lower bush (5.3.6 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #19**

2022-10-10 10:16

MOT test number

231536969943

Result**✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive near lower bush (5.3.6 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive near lower bush (5.3.6 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #18**

2021-10-11 12:04

MOT test number

756790088536

Result

✓ Passed

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #17

2020-08-25 11:24

MOT test number

670390313222

Result

✓ Passed

Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

MOT #16

2020-08-24 08:18

MOT test number

492524666400

Result

✗ Failed

Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR

Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR

Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

**MOT #15**

2019-08-28 11:31

MOT test number

760509574254

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracked in tread (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush 10% split (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively worn and lipped (1.1.14 (a) (i))
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front droplink cup starting to break up still secure no play
- Advice** Offside Front Brake hose has slight corrosion to ferrule ferrule at solid brake pipe join (1.1.12 (f) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracked in tread (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush 10% split (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively worn and lipped (1.1.14 (a) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule ferrule at solid brake pipe join (1.1.12 (f) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Front droplink cup starting to break up still secure no play

MOT #14

2018-08-30 14:44

MOT test number

972951323889

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2018-08-30 12:24**MOT test number** 790155288838**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Central Stop lamp(s) not working high level (4.3.1 (a) (ii))**MOT #12** 2017-08-30 16:02**MOT test number** 949508238196**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #11** 2017-08-30 16:02**MOT test number** 973704069739**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2016-08-30 10:01**MOT test number** 268910232364**Result** ✓ Passed**MOT #9** 2015-08-27 12:12**MOT test number** 852545432257**Result** ✓ Passed**Advice** Centre Front Windscreen has damage to an area less than a 10mm circle within zone 'A' light scrapes (8.3.1a)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Outer Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2015-08-27 09:35**MOT test number** 776374463306**Result** ✗ Failed**Advice** Offside Rear Outer Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Centre Front Windscreen has damage to an area less than a 10mm circle within zone 'A' light scrapes (8.3.1a)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-08-28 15:05**MOT test number** 365440644280**Result** ✓ Passed**MOT #6** 2013-08-29 16:54**MOT test number** 678921643228**Result** ✓ Passed**Notice** Hanger on centre section of exhaust missing but system is still adequately supported by other mounts**MOT #5** 2012-08-28 15:30**MOT test number** 536401942242**Result** ✓ Passed**MOT #4** 2011-08-25 17:19**MOT test number** 608067231216**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #3	2010-09-02 15:55
MOT test number	620455940276
Result	✓ Passed

MOT #2	2009-09-02 17:23
MOT test number	440295049256
Result	✓ Passed
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)
Advice	Offside Rear brake disc slightly pitted (3.5.1h)

MOT #1	2009-09-02 16:15
MOT test number	391065049443
Result	✗ Failed
Fail	Centre Front Seat belt retracting mechanism defective (5.2.5b)
Advice	Offside Rear brake disc slightly pitted (3.5.1h)
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-01
Last registration	2023-10-07
Complete history	See info



Registration #1	2006-09-01	20 mi
Registration #2	2009-09-02	15.895 mi
Registration #3	2009-09-02	15.895 mi
Registration #4	2010-09-02	21.212 mi
Registration #5	2011-08-25	27.944 mi
Registration #6	2012-08-28	34.404 mi
Registration #7	2013-08-29	40.386 mi
Registration #8	2014-08-28	47.078 mi
Registration #9	2015-08-27	51.300 mi
Registration #10	2015-08-27	51.300 mi
Registration #11	2016-08-30	55.581 mi
Registration #12	2017-08-30	59.074 mi
Registration #13	2018-08-30	62.567 mi
Registration #14	2019-08-30	66.060 mi
Registration #15	2020-08-30	69.553 mi
Registration #16	2021-08-30	73.046 mi
Registration #17	2022-08-30	76.539 mi
Registration #18	2023-08-30	80.032 mi
Registration #19	2023-08-30	80.032 mi
Registration #20	2023-08-30	80.032 mi
Registration #21	2023-08-30	80.032 mi
Registration #22	2023-08-30	80.032 mi
Registration #23	2023-08-30	80.032 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1397 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	D17A25303698