



X96IHET

report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER HARD-TOP TD5
Colour	Blue
Year of manufacture	2000
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.3 mpg
Consumption extra urban	32.1 mpg
Consumption combined	32.1 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-11-05
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	76
Total items failed	29

MOT #24	2023-11-06 16:38
MOT test number	594784489260
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #23**

2023-11-04 12:34

MOT test number

124492689142

Result**✗ Failed**

Fail Central Rear Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired (6.2.2 (d) (ii))

Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired body mount (6.2.2 (d) (ii))

Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced shocker (6.1.1 (c) (i))

Fail Offside Front Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired body mount (6.2.2 (d) (ii))

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #22

2022-05-31 12:56

MOT test number

866544009363

Result**✓ Passed****MOT #21**

2021-06-04 15:44

MOT test number

269638774561

Result**✓ Passed**

Advice Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Fluid leak, but not excessive axle swivel seal on swivel joint leaking (8.4.1 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #20**

2021-06-02 16:11

MOT test number

590004148890

Result**✗ Failed**

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chalked yellow (6.1.1 (c) (i))

Advice Nearside Front Fluid leak, but not excessive axel swivel seal on swivel joint leaking (8.4.1 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Nearside Rear Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chalked yellow (6.1.1 (c) (i))

Fail Offside Rear Inner Fuel hose insecure filter housing (6.1.3 (a) (i))

MOT #19

2020-06-03 11:11

MOT test number

267827125181

Result**✓ Passed**

Advice Front Brake pipe corroded, covered in grease or other material Master cylinder to flexi pipe (1.1.11 (c))

Advice Offside Front Tyre slightly damaged/cracking or perishing has slight sidewall damage (5.2.3 (d) (ii))

Advice Underbody corrosion

Advice Rear Oil leak, but not excessive Rear differential has slight leak (8.4.1 (a) (i))

Advice Nearside Front Chalice slightly pitted



MOT #18

2020-05-14 09:54

MOT test number

389039079666

Result

✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Body mount (6.1.1 (c) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt and nearside front (2.1.3 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Body mount (6.1.1 (c) (i))

Fail Nearside Front Position lamp adversely affected by the operation of another lamp and offside front (4.2.3 (c))

Advice Nearside Front chalice slightly pitted

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement and nearside front (5.3.4 (a) (i))

Advice Oil leak, but not excessive Rear differential (8.4.1 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake pipe corroded, covered in grease or other material all front (1.1.11 (c))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Body mount (6.1.1 (c) (i))

Advice Rear Brake pipe corroded, covered in grease or other material all rear brake pipes (1.1.11 (c))

Advice Underbody corrosion

Fail Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #17**

2019-05-24 15:27

MOT test number

367817505556

Result

✓ Passed

- Advice** Nearside Front Wing mirror slightly deteriorated
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material And offside rear (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing has sidewall damage (5.2.3 (d) (ii))

MOT #16

2019-05-10 11:25

MOT test number

923953394481

Result

✗ Failed

- Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Offside Front Seat belt damaged (7.1.2 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing has sidewall damage (5.2.3 (d) (ii))
- Fail** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Wing mirror slightly deteriorated
- Fail** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Horn not working (7.7 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material And offside rear (1.1.11 (c))
- Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Chassis (body mount) (6.2.2 (d) (i))
- Fail** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Chassis (body mount) (6.2.2 (d) (i))

**MOT #15**

2018-05-08 15:26

MOT test number

589942146237

Result

✓ Passed

Advice Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Coolant leak cap**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Chassis corroded numerous places**MOT #14**

2018-05-08 09:59

MOT test number

169958354512

Result

✗ Failed

Fail Offside Rear fog lamp not working (1.3.2b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Chassis corroded numerous places**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Advice** Coolant leak cap**Fail** Fuel system component leaking filter (7.2.3)

**MOT #13**

2017-04-27 18:28

MOT test number

462036268735

Result

✓ Passed

- Advice** Nearside Non obligatory mirror damaged deteriorated
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened and offside (3.5.1i)
- Advice** Offside Front floor corroded
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside chassis corroded
- Advice** Nearside Rear tyre outer edge worn

MOT #12

2017-04-25 10:28

MOT test number

883840263000

Result

✗ Failed

- Advice** Offside chassis corroded
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear tyre outer edge worn
- Advice** Nearside Non obligatory mirror damaged deteriorated
- Fail** Ball joint has excessive play steering pitman arm (2.2.B.1f)
- Fail** Rear Vehicle structure excessively corroded within 30cm of towbar mounting crossmember (6.6.6)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front floor corroded
- Fail** Offside Front Brake pipe leaking to rear (3.6.A.1)
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened and offside (3.5.1i)

**MOT #11** 2016-05-10 12:03**MOT test number** 200364364392**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Seat belt cut but webbing not significantly weakened (5.2.2a)**MOT #10** 2015-05-06 10:53**MOT test number** 267326225492**Result** ✓ Passed**MOT #9** 2014-05-07 10:29**MOT test number** 435707024134**Result** ✓ Passed**Advice** Rear Vehicle structure has slight corrosion (6.1.B.2)**Advice** Rear Vehicle structure has slight corrosion (6.1.B.2)**MOT #8** 2013-05-21 12:09**MOT test number** 365021043190**Result** ✓ Passed**MOT #7** 2012-05-16 11:22**MOT test number** 376607032134**Result** ✓ Passed**Notice** Front tyres wearing on inner edges**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2011-05-17 11:02**MOT test number** 855537231179**Result** ✓ Passed

**MOT #5** 2010-05-12 09:33**MOT test number** 410442530175**Result** ✓ Passed**MOT #4** 2009-05-19 15:36**MOT test number** 494399939133**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #3** 2008-05-21 13:38**MOT test number** 610862548161**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2007-03-15 12:38**MOT test number** 692724577029**Result** ✓ Passed**MOT #1** 2005-11-23 09:10**MOT test number** 812427225337**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
5 November 2024

Tax status		Valid until 1 February
Days left		279
MOT expiry date		5 November 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-28
Current registration	 XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2000-11-29
Last registration	2023-11-06
Complete history	See info



Registration #1	2000-11-29	22 mi
Registration #2	2005-11-23	72.540 mi
Registration #3	2007-03-15	89.040 mi
Registration #4	2008-05-21	103.643 mi
Registration #5	2009-05-19	115.079 mi
Registration #6	2010-05-12	126.578 mi
Registration #7	2011-05-17	137.377 mi
Registration #8	2013-05-21	156.253 mi
Registration #9	2014-05-07	165.295 mi
Registration #10	2015-05-06	173.686 mi
Registration #11	2016-05-10	181.175 mi
Registration #12	2017-04-25	189.439 mi
Registration #13	2018-05-07	197.703 mi
Registration #14	2019-05-06	205.967 mi
Registration #15	2020-05-06	214.231 mi
Registration #16	2021-05-06	222.495 mi
Registration #17	2022-05-06	230.759 mi
Registration #18	2023-05-06	239.023 mi
Registration #19	2023-11-06	247.287 mi
Registration #20	2024-01-06	255.551 mi
Registration #21	2024-02-06	263.815 mi
Registration #22	2024-03-06	272.079 mi
Registration #23	2024-04-06	280.343 mi
Registration #24	2024-05-06	288.607 mi

More info >



Dimensions & weight

Width	1790 mm
Length	3883 mm
Wheel base	2360 mm
Kerb weight	1695 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of axles	2
Engine number	10P90447A