



Mercedes-Benz

**R343KDK**

report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 310D/40 VAN
Colour	Not stated
Year of manufacture	1998
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Engine capacity	2.874 cc
Cylinders	5
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-11
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-04-28
MOT pass rate	62 %
MOT passed	16
Failed MOT tests	10
Total advice items	47
Total items failed	16

MOT #26	2023-04-26 14:47
---------	------------------

MOT test number	498186410115
-----------------	--------------

Result	✗ Failed
<div><div>Advice</div>Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))</div>	
<div><div>MAJOR</div>Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))</div>	
<div><div>MAJOR</div>Nearside Front Inner Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting cill (6.2.2 (d) (i))</div>	
<div><div>Advice</div>Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))</div>	
<div><div>MAJOR</div>Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))</div>	
<div><div>MAJOR</div>Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength front mount (5.3.6 (a) (i))</div>	
<div><div>MAJOR</div>Offside Front Inner Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting cill (6.2.2 (d) (i))</div>	

**MOT #25**

2022-04-29 09:50

**MOT test number**

362979758783

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Power steering pump has slight seepage (2.1.5 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** WINGS/ WHEEL ARCHES CORRODED
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #24**

2022-04-28 10:02

**MOT test number**

975391041131

**Result**

✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** WINGS/ WHEEL ARCHES CORRODED
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Power steering pump has slight seepage (2.1.5 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #23**

2020-06-22 16:55

**MOT test number**

259450167489

**Result**

✓ Passed

**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** N/s ans o/s front wheel acres corroded**MOT #22**

2020-06-17 10:57

**MOT test number**

836847319375

**Result**

✗ Failed

**Advice** N/s ans o/s front wheel acres corroded**MAJOR** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #21**

2019-03-26 11:26

**MOT test number**

873940489903

**Result**

✓ Passed

**Advice** Nearside Front Seat belt flexible stalk damaged (7.1.2 (b) (i))**Advice** Front both front wheel acres are corroded**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front both front sills are corroded

**MOT #20**

2018-03-21 15:07

**MOT test number**

375182253763

**Result**

✓ Passed

**Advice** Nearside Front Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)**Advice** Front both front wheel arches are slightly corroded**Advice** Front both front sills are slightly corroded**MOT #19**

2018-03-21 12:27

**MOT test number**

760648818408

**Result**

✗ Failed

**Advice** Front both front wheel arches are slightly corroded**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Side repeater not working (1.4.A.2c)**Advice** Front both front sills are slightly corroded**Advice** Nearside Front Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #18**

2017-03-28 09:22

**MOT test number**

293048649988

**Result**

✓ Passed

**Advice** Both sills slightly corroded**Advice** Nearside Front Seat belt flexible stalk damaged but not likely to lead to failure under load cover missing (5.2.4a)**Advice** Both front wheel arch slightly corroded

**MOT #17**

2017-03-27 14:49

**MOT test number**

453089060292

**Result****✗ Failed**

**Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded spring mount corroded (2.4.A.3)

**Advice** Both sills slight corroded

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded stabilizer mount corroded (2.4.A.3)

**Advice** Both front wheel arch slight corroded

**Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded spring mount corroded (2.4.A.3)

**Advice** Nearside Front Seat belt flexible stalk damaged but not likely to lead to failure under load cover missing (5.2.4a)

**MOT #16**

2016-03-11 12:08

**MOT test number**

398984231005

**Result****✓ Passed**

**Advice** Rear drop link mounts slight corrosion

**MOT #15**

2016-03-10 11:32

**MOT test number**

389631717070

**Result****✗ Failed**

**Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)

**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

**Advice** Rear drop link mounts slight corrosion

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded top shocker mount (2.4.A.3)

**MOT #14**

2015-03-17 12:13

**MOT test number**

787436775095

**Result****✓ Passed**

**MOT #13** 2014-03-18 11:36**MOT test number** 147907674414**Result** ✓ Passed**MOT #12** 2014-03-17 13:52**MOT test number** 709396774006**Result** ✗ Failed**Fail** Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Spare wheel carrier insecure (6.4.2)**MOT #11** 2013-03-26 17:11**MOT test number** 827995483067**Result** ✓ Passed**MOT #10** 2012-03-19 15:36**MOT test number** 345169672036**Result** ✓ Passed**MOT #9** 2011-03-29 12:54**MOT test number** 765258681064**Result** ✓ Passed**MOT #8** 2011-03-28 13:18**MOT test number** 656877281006**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)





<b>MOT #7</b>	2010-03-15 15:21
---------------	------------------

<b>MOT test number</b>	350224470070
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2010-03-15 12:58
---------------	------------------

<b>MOT test number</b>	864704770014
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Headlamp aim too low (1.8)
-------------	-------------------------------------

<b>Fail</b>	Direction indicators incorrect colour (1.4.A.2f)
-------------	--

<b>MOT #5</b>	2009-03-16 11:51
---------------	------------------

<b>MOT test number</b>	123345579054
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2008-03-18 17:03
---------------	------------------

<b>MOT test number</b>	151028978038
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2008-03-18 16:14
---------------	------------------

<b>MOT test number</b>	951488978027
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Service brake: efficiency below requirements (3.7.B.7)
-------------	--

<b>MOT #2</b>	2007-03-29 12:51
---------------	------------------

<b>MOT test number</b>	180118787038
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2006-03-20 12:52
---------------	------------------

<b>MOT test number</b>	592549476076
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>R343KDK</b>
Plate since	2024-03-28
Current registration	 <b>R343KDK</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	1998-04-02
Last registration	2023-04-26
Complete history	<a href="#">See info</a>



Registration #1	1998-04-02	14 mi
Registration #2	2006-03-20	32.300 mi
Registration #3	2007-03-29	36.467 mi
Registration #4	2008-03-18	39.160 mi
Registration #5	2008-03-18	39.160 mi
Registration #6	2009-03-16	42.527 mi
Registration #7	2010-03-15	45.516 mi
Registration #8	2010-03-15	45.516 mi
Registration #9	2011-03-28	48.104 mi
Registration #10	2011-03-29	48.104 mi
Registration #11	2012-03-19	52.188 mi
Registration #12	2013-03-26	60.080 mi
Registration #13	2014-03-17	65.811 mi
Registration #14	2014-03-18	65.811 mi
Registration #15	2015-03-20	70.377 mi
Registration #16	2015-03-20	70.377 mi
Registration #17	2016-03-20	75.377 mi
Registration #18	2016-03-20	75.377 mi
Registration #19	2017-03-20	80.377 mi
Registration #20	2017-03-20	80.377 mi
Registration #21	2018-03-20	85.377 mi
Registration #22	2018-03-20	85.377 mi
Registration #23	2019-03-20	90.377 mi
Registration #24	2019-03-20	90.377 mi
Registration #25	2020-03-20	95.377 mi
Registration #26	2023-04-26	100.377 mi

Registration #27	2023-25-27	25,277-462
Registration #28	2023-25-28	25,277-462

More info >



Dimensions & weight

Width	1933 mm
Kerb weight	2070 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of axles	2
Engine number	60298000178187