





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	ACCENT CDX
Colour	Green
Year of manufacture	2003
Top speed	102 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

#### Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/18



MOT history

MOT expiry date	2021-11-05
MOT pass rate	68 %
MOT passed	19
Failed MOT tests	9
Total advice items	87
Total items failed	27

MOT #28	2020-11-05 09:47
MOT test number	494793342298
Result	✓ Passed
Next expiry date	2021-11-05
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #27	2020-11-04 13:03
MOT test number	387483945331
Result	<b>X</b> Failed
Fail Rear Exhaust system insecure (6.1.2 (a))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #26	2019-10-29 15:32
MOT test number	779253422726
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/18



**MOT #25** 

RY03KFD report date: 2024-03-28

2019-10-29 09:24

MOT test number 832804692552

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #24** 2018-11-06 16:10

**MOT test number** 727207929199

**Result** ✓ Passed

MOT #23 2018-11-06 14:28

**MOT test number** 322881472238

Result X Failed

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick and o/s/f (1.1.13 (a) (ii))

**Fail** Nearside Front Headlamp aim too low and o/s/f (4.1.2 (a))

**MOT #22** 2017-12-07 15:37

**MOT test number** 862314925714

**Result** ✓ Passed

**Advice** Brake pedal anti slip pad split

**Advice** O/s & n/s front to rear brake pipes corroded

**Advice** Nearside wiper split

Advice Front o/s & n/s brake pipes corroded

CarCheck.co.uk page 3/18



**MOT #21** 2017-12-04 15:30

MOT test number 552545122935

**Result** X Failed

Advice Nearside Rear tyre 2.5mm/perished/cut sidewall

Fail Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

**Fail** Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)

**Advice** Brake pedal anti slip pad split

**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** O/s & n/s front to rear brake pipes corroded

**Fail** Offside Rear Inner Suspension component mounting prescribed area is excessively corroded body sill (2.4.A.3)

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**Advice** Nearside wiper split

Fail Offside Stop lamp not working (1.2.1b)

Advice Front o/s & n/s brake pipes corroded

**Fail** Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #20** 2016-12-07 15:36

MOT test number 832386394567

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Nearside rear tyre perishing

**Advice** Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)

**Advice** Nearside front tyre has cuts to outer sidewall

**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

CarCheck.co.uk page 4/18



report date: 2024-03-28

MOT #19 2016-12-06 16:11 MOT test number 636685056210

Result × Failed

Fail Offside Rear Tyre not fitted in accordance with side wall instructions wrong direction (4.1.D.1f)

**Advice** Nearside rear tyre perishing

Fail Offside Stop lamp not working (1.2.1b)

**Advice** Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)

**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Nearside front tyre has cuts to outer sidewall

**Fail** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)

**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Offside front tyre 2mm/worn on the inside edge

MOT #18 2015-12-07 13:30

MOT test number 418428785249

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**Advice** Nearside outer cv boot perishing

**Advice** Offside outer cv boot perishing

**Advice** Nearside rear tyre perishing

**MOT #17** 2015-01-13 09:34

**MOT test number** 786303015030

**Result** ✓ Passed

**Notice** Both front outer c.v boots perishing

CarCheck.co.uk page 5/18



report date: 2024-03-28

MOT #16

MOT test number

479389205098

Result

Notice Both front outer c.v boots perishing

Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c)

2014-01-17 17:19 MOT #15 **MOT** test number 996577414033 Result ✓ Passed Notice Stone chips in windscreen Notice O/s/r tyre 3mm Notice Front brakes imbalanced Notice Slight wear to o/s/r anti roll bar bush Notice N/s/f brake binding

MOT #14		2013-10-15 10:52
MOT test	number	718938983204
Result		✓ Passed
Notice	Both rear anti roll bar D bushes worn	
Notice	Both front c.v boots perishing	
Notice	Both front wish bone bushes starting to split	
Notice	Stone chip in windscreen	
Notice	O/s/f tyre wearing on outer edge	
Notice	N/s/f tyre 3mm	

CarCheck.co.uk page 6/18



Notice

Nearside rear tyre slightly perishing

RY03KFD

report date: 2024-03-28

**MOT #13** 2013-04-08 09:59 865578793057 **MOT test number** Result ✓ Passed Notice Rear exhaust joint corroded Advice Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) Notice Slight play in both rear anti-roll bar d bushes Notice Offside rear tyre slightly feathering on inner edge Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) Notice Both front windscreen wipers slightly smearing

MOT #12	2013-04-08 09:59		
MOT test	number 267648993004		
Result	<b>★</b> Failed		
<b>Advice</b> (2.5.C.1a)	Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt		
Notice	Both front windscreen wipers slightly smearing		
Notice	Nearside rear tyre slightly perishing		
Notice	Rear exhaust joint corroded		
<b>Advice</b> (2.5.C.1a)			
Notice	Slight play in both rear anti-roll bar d bushes		
Notice	Offside rear tyre slightly feathering on inner edge		
Pass wit	th rectification Nearside Front Headlamp aim too high (1.8)		

CarCheck.co.uk page 7/18



report date: 2024-03-28




MOT #10	2012-04-04 12:15
MOT test number	298345792021
Result	<b>X</b> Failed
Notice Slight play in both front anti roll bar D bushes	
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Notice Engine has a oil leak	
Notice O/s/f tyre 1.6mm	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail Nearside Headlamp aim not tested (1.8.A.1c)	
Notice Stone chip in windscreen	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its st	tructure (4.1.D.1b)

CarCheck.co.uk page 8/18



report date: 2024-03-28



MOT #8			2011-04-13 09:51
MOT test	number		689333801131
Result			<b>X</b> Failed
Pass wit	th rectification	Offside Rear fog lamp not working (1.3.2b)	
Notice	O/s/f brake pipe	corroded	
Notice	Both rear brake	pipes corroded	
Notice Front brake pads look low and discs worn			
Pass wit	th rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Notice	Slight play in bot	th front anti roll bar D bushes	
Notice	N/s front to rear	brake pipe corroded	
Notice	N/s/f tyre has a l	arge cut to outer wall	

CarCheck.co.uk page 9/18



report date: 2024-03-28

MOT #7		2010-04-19 10:26
MOT test	number	373539700146
Result		✓ Passed
Notice	O/s/r barke pipe corroded	
Notice	N/s/f tyre has a cut to outer wall	
Notice	Slight play in o/s/f anti roll bar D bushes	
Notice	N/s front to rear brake pipe corroded	

MOT #6		2009-09-04 12:25
MOT test	number	783407949296
Result		✓ Passed
Notice	Stone chips in windscreen	
Notice	N/s front to rear brake pipe corroded	

MOT #5		2009-05-21 11:04
MOT test	number	333841949145
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #4		2008-10-02 11:47
MOT test	number	321446078414
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zo	ne 'A' (8.3.1d)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 10/18



report date: 2024-03-28

MOT #3	2007-10-05 09:28
MOT test number	204128577206
Result	<b>✓</b> Passed
MOT #2	2007-03-27 17:24
MOT test number	663866487044
Result	<b>✓</b> Passed
MOT #1	2006-04-03 18:04
MOT test number	113773296430
Result	<b>✓</b> Passed

CarCheck.co.uk page 11/18





#### Tax & MOT check



**Tax expired:** 15 December 2020

# X MOT

Expired: 5 November 2021

Tax status	Expired at 15 December 2020
Days left	1231 days too late
MOT expiry date	5 November 2021
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 12/18



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 14/18



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET CONTRACTOR CONT	
********	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK AIS
Flate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 15/18



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 


More info >

CarCheck.co.uk page 16/18



## Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-06-05
Last registration	2020-11-05
Complete history	See info



Registration #1	2003-06-05	6 mi
Registration #2	2006-04-03	14.580 mi
Registration #3	2007-03-27	22.513 mi
Registration #4	2007-10-05	22.996 mi
Registration #5	2008-10-02	27.670 mi
Registration #6	2009-05-21	30.601 mi
Registration #7	2009-09-04	30.620 mi
Registration #8	2010-04-19	33.887 mi
Registration #9	2011-04-13	40.634 mi
Registration #10	2012-04-04	47.391 mi
Registration #11	2012-04-04	47.391 mi
Registration #12	2013-04-08	53.654 mi
Registration #13	2013-10-15	55.876 mi
Registration #14	2014-01-17	57.698 mi
Registration #15		11.177 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		11.777 ea
Registration #19		11.777 es
Registration #20		11.777 ea
Registration #21		11.777 es
Registration #22		11.777 ea
Registration #23		11.777 mi
Registration #24		11.777 es
Registration #25		11,777 mi
Registration #26		11.777 es
CarCheck.co.uk		page 17/18

More info >



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1072 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	G4EA3362542 page 18/18