






General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	White
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1	
Date	2021-06-04
Pictures	28

Listing price

28

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	27
Total items failed	4

MOT #14		2023-07-26 09:28
MOT test nu	Imber	793108264402
Result		✓ Passed
Next expiry	date	2024-07-29
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii	i))
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced rear axle and connecting components (6.1.1 (c) (i))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material b	pefore axle (1.1.11 (c))
Advice Front Vehicle structure is corroded but structural rigidity is not significantly reduced front frame and connecting components (6.1.1 (c) (i))		
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material	l before axle (1.1.11 (c))
Advice	Front Oil leak, but not excessive underside of engine (8.4.1 (a) (i))	





MOT #13	2	2023-07-26 09:28
MOT test num	ıber	729189691370
Result		🗙 Failed
Advice Nea	arside Rear Brake pipe corroded, covered in grease or other material before axl	e (1.1.11 (c))
Advice Nea	arside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice From	ont Oil leak, but not excessive underside of engine (8.4.1 (a) (i))	
Pass with red	Offside Front Headlamp aim too high (4.1.2 (a))	
	ar Vehicle structure is corroded but structural rigidity is not significantly reduced mponents (6.1.1 (c) (i))	d rear axle and
Advice Nea	arside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offs	fside Rear Brake pipe corroded, covered in grease or other material before axle	(1.1.11 (c))
Advice Offs	fside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with red	Actification Nearside Front Headlamp aim too high (4.1.2 (a))	
	ont Vehicle structure is corroded but structural rigidity is not significantly reduce g components (6.1.1 (c) (i))	d front frame

MOT #12	2022-07-15 10:37
MOT test number	884447771679
Result	✓ Passed

MOT #11		2022-07-15 10:37
MOT test number		593295685242
Result		🗙 Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10	2021-07-30 06:53
MOT test number	830412640750
Result	✓ Passed





MOT #9		2021-01-13 12:07
MOT test number		805678883915
Result		✓ Passed
Advice Offside From	t Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside R	ar Child Seat fitted not allowing full inspection of adult b	elt
Advice Nearside Fr	ont Direction indicator slightly discoloured (4.4.3 (a))	

MOT #8	2020-01-08 09:20
MOT test number	865658337898
Result	✓ Passed

MOT #7	2019-01-11 14:19
MOT test number	724610363990
Result	✓ Passed

МОТ #6	2019-01-11 09:18
MOT test number	715702050146
Result	🗙 Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Track rod end ball joint has excessive play Both (2.1.3 (b) (i))	

MOT #5	2018-01-12 09:52
MOT test number	601516717123
Result	✓ Passed





MOT #4		2017-01-05 13:21
MOT test	number	273096546532
Result		✓ Passed
MOT #3		2016-01-08 11:29
MOT test	number	658004741678
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin pads wearing thin (3.5.1g)	
Advice	Centre Rear Lower engine mounting bracket not fully secure mountin	g worn in bush (6.1.D.1b)
MOT #2		2015-01-09 16:12
MOT test	number	439669105065
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
--------	--

MOT #1	2014-01-10 14:05
MOT test number	526700414014
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 August 2024	✓ MOT Expires: 29 July 2024
Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-10
Last registration	2023-07-26
Complete history	<u>See info</u>



Registration #1	2011-01-10	7 mi
Registration #2	2014-01-10	14.470 mi
Registration #3	2015-01-09	19.396 mi
Registration #4	2016-01-08	24.894 mi
Registration #5	2017-01-05	21.920 mi
Registration #6	2018-01-12	32.931 mi
Registration #7	2019-01-11	37.278 mi
Registration #8	2019-01-11	37.301 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	G4FABZ370121