

# Paimler



### General information

Make	DAIMLER
Model	V8 DAIMLER V8
Colour	Blue
Year of manufacture	1998
Top speed	150 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	290 BHP	0 < 101 A
Max. torque	393 Nm at 4.250 rpm	101 - 120 B
Engine capacity	3.996 cc	121 - 140 E
Cylinders	8	141 - 165 F G
Fuel type	Petrol	166 - 185
Consumption city	16.6 mpg	186 - 225 K
Consumption extra urban	31.0 mpg	225+ L
Consumption combined	23.5 mpg	





### Internet history Entry 2 Date 2021-10-29 7 Pictures Listing price View report Cilton Car Sales Clifton Car Sales C C.S. sons to buy from us RESERVE TODAY WITH A £200 REFUNDABLE DEPOSIT **Click & Collect** source: autotrader.co.uk Entry 1 Date 2021-01-29 **Pictures** 1 Listing price View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2024-02-03
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	25
Total items failed	32

MOT #23	2023-01-11 11:58
MOT test number	158865047989
Result	✓ Passed
Next expiry date	2024-02-03
Advice Underbody undersealed	
Advice Brake pipe corroded, covered in grease or other material All undersealed (1.1.11 (	c))

MOT #22	2022-02-02 09:17
MOT test number	349180903045
Result	✓ Passed
Advice Underside covered in underseal	
MOT #21	2021-02-02 16:51

MOT test number	362118273276
Result	✓ Passed





MOT #20		2020-01-14 16:33
MOT test	number	377296276043
Result		✓ Passed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Non obligatory mirror damaged	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	



**R950PRH** report date: 2024-03-29

<b>DT #19</b> 2020-01-04 09	:32
<b>DT test number</b> 2478109265	593
sult X Fai	led
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
• Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
•ail Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significant duced inner arch and sill (6.1.1 (c) (i))	y
•ail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly ducing structural strength floor and inner arch (5.3.6 (a) (i))	
Advice Non obligatory mirror damaged	
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
•ail Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.) (i))	.1
A Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
A Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is gnificantly reduced inner arch and sill (6.1.1 (c) (i))	
•ail Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly duced sill to floor (6.1.1 (c) (i))	
Offside Rear Suspension component mounting prescribed area excessively corroded significantly ducing structural strength floor and inner arch (5.3.6 (a) (i))	
ail Offside Rear Suspension component corroded and seriously weakened mount (5.3.3 (b) (i))	
•ail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 ) (i))	
•ail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	

MOT #18	2019-02-04 15:06
MOT test number	646460983848
Result	✓ Passed





MOT #17		2019-02-04 15:06
MOT test number		151059284621
Result		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a))	
MOT #16		2017-10-11 14:17
MOT test number		465744989174
Result		✓ Passed
Advice ALL 4 TYRES CRACKING IN OUTER WALL AND TREAD(NO PLY OR CORDS SHOWING AT TIME OF		

Offside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2) Advice

MOT #15	2017-09-27 15:56
MOT test number	478059010930
Result	🗙 Failed
Fail Nearside Rear Stop lamp not working (1.2.1b)	
Advice ALL 4 TYRES CRACKING IN OUTER WALL AND TREAD(NO PLY OR CORDS SHOW TEST).	ING AT TIME OF
<b>Fail</b> Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3)	.D.3)
Advice Offside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)	
<b>Fail</b> Offside Front Exhaust has a major leak of exhaust gases CAT. (7.1.2)	

MOT #14	2015-11-25 10:31
MOT test number	333805089234
Result	✓ Passed
MOT #13	2014-11-13 15:21
MOT test number	109317514368
Result	✓ Passed

TEST).





MOT #2	12	2014-11-05 12:32
MOT te	st number	295669604315
Result		🗙 Failed
Fail	Nearside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3	)
Fail	Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)	

MOT #11	2013-10-23 11:57
MOT test number	935206393244
Result	🗸 Passed
Advice Vehicle structure has slight corrosion (6.1.A.1)	

MOT #10	2012-10-08 14:56
MOT test number	518132582283
Result	✓ Passed

MOT #9	2012-10-03 09:36
MOT test number	976907172217
Result	🗙 Failed
<b>Fail</b> Nearside Exhaust has a major leak of exhaust gases (7.1.2)	
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Fail Offside rear brake binding (3.7.B.1)	
Fail Front brake juddering severely (3.7.A.2b)	
Advice Offside Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	
FailNearside rear brake binding (3.7.B.1)	
Fail Rear brake juddering severely (3.7.A.5b)	





MOT #8	2010-03-30 16:00
MOT test number	602809780099
Result	✓ Passed
<b>Advice</b> Rear Drive shaft uj which forms part of the suspension has slight play in (2.4.G.4b)	a universal joint

MOT #7	2010-03-30 10:18
MOT test number	373579580067
Result	🗙 Failed
Fail Nearside Brake pipe excessively corroded (3.6.B.2c)	
Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail Offside Brake pipe excessively corroded (3.6.B.2c)	
Advice Rear Drive shaft uj which forms part of the suspension has slight play in a un (2.4.G.4b)	iversal joint

МОТ #6	2009-02-13 11:47
MOT test number	183334549444
Result	✓ Passed

MOT #5	2008-02-07 14:42
MOT test number	923848438058
Result	✓ Passed
Advice Offside Front Suspension spring mounting prescribed area is corre	oded but not considered

excessive (2.4.A.3)

МОТ #4	2008-02-01 11:39
MOT test number	580152138023
Result	🗙 Failed
Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail Nearside Front Suspension spring mounting prescribed area is excessively corrode	ed (2.4.A.3)
Advice Offside Front Suspension spring mounting prescribed area is corroded but not excessive (2.4.A.3)	considered






MOT #3	2007-01-31 11:22
MOT test number	103811537409
Result	✓ Passed
MOT #2	2006-02-03 08:52
MOT test number	722724636003
Result	✓ Passed
MOT #1	2006-02-01 11:25
MOT test number	900742636003
Result	🗙 Failed
<b>Fail</b> Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
FailOffside Registration plate lamp not working (1.1.5c)	
<b>Fail</b> Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check







#### Damage history

Check the damage history for this DAIMLER. See if, where and when this DAIMLER had damage and the car repair costs. We also check if this DAIMLER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	*
Category	AMP
Туре	

#### Extra DAIMLER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this DAIMLER? How many owners did this DAIMLER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this DAIMLER had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this DAIMLER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DAIMLER has been settled.

If not, and you buy this DAIMLER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this DAIMLER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



R950PRH report date: 2024-03-29

# Mileage check

In miles
26
1998-03-13
2023-01-11
See info



Registration #1	1998-03-13	15 mi
Registration #2	2006-02-01	67.061 mi
Registration #3	2006-02-03	67.061 mi
Registration #4	2007-01-31	73.313 mi
Registration #5	2008-02-01	78.562 mi
Registration #6	2008-02-07	78.595 mi
Registration #7	2009-02-13	81.344 mi
Registration #8	2010-03-30	83.088 mi
Registration #9	2010-03-30	83.088 mi
Registration #10	2012-10-03	83.529 mi
Registration #11	2012-10-08	83.532 mi
Registration #12	2013-10-23	85.766 mi
Registration #13	2014-11-05	86.207 mi
Registration #14		11.777 esi
Registration #15		11.117 esi
Registration #16		11.117 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 esi
Registration #21		11.777 mi
Registration #22		11.117 esi
Registration #23		11.777 esi
Registration #24		11.777 est
Registration #25		11.777 mi
Registration #26		11.777 esi

CarCheck.co.uk

More info >



Dimensions & weight	
Width	1799 mm
Height	1333 mm
Length	5149 mm
Additional information	
Number of axles	2
Engine number	BC9802251049