





General information

Make	HYUNDAI
Model	SANTA FE CRTD LIMITED 7STR
Colour	Black
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	335 Nm at 2.500 rpm
Engine capacity	2.188 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	191 g/km
CO2 label	J





MOT history

MOT expiry date	2020-12-16	
MOT pass rate	56 %	
MOT passed	9	
Failed MOT tests	7	
Total advice items	68	
Total items failed	12	

MOT #16	2019-12-17 13:50
MOT test number	115490354169
Result	✓ Passed
Next expiry date	2020-12-16
Advice Coil spring corroded All (5.3.1 (b) (i))	





MOT #15 2019-11-22 19:57
MOT test number 202954724357
Result X Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice Coolant low
Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice Front Coil spring corroded (5.3.1 (b) (i))
Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice Radiator leaking
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice Oil leak
Advice Rear Coil spring corroded (5.3.1 (b) (i))
Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))





MOT #14	2018-11-20 16:11
MOT test	number 703066406033
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Upper Oil leak, but not excessive (8.4.1 (a) (i))
Advice (a) (i))	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor ingress of	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the dirt (2.1.3 (g) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13		2018-11-20 16:11
MOT test	number	759754281208
Result		× Failed
Advice (a) (i))	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive moveme	ent D bush (5.3.4
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	.4 (a) (ii))
Pass wit	h rectification Offside Front Position lamp not working (4.2.1 (a))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Advice	Front Upper Oil leak, but not excessive (8.4.1 (a) (i))	
Minor ingress of	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but p dirt (2.1.3 (g) (i))	reventing the





MOT #12		2017-11-16 16:51
MOT test	number	781992849447
Result		✓ Passed
Advice	Engine covers / under trays fitted	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rears (3.5.1i)	
Advice	Items removed from driver's view prior to test	
Advice	Brake anti-slip worn	
Advice	Brake pipe slightly corroded both rears (3.6.B.2c)	

MOT #11	2017-11-16 13:15
MOT test number	280521172295
Result	🗙 Failed
Advice Brake pipe slightly corroded both rears (3.6.B.2c)	
Advice Brake anti-slip worn	
Advice Brake disc worn, pitted or scored, but not seriously weakened both rears (3.5.1i)	
Advice Items removed from driver's view prior to test	
Advice Offside Rear slight binding	
Advice Engine covers / under trays fitted	
Fail Parking brake lever has no reserve travel (3.1.6b)	



DV58EOS
report date: 2024-03-28

MOT #10		2016-11-29 14:06
MOT test	number	189862184490
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #9	2016-1	1-29 14:06
MOT test number	424	647379198
Result		🗙 Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.	1)
Advice Nearside Rear T	Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front B	Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Br	rake pad(s) wearing thin (3.5.1g)	
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Rear Tyr	re worn close to the legal limit (4.1.E.1)	
Advice Nearside Front B	Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Rear S	Seat belt cut but webbing not significantly weakened (5.2.2a)	



MOT #8		2015-12-04 14:29
MOT test	number	412475382558
Result		✓ Passed
Advice	Brake anti-slip worn	
Advice	Nearside Rear Seat belt damaged but webbing not significantly weakened (5	.2.2a)
Advice	Engine covers / under trays fitted	
MOT #7		2015-11-30 12:44
MOT #7 MOT test	number	2015-11-30 12:44 862772914840
	number	
MOT test	number Brake anti-slip worn	862772914840
MOT test Result	Brake anti-slip worn Offside Lower Front suspension ball joint dust cover deteriorated, but preven	862772914840 🗙 Failed

Fail Nearside Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)

MOT #6		2014-12-01 13:44
MOT test	number	749595534322
Result		✓ Passed
Notice	Advise wiper blades	
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	





MOT #5	2013-11-28 13:49
MOT test	number 596112133384
Result	✓ Passed
Advice (2.5.C.1a)	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt
Notice	Under-trays fitted obscuring some underside components
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #4		2012-11-19 17:43
MOT test	number	187224822352
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #3	2012-11-19 09:59
MOT test number	766144022347
Result	🗙 Failed
Fail Nearside Rear wheel bearing has excessive play (2.6.2)	
Notice Nail in nearside front tyre	
Advice Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Parking brake lever has little reserve travel (3.1.6b)	





MOT #2		2011-11-28 17:31
MOT test number		175342631356
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #1	2011-11-28 17:31
MOT test number	495162631371
Result	✓ Passed





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	8005-25-25
Current registration	
Plate since	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-01
Last registration	2019-12-17
Complete history	See info



Registration #1	2008-12-01	28 mi
Registration #2	2011-11-28	81.142 mi
Registration #3	2012-11-19	110.291 mi
Registration #4	2012-11-19	110.291 mi
Registration #5	2013-11-28	121.751 mi
Registration #6	2014-12-01	125.271 mi
Registration #7	2015-11-30	129.553 mi
Registration #8	2015-12-04	129.622 mi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		
Registration #15		11.777 esi
Registration #14		10.000 est
-		10.000 est 10.000 est 10.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1916 kg
Max. allowed weight	2570 kg
Additional information	
Fuel tank capacity	75
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

D4EB7317581