





### General information

Make	VOLVO
Model	XC90 D5 SE
Colour	Green
Year of manufacture	2003
Top speed	115 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.0 mpg
CO2 emission	239 g/km
CO2 label	L







Internet history		
Entry 2		
Date	2021-06-29	
Pictures	2	
Listing price	View report	
LEAVE A DEPOSIT AND SECURE THIS CAR		
Pictures	10	
Listing price	View report	



source: autoonline.co.uk









### MOT history

MOT expiry date	2022-05-18
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	36
Total items failed	56

MOT #26	2021-05-19 12:26
MOT test number	996124661529
Result	✓ Passed
Next expiry date	2022-05-18

МОТ #25	2021-05-17 17:03
MOT test number	203743049899
Result	🗙 Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
<b>Fail</b> Rear Parking (secondary brake) on a single line braking system has inadequate efficiency parking brake (1.3.1 (a) (i))	fort at a wheel both
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
<b>Minor</b> Registration plate lamp insecure front and rear reg plate (4.7.1 (c) (i))	

МОТ #24	2020-01-09 13:38
MOT test number	635688453589
Result	✓ Passed





MOT #2	23	2020-01-09 10:51
MOT te	st number	500151938141
Result		🗙 Failed
Fail	Offside Rear All direction indicators obviously incorrectly positioned (4.4.3 (a))	
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)	)
Fail	Nearside Front Inner Brake disc fractured (1.1.14 (a) (ii))	
Fail	Nearside Rear All direction indicators obviously incorrectly positioned (4.4.3 (a))	
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #22	2019-02-01 15:51
MOT test number	303038697441
Result	✓ Passed





MOT #2	21	2019-01-30 14:35
MOT te	st number	408824404286
Result		× Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Fail	Rear Front passenger door cannot be opened from outside the vehicle boot lid (6.2.3	3 (a))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Nearside Rear reflector missing (4.8.2 (a) (ii))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
Fail	Offside Front Front passenger door cannot be opened from outside the vehicle (6.2.3	3 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Rear fog lamp not working (4.5.1 (a) (ii))	

МОТ #20		2017-10-03 13:39
MOT test number		977602902402
Result		✓ Passed
Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)		
Advice Offside Front Lower Susp movement rear (2.4.G.2)	ension arm synthetic bush de	eteriorated but not resulting in excessive

Advice Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear (2.4.G.2)





MOT #19	2017-10-02 12:14
MOT test number	302392040148
Result	🗙 Failed
<b>Fail</b> Rear passenger door cannot be opened from outside the vehicle boots (6.2.B.1c)	
Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but pre of dirt (2.4.G.2)	eventing the ingress
Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not result movement rear (2.4.G.2)	ting in excessive
Fail Offside Front Driver's door cannot be opened from inside the vehicle (6.2.B.1b)	
Fail Nearside Rear reflector missing (1.5.1a)	
<b>Advice</b> Nearside Front Lower Suspension arm synthetic bush deteriorated but not res movement rear (2.4.G.2)	ulting in excessive

MOT #18	2016-06-11 13:50
MOT test number	384341629059
Result	✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #17	2016-06-11 09:37
MOT test number	472045398765
Result	🗙 Failed
Fail Nearside Rear Outer Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but pr of dirt (2.4.G.2)	eventing the ingress

**Fail** Rear fog lamp not working (1.3.2b)





MOT #16		2015-06-08 15:47
MOT test	number	715319155175
Result		✓ Passed
Advice	Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.	1c)
Notice	Oil leak	
Advice	Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.	A.1c)

MOT #15	2015-06-08 13:00
MOT test number	845799555155
Result	🗙 Failed
<b>Fail</b> Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail Nearside Headlamp aim too low (1.8)	
Advice Nearside Front suspension has slight movement at a wishbone pin or bu	sh (2.5.A.1c)
Notice Oil leak	
<b>Fail</b> Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail Nearside Stop lamp not working (1.2.1b)	
Advice Offside Front suspension has slight movement at a wishbone pin or bush	n (2.5.A.1c)

MOT #14	2014-04-18 13:05
MOT test number	588038204138
Result	✓ Passed





MOT #13		2013-04-18 11:07
MOT test	number	827058203180
Result		✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.2	Li)
Notice	Oil leak	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #12		2013-04-17 10:53
MOT test number		677557703122
Result		🗙 Failed
Fail Windscreen has damage	to an area in excess of a 10mm circle within zone	e'A'(8.3.1a)
Advice Rear Exhaust has a m	inor leak of exhaust gases (7.1.2)	
Fail Offside Front Suspension	arm has excessive play in a ball joint (2.4.G.2)	
Fail Nearside Registration plat	te lamp not working (1.1.C.1d)	
Advice Offside Rear brake dis	c worn, pitted or scored, but not seriously weake	ned (3.5.1i)
Fail Service brake: efficiency	below requirements (3.7.C.1a)	
Notice Oil leak		
Fail Front registration plate m	issing (6.3.1a)	
Advice Nearside Front Tyre w	orn close to the legal limit (4.1.E.1)	
Fail Offside Windscreen wiper	does not clear the windscreen effectively (8.2.2)	)
Advice Nearside Rear Tyre wo	orn close to the legal limit (4.1.E.1)	
Fail Brake performance not te	ested (3.7.A.1)	
Advice Nearside Rear brake d	lisc worn, pitted or scored, but not seriously weak	kened (3.5.1i)
Fail Nearside Rear rear brake	grabbing severely (3.7.A.5b)	
Fail Offside Registration plate	lamp not working (1.1.C.1d)	
Fail Parking brake: efficiency	below requirements (3.7.C.1b)	
Fail Nearside Windscreen wip	er does not clear the windscreen effectively (8.2.	2)
Advice Offside Front Tyre wor	n close to the legal limit (4.1.E.1)	

MOT #11	2012-03-26 11:34
MOT test number	285946282004
Result	✓ Passed





MOT #10	2011-03-31 09:37
MOT test number	646890691087
Result	✓ Passed
MOT #9	2011-03-25 11:03
MOT test number	156174681447
Result	🗙 Failed
Fail Parking brake: efficiency below requirements (3.7.C.1b)	
<b>Fail</b> Offside Front suspension has excessive play in a lower suspension ball joint (2.	5.B.1a)
MOT #8	2010-04-01 16:38
MOT test number	382781490080
Result	🗸 Passed

MOT #7	2010-03-26 17:01
MOT test number	151415180437
Result	🗙 Failed
<b>Pass with rectification</b> Offside Headlamp aim too high (1.8)	
FailFront Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
<b>Pass with rectification</b> Nearside Headlamp aim too high (1.8)	
Fail Nearside Registration plate lamp not working (1.1.5c)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	



MOT #6

CE03DGZ
report date: 2024-03-29
2009-03-31 14:46
151400899469

MOT te	st number	151400899469
Result		✓ Passed
Advic	• Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advic	e Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advic	e Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2008-03-26 15:14
MOT test number	220686688093
Result	✓ Passed

MOT #	4	2008-03-26 11:17
MOT te	st number	124596888045
Result		× Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)	
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)	
Fail	Offside Headlamp aim too low (1.8)	
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	

МОТ #3	2007-03-28 16:37
MOT test number	162487187457
Result	✓ Passed

MOT #2	2006-02-15 16:12
MOT test number	403426646085
Result	✓ Passed





MOT #1	2006-02-15 12:43
MOT test number	853836646047
Result	🗙 Failed
NoticeN/side o/ side fron t tyres legal at testFailNearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

X Untaxed Tax expired: 12 December 2020	<b>X</b> <b>MOT</b> Expired: 18 May 2022
Tax status	Expired at 12 December 2020
Days left	1235 days too late
MOT expiry date	18 May 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	
**********	
********	
**********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-03-25
Last registration	2021-05-19
Complete history	See info



Registration #1	2003-03-25	23 mi
Registration #2	2006-02-15	53.415 mi
Registration #3	2006-02-15	53.415 mi
Registration #4	2007-03-28	69.352 mi
Registration #5	2008-03-26	83.451 mi
Registration #6	2008-03-26	83.453 mi
Registration #7	2009-03-31	95.204 mi
Registration #8	2010-03-26	104.952 mi
Registration #9	2010-04-01	104.952 mi
Registration #10	2011-03-25	114.542 mi
Registration #11	2011-03-31	114.679 mi
Registration #12	2012-03-26	124.327 mi
Registration #13	2013-04-17	132.890 mi
Registration #14	2013-04-18	132.892 mi
Registration #15	2014-04-18	138.348 mi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 mi
Registration #24		01.777 est
Registration #25		11.777 mi
Registration #26		01.707 est
CarCheck.co.uk		page 18/19

Registration #27	10.317 esi
Registration #28	11.777 est
Registration #29	11.777 esi





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Additional information	
Fuel tank capacity	72 I
Fuel delivery	Direct Injection
Number of doors	5
Engine number	94999