





### General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Red
Year of manufacture	2004
Top speed	100 mph
0 - 60 mph	14.8 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	164 g/km
CO2 label	G







# Internet history

Entry	1	

Date Pictures 2021-07-16

6

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-24
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	42
Total items failed	17

MOT #26	2024-04-25 10:36	
MOT test number	989002348045	
Result	✓ Passed	
Next expiry date	2025-04-24	
Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))		
Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))		
Advice Offside Front Headlamp has a product on the lens but not seriously red (b))	ucing light output (4.1.4	

## MOT #25

<b>MOT test number</b>	
------------------------	--

MOT test	number 703872543063
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Headlamp has a product on the lens but not seriously reducing light output both misted (4.1.4 (b))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

2023-03-22 11:13





MOT #24	2023-03-22 10:31
MOT test number	397788358457
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (2)	1.1.14 (a) (ii))
Advice Headlamp has a product on the lens but not seriously reducing light of	output both misted (4.1.4 (b))
Advice Items removed from driver's view prior to test	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lan (b) (i))	mps or light sources (4.7.1
FailStop lamp(s) all not working (4.3.1 (a) (iii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Play in steering rack inner joint(s)	

МОТ #23	2022-03-04 11:41
MOT test number	800311608762
Result	✓ Passed

MOT #22		2021-03-12 11:45
MOT test	number	621895324497
Result		✓ Passed
Advice	Front front shock absorbers are corroded	
Advice	Exhaust has a minor leak of exhaust gases front flex section is deteriorating (	6.1.2 (a))
Advice Front Play in steering rack inner joint(s) tie rods have some play		
Minor	Windscreen damaged but not adversely affecting driver's view chip in screen (	3.2 (a) (i))
Advice	Brake hose has slight corrosion to ferrule all brake hoses have corroded ferru	les (1.1.12 (f) (i))





MOT #21	2021-03-09 09:51
MOT test number	940508837774
Result	🗙 Failed
Advice Front front shock absorbers are corroded	
<b>Advice</b> Front Play in steering rack inner joint(s) tie rods have some play	
Advice Brake hose has slight corrosion to ferrule all brake hoses have corroded f	ferrules (1.1.12 (f) (i))
Minor Windscreen damaged but not adversely affecting driver's view chip in screen	een (3.2 (a) (i))
Advice Exhaust has a minor leak of exhaust gases front flex section is deteriorating (6.1.2 (a))	
Advice Osr brake isnt quite as good as nsr, advise to inspect	
<b>Fail</b> Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #20		2020-03-05 11:43
MOT test number		859758379159
Result		✓ Passed
	absorbers has slight external damage to the ca t is quite corroded (5.3.2 (b))	asing both front shock absorbers, area
Advice Front Play in	steering rack inner joint(s) both tie rod joints h	have slight play
Advice Brake hose h (i))	as slight corrosion to ferrule all 4 flex hoses ha	ave quite corroded ferrules (1.1.12 (f)
Minor Windscreen da	amaged but not adversely affecting driver's vi	ew chip in screen (3.2 (a) (i))

MOT #19		2019-02-19 12:07
MOT test	t number	400497492920
Result		✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view stone chip	) (3.2 (a) (i))





MOT #18	2018-02-27 11:07
MOT test number	744386710390
Result	✓ Passed
AdviceA/c pump drive clutch pulley semi seized when free wheelingAdviceWindscreen has damage to an area less than a 40mm circle outside zon	e 'A' (8.3.1d)

MOT #17	2018-02-20 14:41	
MOT test number	727552845108	
Result	🗙 Failed	
<b>Fail</b> Brake pipe excessively corroded front to rear (3.6.B.2c)		
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Fail         Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)		
Advice A/c pump drive clutch pulley semi seized when free wheeling		

MOT #16		2017-03-09 10:42
MOT test	number	917323673074
Result		Passed
Advice	Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
MOT #15		2016-03-07 14:57

MOT test number	803823816715
Result	✓ Passed





MOT #14	2016-03-07 11:25
MOT test number	102808276930
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Fail</b> Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D	.3)
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
<b>Fail</b> Exhaust has a major leak of exhaust gases (7.1.2)	

MOT #13	2015-03-10 14:23
MOT test number	149919965465
Result	✓ Passed
<b>Notice</b> Both front tyres wearing on both edges	

MOT #12		2015-03-10 14:23
MOT test number		177029765099
Result		🗙 Failed
Pass with rectification	Rear registration plate deteriorated (6.3.1d)	
Notice Both front tyres wearing on both edges		

MOT #11	2014-03-08 11:06
MOT test number	149537464410
Result	Passed
<b>Notice</b> Nearside rear tyre close to legal limit(1.6MM)	





МОТ #10		2014-03-08 11:06
MOT test number		156847064461
Result		🗙 Failed
Pass with rectification	Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
<b>Notice</b> Nearside rear tyre close to legal limit(1.6MM)		
Pass with rectification	Nearside Front Brake pipe excessively corroded (3.6.B.2c)	
Pass with rectification	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Pass with rectification	Rear Brake pipe excessively corroded (3.6.B.2c)	
Pass with rectification	Offside Front Brake pipe excessively corroded (3.6.B.2c)	

МОТ #9	2013-03-07 11:58
MOT test number	825916863006
Result	✓ Passed

МОТ #8	2012-03-05 09:19
MOT test number	887255662061
Result	✓ Passed
MOT #7	2011-03-03 11:14
MOT test number	636722161071
Result	✓ Passed
МОТ #6	2010-03-11 17:15
MOT test number	982490870098
Result	✓ Passed

MOT #5	2009-03-11 15:26
MOT test number	701240079080
Result	✓ Passed





MOT #4	2009-03-11 12:41
MOT test number	753650279037
Result	🗙 Failed
<ul><li>Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</li><li>Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</li></ul>	

MOT #3	2008-03-13 12:46
MOT test number	920923478011
Result	✓ Passed

МОТ #2	2008-03-13 12:46
MOT test number	990213978060
Result	× Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2007-03-08 15:09
MOT test number	554357167038
Result	✓ Passed



Tax & MOT check

<b>Taxed</b> <b>Tax due:</b> 1 September 2024	MOT Expires: 24 April 2025
Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 April 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEI
Category	Lamp
Туре	
Damage 2	AMPL
Damage 2	E Stand
Date	*
Category	A SUPP.
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	
**********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-13
Last registration	2024-04-25
Complete history	See info



Registration #1	2004-03-13	9 mi
Registration #2	2007-03-08	4.808 mi
Registration #3	2008-03-13	5.997 mi
Registration #4	2009-03-11	7.176 mi
Registration #5	2009-03-11	7.176 mi
Registration #6	2010-03-11	8.140 mi
Registration #7	2011-03-03	12.725 mi
Registration #8	2012-03-05	17.138 mi
Registration #9	2013-03-07	24.109 mi
Registration #10	2014-03-08	32.020 mi
Registration #11	2015-03-10	38.503 mi
Registration #12	2016-03-07	45.143 mi
Registration #13	2016-03-07	45.143 mi
Registration #14		11.117 esi
Registration #15		11.777 mi
Registration #16		11.117 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 esi
Registration #21		11.227 est
Registration #22		11.777 est
Registration #23		11.777 mi
Registration #24		11.117 est
Registration #25		10.777 est





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1102 kg
Max. allowed weight	1530 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 16/16

Number of axles	2
Engine number	64EA4634170