




report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ4
Colour	Grey
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	133 Nm at 4.100 rpm
Engine capacity	1.490 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	153 g/km
CO2 label	G





MOT history

MOT expiry date	2025-04-17
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	23
Total items failed	34

MOT #19	2024-04-18 13:33
MOT test number	511120468233
Result	✓ Passed
Next expiry date	2025-04-17
Advice	Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #18	2024-04-10 08:48
MOT test number	385656258295
Result	✗ Failed
Advice	Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Rear Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
Fail	Front Registration plate incorrect (0.1 (c))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))



MOT #17	2023-04-13 10:37
MOT test number	159632257305
Result	✓ Passed
Advice	Fuel supply neck corroded

MOT #16	2023-04-11 08:53
MOT test number	190345303136
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Service brake excessively binding (1.2.1 (f))
Advice	Fuel supply neck corroded

MOT #15	2022-04-12 08:38
MOT test number	867279791967
Result	✓ Passed

MOT #14	2021-03-30 11:53
MOT test number	103708998229
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c))

MOT #13	2021-03-30 11:53
MOT test number	405418514529
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c))



MOT #12	2020-04-04 13:54
MOT test number	150136187857
Result	✓ Passed
Advice	Fuel filler pipe corroded

MOT #11	2020-03-28 13:19
MOT test number	306373262440
Result	✗ Failed
Advice	Fuel filler pipe corroded
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #10	2019-03-16 10:46
MOT test number	923449380398
Result	✓ Passed

MOT #9	2018-04-07 12:52
MOT test number	432008474240
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Nail in tyre

**MOT #8**

2018-03-24 08:54

MOT test number

301826909611

Result**✗ Failed****Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Headlamp insecure (1.7.3)**Fail** Emissions not tested Due to the state of the exhaust (7.3.A.1)**Advice** Offside Front Nail in tyre**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Exhaust has a major leak of exhaust gases Rear box is broken off (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2017-04-03 12:41

MOT test number

134563247184

Result**✓ Passed****Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #6**

2017-03-25 10:17

MOT test number

787311962536

Result**✗ Failed**

- Fail** Nearside Headlamp insecure (1.7.3)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Central Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Fail** Front registration plate insecure (6.3.1b)
- Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Fail** Body has a sharp edge caused by damage Grill also insecure (6.1.C.1)

MOT #5

2016-04-11 14:28

MOT test number

709957756971

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit At 1.6mm at time of test (4.1.E.1)

**MOT #4** 2016-04-01 08:23**MOT test number** 322246899751**Result** ✗ Failed**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Tyre worn close to the legal limit At 1.6mm at time of test (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Slight bind on O/S/R wheel**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #3** 2014-04-05 11:31**MOT test number** 129575294095**Result** ✓ Passed**MOT #2** 2013-03-09 14:23**MOT test number** 245608763069**Result** ✓ Passed**MOT #1** 2013-03-09 12:47**MOT test number** 298418963057**Result** ✗ Failed**Fail** Offside Front Headlamp aim too far to the right (1.8)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Headlamp aim too far to the right (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	VO10TXA
Plate since	2019-03-29
Current registration	VO10TXA
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-04-08
Last registration	2024-04-18
Complete history	See info



Registration #1	2010-04-08	24 mi
Registration #2	2013-03-09	71.708 mi
Registration #3	2013-03-09	71.708 mi
Registration #4	2014-04-05	75.367 mi
Registration #5	2016-04-01	84.814 mi
Registration #6	2016-04-11	85.096 mi
Registration #7	2017-03-25	98.255 mi
Registration #8	2017-04-03	98.598 mi
Registration #9	2018-03-24	112.903 mi
Registration #10	2018-04-07	113.496 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi
Registration #19	2019-05-20	121.277 mi
Registration #20	2019-05-20	121.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3760 mm
Wheel base	2380 mm
Kerb weight	1020 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M15A-1408123