





report date: 2024-03-29

General information

| Make | MERCEDES-BENZ |
|---------------------|--------------------------|
| Model | SPRINTER 311 CDI LWB P/V |
| Colour | White |
| Year of manufacture | - |
| Top speed | 93 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 109 BHP |
|-------------|--------------|
| Max. torque | at 1.400 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/17



Internet history

Entry 3

Date 2022-03-31

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

| Date 2021-11-20 | |
|-----------------|--|
|-----------------|--|

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-06-28 |
|------|------------|

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT #27 2023-01-30 16:30

MOT test number 777435708408

Result ✓ Passed

Next expiry date 2024-01-29

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear AXLE SEAL LEAKING

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear AXLE SEAL LEAKING

MOT #26 2023-01-18 14:38

MOT test number 702220265552

Result X Failed

Advice Offside Rear AXLE SEAL LEAKING

Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced BACK OF CAB LOWER RIGHT (6.1.1 (c) (i))

Fail Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Rear AXLE SEAL LEAKING

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Vehicle structure is deformed and structural rigidity is significantly reduced INNER STEP WELL (6.1.1 (a) (i))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn ANTI ROLLBAR (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #25 2022-01-19 18:52

MOT test number 302957793386

CarCheck.co.uk page 3/17

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #24 2021-01-02 11:45

MOT test number 831716992576

Result ✓ Passed

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Brake pedal wearing smooth (1.1.2 (c))

MOT #23 2021-01-02 11:45

MOT test number 697414099014

Result × Failed

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Stop lamp(s) adversely affected by the operation of another lamp

(4.3.3 (b))

Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice

MOT #22 2019-09-16 16:26

MOT test number 938760496523

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/17



Fail

Fail

CN54MVJ report date: 2024-03-29

MOT test number

Result

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fluid leaking continuously posing a serious risk to road safety diesel leak (8.4.1 (a) (ii))

Nearside Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))

MOT #20

MOT test number

134184935682

Result

Advice Oil leak

2019-08-01 12:46

√ Passed

MOT #19

MOT test number

971255768202

Result

Advice Offside Rear hub oil seal leaking

Advice Oil leak

Fail Rear Brake pipe excessively corroded (1.1.11 (c))

CarCheck.co.uk page 5/17



MOT #18 2018-08-01 17:01

MOT test number 418868301395

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Engine oil leak

Advice Nearside Play in steering rack inner joint(s)

Advice All four tyres wearing on edges

Advice Corrosion around the outer perimeter of windscreen

MOT #17 2018-07-31 10:31

MOT test number 881550372054

Result X Failed

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice All four tyres wearing on edges

Advice Corrosion around the outer perimeter of windscreen

Fail Offside Rear Brake drum contaminated (1.1.14 (b))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Engine oil leak

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Play in steering rack inner joint(s)

Fail Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

CarCheck.co.uk page 6/17



2017-08-01 17:18

MOT test number 193047636311

Result
✓ Passed

Advice Nearside Rear Outer Body has slight corrosion (6.1.B.2)

Advice Offside Rear Outer Body has slight corrosion (6.1.B.2)

Advice Oil leak

MOT #16

MOT #15 2017-07-29 09:25

MOT test number 211116733481

Result X Failed

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Oil leak

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear Outer Body has slight corrosion (6.1.B.2)

Fail Offside Side repeater not working (1.4.A.2c)

Fail Offside Rear brake drum contaminated by oil DISC (3.5.1h)

Advice Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Headlamp not working on main beam (1.7.5a)

Advice Offside Rear Outer Body has slight corrosion (6.1.B.2)

Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Service brake: efficiency below requirements (3.7.B.7)

Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

CarCheck.co.uk page 7/17



MOT #14 2016-07-09 10:39 **MOT test number** 973423424051 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Nearside Rear Mudguard insecure Advice Advice Offside Front Shock absorber has a light misting of oil (2.7.3) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

| MOT #13 | 2016-07-08 17:24 |
|---|---------------------|
| MOT test number | 202174482747 |
| Result | ≍ Failed |
| Advice Nearside Front Shock absorber has a light misting of oil (2.7.3) | |
| Fail Nearside Front Front position lamp(s) not working (1.1.A.3b) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Front Front suspension has excessive play in a lower suspension ba | II joint (2.5.B.1a) |
| Advice Offside Front Shock absorber has a light misting of oil (2.7.3) | |
| Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8 | 3.2.2) |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Rear Mudguard insecure | |
| | |

CarCheck.co.uk page 8/17



MOT #12 2015-07-18 12:06

MOT test number 298459995161

Result ✓ Passed

Notice Rear brake pipes are corroded

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

Notice Very bad oil leak

Notice Very slight movement in nearside front lower ball joint

Notice Knocking in steering whilst rocking side to side

MOT #11 2015-07-17 17:21

MOT test number 586798995169

Result × Failed

Fail Service brake: efficiency below requirements (3.7.B.7)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Notice Very slight movement in nearside front lower ball joint

Fail Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Notice Knocking in steering whilst rocking side to side

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

Notice Rear brake pipes are corroded

Fail Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Fail Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Notice Very bad oil leak

CarCheck.co.uk page 9/17



Passed

MOT #10 2014-07-11 10:04

MOT test number 635512694177

Result ✓ Passed

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Notice O/s/f side marker not working

Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

Notice Engine oil leak an covered the alternator

MOT #9 2013-07-31 17:22

MOT test number 338782813241

Result ✓ Passed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Notice Knocking noise from steering rack.

Advice Offside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Both rear tyre's wearing on inner treads

Result

MOT #8 2012-07-14 13:11

MOT test number 789666692135

Advice Nearside Front Direction indicators slightly discoloured (1.4.A.2f)

Notice Oil leak

CarCheck.co.uk page 10/17



MOT #7 2012-07-14 12:05

MOT test number 206596592183

Result X Failed

Notice Oil leak

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Front Direction indicators slightly discoloured (1.4.A.2f)

MOT #6 2011-07-01 11:11

MOT test number 428412281198

Result \rightarrow Passed

MOT #5 2009-11-11 16:17

MOT test number 323325819369

Result

Passed

Advice Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4 2009-11-11 16:17

MOT test number 712465119376

Result X Failed

Pass with rectification Nearside Headlamp aim too low and too far to the right. (1.8)

Advice Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Pass with rectification Offside Headlamp aim too low and too far to the right. (1.8)

Advice Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 11/17



MOT #3 2008-11-10 16:00 **MOT test number** 534035718390 Result ✓ Passed MOT #2 2008-10-30 16:25 **MOT** test number 334064308380 Result × Failed Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #1

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 12/17



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.


Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/17



| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Export here. | |
| ******* | |
| | |
| *************************************** | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| Number of plates | , |
| Current registration | NK SIN |
| Plate since | |
| Current registration | NE SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 14/17



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 30 |
| First mileage registration | 2004-10-28 |
| Last registration | 2023-01-30 |
| Complete history | See info |



| Registration #6 2011-07-01 147.794 mi Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #8 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 20.657 mi Registration #16 Registration #18 Registration #18 Registration #19 Registration #19 Registration #19 Registration #19 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #26 Registration #26 Registration #27 Registration #28 Registration #29 Registration #29 Registration #29 Registration #29 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20 Registration #25 Registration #25 Registration #26 Registration #26 Registration #26 Registration #27 Registration #28 Registration #29 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20 Registration | | | |
|--|------------------|------------|------------|
| Registration #3 2008-10-30 118.467 mi Registration #4 2008-11-10 118.494 mi Registration #5 2009-11-11 139.108 mi Registration #6 2011-07-01 147.794 mi Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 20.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #25 Registration #25 Registration #25 Registration #25 | Registration #1 | 2004-10-28 | 13 mi |
| Registration #4 2008-11-10 118.494 mi Registration #5 2009-11-11 139.108 mi Registration #6 2011-07-01 147.794 mi Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 20.657 mi Registration #16 Registration #18 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #25 | Registration #2 | 2007-10-23 | 92.695 mi |
| Registration #5 2009-11-11 139.108 mi Registration #6 2011-07-01 147.794 mi Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 200.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #25 Registration #26 | Registration #3 | 2008-10-30 | 118.467 mi |
| Registration #6 2011-07-01 147.794 mi Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #8 2013-07-31 173.100 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 20.657 mi Registration #16 Registration #18 Registration #18 Registration #18 Registration #19 Registration #19 Registration #20 Registration #20 Registration #20 Registration #20 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #26 | Registration #4 | 2008-11-10 | 118.494 mi |
| Registration #7 2012-07-14 160.274 mi Registration #8 2012-07-14 160.274 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #24 Registration #25 Registration #25 Registration #26 | Registration #5 | 2009-11-11 | 139.108 mi |
| Registration #8 2012-07-14 160.274 mi Registration #9 2013-07-31 173.100 mi Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #6 | 2011-07-01 | 147.794 mi |
| Registration #9 | Registration #7 | 2012-07-14 | 160.274 mi |
| Registration #10 2014-07-11 184.472 mi Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 20.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #8 | 2012-07-14 | 160.274 mi |
| Registration #11 2015-07-17 196.290 mi Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #9 | 2013-07-31 | 173.100 mi |
| Registration #12 2015-07-18 196.290 mi Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #10 | 2014-07-11 | 184.472 mi |
| Registration #13 2016-07-08 208.012 mi Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #11 | 2015-07-17 | 196.290 mi |
| Registration #14 2016-07-09 208.012 mi Registration #15 2017-07-29 220.657 mi Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #12 | 2015-07-18 | 196.290 mi |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22 Registration #28 Registration #28 Registration #29 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #13 | 2016-07-08 | 208.012 mi |
| Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #14 | 2016-07-09 | 208.012 mi |
| Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #15 | 2017-07-29 | 220.657 mi |
| Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #16 | | 11.777 es |
| Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #17 | | 11.777 ms |
| Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #18 | | 11.777 es |
| Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #19 | | 11.177 mi |
| Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26 | Registration #20 | | 11.777 ms |
| Registration #23 Registration #24 Registration #25 Registration #26 | Registration #21 | | 11.177 mi |
| Registration #24 Registration #25 Registration #26 | Registration #22 | | 11.777 es |
| Registration #25 Registration #26 | Registration #23 | | 11.777 mi |
| Registration #26 | Registration #24 | | 11.777 46 |
| - | Registration #25 | | 11.777 es |
| CarCheck.co.uk page 16/17 | Registration #26 | | 11.777 es |
| | CarCheck.co.uk | | page 16/17 |

| Registration #27 | 0.00 40 |
|------------------|-----------|
| Registration #28 | 71.777 66 |
| Registration #29 | 11.777 es |
| Registration #30 | 11.777 au |

More info >



Car features

| 50225 | Air conditionin |
|--|-----------------|
| 60295 | |
| 0482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 0569 | |
| iew the complete MERCEDES-BENZ factory list for this | More info > |

Dimensions & weight

| Width | 1933 mm |
|---------------------|---------|
| Kerb weight | 2090 kg |
| Max. allowed weight | 3500 kg |

Additional information

| Fuel tank capacity | 75 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of axles | 2 |
| Engine number | 61198150828212 |

CarCheck.co.uk page 17/17