





General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | BORA SE |
| Colour | Grey |
| Year of manufacture | 1999 |
| Top speed | 121 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 115 BHP |
|-------------------------|---------------------|
| Max. torque | 169 Nm at 2.400 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.4 mpg |
| Consumption extra urban | 44.8 mpg |
| Consumption combined | 34.9 mpg |





Internet history

| Entry | 1 |
|-------|---|
| Date | |

Pictures

2021-11-09

19

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-11-17 |
|--------------------|------------|
| MOT pass rate | 68 % |
| MOT passed | 19 |
| Failed MOT tests | 9 |
| Total advice items | 61 |
| Total items failed | 28 |

| MOT #28 | 2023-11-18 12:21 | |
|---|------------------|--|
| MOT test number | 292390051467 | |
| Result | 🗸 Passed | |
| Next expiry date 2024-11-17 | | |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | | |
| Advice Nearside Front Brake pipe corroded, covered in grease or other material (2 | 1.1.11 (c)) | |

| MOT #27 | 2023-11-16 12:07 |
|--|-------------------|
| MOT test number | 611874924062 |
| Result | × Failed |
| Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) | |
| Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) | |
| Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources | ; (4.7.1 (b) (i)) |
| Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2) | 2 (b)) |
| Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1) | L (c)) |





| MOT #26 | 2022-11 | -08 14:56 |
|----------|---|-----------|
| MOT test | number 21528 | 32297554 |
| Result | | ✓ Passed |
| Advice | Rear Exhaust has a minor leak of exhaust gases and has advanced corrosion (6.1.2 (a)) | |
| Advice | Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) | |

| MOT #25 | 2021-11-09 12:10 |
|--|-------------------------------|
| MOT test number | 621410911959 |
| Result | ✓ Passed |
| Advice Offside Front Macpherson strut ball joint has | s slight play (5.3.4 (a) (i)) |

| MOT #24 | | 2021-03-29 11:06 |
|------------------------|--|---------------------|
| MOT test | number | 817590174172 |
| Result | | ✓ Passed |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive | e movement (5.3.4 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii)) |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessive r | movement (5.3.4 (a) |
| Advice | Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |





| MOT #23 | 2020-06-05 10:29 |
|------------------------|--|
| MOT test | number 316598597634 |
| Result | ✓ Passed |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 |
| Advice | Rear Service brake fluctuating, but not excessively both (1.2.1 (e)) |

| MOT #22 | 2019-04-10 11:15 |
|---|------------------|
| MOT test number | 358071670809 |
| Result | ✓ Passed |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii |)) |

| MOT #21 | 2019-04-08 11:57 |
|---|------------------|
| MOT test number | 923662193351 |
| Result | 🗙 Failed |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii |)) |
| FailNearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |

| MOT #20 | | 2018-04-17 15:11 |
|-------------------------|---|------------------------|
| MOT test | number | 190910433981 |
| Result | | ✓ Passed |
| Advice (2.4.G.2) | Nearside Front Suspension arm rubber bush deteriorated but not resulting | in excessive movement |
| Advice | Nearside Front Macpherson strut has slight movement at the upper attach | iment (2.5.A.1c) |
| Advice movement | Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not (2.4.G.2) | resulting in excessive |





| MOT #19 | 2018-04-11 15:17 |
|--|------------------|
| MOT test number | 560227477880 |
| Result | 🗙 Failed |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail Parking brake: efficiency below requirements (3.7.B.7) | |
| Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f) | |
| Advice Offside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in ex (2.4.G.2) | cessive movement |
| Fail Nearside Stop lamp not working (1.2.1b) | |
| Advice Nearside Front Macpherson strut has slight movement at the upper attachment | (2.5.A.1c) |
| Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Advice Parking brake lever has little reserve travel (3.1.6b) | |
| Advice Nearside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not result movement (2.4.G.2) | ing in excessive |
| | |

| MOT #18 | | 2017-04-18 10:30 |
|----------|---|------------------|
| MOT test | number | 622385472474 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit Bald on inner edge (4.1.E.1) | |
| Advice | Nearside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Advice | Offside Rear Tyre worn close to the legal limit on limit and bald on inner edge (4. | 1.E.1) |





| MOT #17 | 2017-04-11 11:10 |
|---|------------------|
| MOT test number | 629992808502 |
| Result | 🗙 Failed |
| Fail Offside Stop lamp not working (1.2.1b) | |
| Advice Offside Rear Tyre worn close to the legal limit on limit and bald on inner edge (4 | .1.E.1) |
| Advice Nearside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Advice Nearside Rear Tyre worn close to the legal limit Bald on inner edge (4.1.E.1) | |
| Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) | |

| MOT #16 | 2016-04 | -11 10:46 |
|-------------------------|--|-----------|
| MOT test | number 25853 | 10148640 |
| Result | | ✓ Passed |
| Advice | Park brake only just met the requirement | |
| Advice (2.4.G.2) | Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive mov | vement |
| Advice | Nearside Brake pipe slightly corroded front to rear (3.6.B.2c) | |
| Advice (2.4.G.2) | Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive mo | ovement |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |





| MOT #15 | 2015-04-14 12:17 |
|--|-----------------------|
| MOT test number | 109564605152 |
| Result | ✓ Passed |
| Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not removement (2.4.G.2) | esulting in excessive |
| Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e) | |
| Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |

| MOT #14 | 2015-04-13 13:54 |
|--|--------------------|
| MOT test number | 135833005198 |
| Result | 🗙 Failed |
| Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e) | |
| Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) | |
| Fail Parking brake: efficiency below requirements (3.7.B.7) | |
| Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |
| Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resu movement (2.4.G.2) | Iting in excessive |
| Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2) | |

| MOT #13 | 2014-03-17 17:28 |
|-----------------|------------------|
| MOT test number | 527286074023 |
| Result | ✓ Passed |

| MOT #12 | 2013-04-05 15:50 |
|--|------------------|
| MOT test number | 669155593098 |
| Result | 🗸 Passed |
| Advice Offside Brake pipe slightly corroded (3.6.B.2c) | |





| MOT #11 | 2013-04-04 11:24 |
|--|--------------------|
| MOT test number | 458644093067 |
| Result | 🗙 Failed |
| Fail Offside Front Suspension arm rubber bush bonding deteriorated resulting in (2.4.G.2) | excessive movement |
| Advice Offside Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Offside Rear Brake pad(s) wearing thin (3.5.1g) | |
| | |
| MOT #10 | 2012-03-17 08:33 |
| MOT test number | 285037272006 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2011-03-17 14:27 |
| MOT test number | 946726271037 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2010-03-24 17:32 |
| MOT test number | 990073180018 |

Result

Passed





| MOT #7 | 1 | 2010-03-23 16:38 |
|--------|--|------------------|
| MOT te | st number | 160192880409 |
| Result | | 🗙 Failed |
| Fail | Offside rear parking brake recording little or no effort (3.7.B.6a) | |
| Fail | Parking brake: efficiency below requirements (3.7.B.7) | |
| Fail | Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) | |
| Fail | Offside rear brake binding (3.7.B.1) | |
| Fail | Front brake disc excessively pitted (3.5.1h) | |
| Fail | Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) | |
| Fail | Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D |).3) |

| MOT #6 | | 2009-03-16 14:20 |
|----------|---|------------------|
| MOT test | number | 582985279036 |
| Result | | ✓ Passed |
| Advice | Offside Front brake disc slightly pitted (3.5.1h) | |
| Advice | Nearside Brake pipe slightly corroded (3.6.B.2c) | |

| MOT #5 | | 2009-03-16 14:20 |
|--------------------------|---|------------------|
| MOT test number | | 832185879096 |
| Result | | 🗙 Failed |
| Advice Nearside Brake | pipe slightly corroded (3.6.B.2c) | |
| Pass with rectification | Offside Front position lamp(s) not working (1.1.A.3b) | |
| Advice Offside Front bra | ke disc slightly pitted (3.5.1h) | |





| MOT #4 | 2008-04-15 12:16 |
|--|------------------|
| MOT test number | 290996508107 |
| Result | ✓ Passed |
| Notice Front & Rear No plates slightly defaced | |
| MOT #3 | 2008-04-07 14:37 |
| MOT test number | 880878998029 |
| Result | 🗙 Failed |
| Fail Nearside rear parking brake recording little or no effort (3.7.B.6a) | |
| Fail Parking brake: efficiency below requirements (3.7.B.7) | |
| Fail Offside rear parking brake recording little or no effort (3.7.B.6a) | |
| Notice Front & Rear No plates slightly defaced | |

| MOT #2 | | 2007-04-04 14:03 |
|------------------|---|------------------|
| MOT test | number | 133904097013 |
| Result | | ✓ Passed |
| Advice Advice | Offside Front brake disc slightly scored (3.5.1h) Centre Exhaust has part of the system slightly deteriorated (7.1.1a) | |
| | | |

| MOT #1 | 2006-04-08 08:51 |
|-----------------|------------------|
| MOT test number | 703578996002 |
| Result | ✓ Passed |





Tax & MOT check

| √ Taxed | √ MOT |
|-----------------------------|-------------------------------------|
| Tax due: 1 December 2024 | Expires: 17 November 2024 |
| Tax status | Valid until 1 December |
| Days left | 216 |
| MOT expiry date | 17 November 2024 |
| Full MOT history | See MOT history |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FETTOR |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE . |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And and a second s | |
|--|-------------|
| ********** | |
| ********* | |
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Exerned registration | |
| | |
| Plate since | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 29 |
| First mileage registration | 1999-07-08 |
| Last registration | 2023-11-18 |
| Complete history | See info |



| Registration #1 | 1999-07-08 | 9 mi |
|------------------|------------|------------|
| Registration #2 | 2006-04-08 | 39.362 mi |
| Registration #3 | 2007-04-04 | 43.325 mi |
| Registration #4 | 2008-04-07 | 46.917 mi |
| Registration #5 | 2008-04-15 | 46.942 mi |
| Registration #6 | 2009-03-16 | 51.043 mi |
| Registration #7 | 2010-03-23 | 53.493 mi |
| Registration #8 | 2010-03-24 | 53.497 mi |
| Registration #9 | 2011-03-17 | 54.912 mi |
| Registration #10 | 2012-03-17 | 56.777 mi |
| Registration #11 | 2013-04-04 | 58.210 mi |
| Registration #12 | 2013-04-05 | 58.225 mi |
| Registration #13 | 2014-03-17 | 60.505 mi |
| Registration #14 | 2015-04-13 | 63.150 mi |
| Registration #15 | 2015-04-14 | 63.158 mi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.707 esi |
| Registration #18 | | 11.777 est |
| Registration #19 | | 11.777 est |
| Registration #20 | | 11.777 est |
| Registration #21 | | 11.777 esi |
| Registration #22 | | 11.777 est |
| Registration #23 | | 11.777 esi |
| Registration #24 | | 11.117 est |
| Registration #25 | | 11.777 mi |
| Registration #26 | | 11.777 est |
| CarCheck.co.uk | | page 17/18 |
| | | |

| Registration #27 | 10.317 esi |
|------------------|------------|
| Registration #28 | 11.777 est |
| Registration #29 | 11.777 esi |
| | |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| \$0482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 2018 mm |
| Height | 1446 mm |
| Length | 4376 mm |
| Wheel base | 2519 mm |
| Additional information | |
| Fuel tank capacity | 55 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |

2

APK005086

Number of axles

Engine number