



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Red
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-04
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #17**

2022-10-07 16:25

MOT test number

986271689781

Result

✓ Passed

Next expiry date

2023-10-06

- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**




2022-09-28 16:31

MOT test number

132629073511

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Offside Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Offside Front Drive shaft joint excessively worn (6.1.7 (c) (i))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**MOT #15** 2021-08-03 09:58**MOT test number** 763781616106**Result**  Passed**MOT #14** 2021-08-02 15:25**MOT test number** 751349888834**Result**  Failed**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Offside Body panel corroded and likely to cause injury outer sill holed (6.2.1 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2020-07-31 14:05**MOT test number** 429991325246**Result**  Passed**Advice** Exhaust has a minor leak of exhaust gases front pipe flexy (6.1.2 (a))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2020-07-24 11:02

MOT test number

317134369472

Result**✗ Failed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Exhaust has a minor leak of exhaust gases front pipe flexy (6.1.2 (a))
- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11

2019-04-17 12:06

MOT test number

455420041339

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edge (5.2.3 (e))

**MOT #10** 2018-04-16 08:54**MOT test number** 513916479733**Result** ✓ Passed**MOT #9** 2017-04-28 15:57**MOT test number** 376641501087**Result** ✓ Passed**MOT #8** 2017-04-25 15:29**MOT test number** 565090226458**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded flex to w/cyl (3.6.B.2c)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Brake pipe excessively corroded flex to w/cyl (3.6.B.2c)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2015-12-22 12:51**MOT test number** 156098931987**Result** ✓ Passed**MOT #6** 2015-12-16 11:17**MOT test number** 804007197853**Result** ✗ Failed**Fail** Offside Front Macpherson strut has excessive movement at the upper attachment bearing (2.5.A.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #5** 2014-12-16 11:22**MOT test number** 699550254399**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-12-14 09:56**MOT test number** 895848443382**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #3** 2013-12-14 09:56**MOT test number** 989878943368**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Pass with rectification** Rear fog lamp not working (1.3.2b)**MOT #2** 2012-12-19 15:48**MOT test number** 985004152356**Result** ✓ Passed**MOT #1** 2011-12-22 15:39**MOT test number** 486746151493**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-26
Last registration	2022-10-07
Complete history	See info



Registration #1	2009-01-26	9 mi
Registration #2	2011-12-22	22.176 mi
Registration #3	2012-12-19	29.138 mi
Registration #4	2013-12-14	35.428 mi
Registration #5	2014-12-16	42.723 mi
Registration #6	2015-12-16	51.479 mi
Registration #7	2015-12-22	51.479 mi
Registration #8	2017-04-25	60.447 mi
Registration #9	2017-04-28	60.458 mi
Registration #10	2019-05-29	65.377 mi
Registration #11	2019-05-29	65.377 mi
Registration #12	2019-05-29	65.377 mi
Registration #13	2019-05-29	65.377 mi
Registration #14	2019-05-29	65.377 mi
Registration #15	2019-05-29	65.377 mi
Registration #16	2019-05-29	65.377 mi
Registration #17	2019-05-29	65.377 mi
Registration #18	2019-05-29	65.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG7289098