





report date: 2024-03-28

### General information

Make	NISSAN
Model	CABSTAR 34.11 SWB SHR PU 110
Colour	White
Year of manufacture	2007
Top speed	78 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.600 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/19



report date: 2024-03-28

### Internet history

Emter.	1
Entry	т.

ciitiy 1	
Date	2021-07-24
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/19



report date: 2024-03-28

# MOT history

MOT expiry date	2025-04-09
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	52
Total items failed	59

MOT #23	2024-04-10 11:34
MOT test number	424569261036
Result	<b>✓</b> Passed
Next expiry date	2025-04-09
Advice Steering column universal joint has slight wear or play X2 (2.2.2 (c))	
Minor  Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice MIL on	

CarCheck.co.uk page 3/19



report date: 2024-03-28

MOT #22 2024-03-26 15:41

MOT test number 806616492868

Result × Failed Fail Service brake efficiency below requirements (1.2.2 (a) (i)) Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Exhaust has a major leak of exhaust gases back box joint (6.1.2 (a)) Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Fail Nearside Front Lower Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i)) Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Steering column universal joint has slight wear or play X2 (2.2.2 (c)) Fail Nearside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i)) **Advice** Nearside Front Play in steering rack inner joint(s) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) MIL on **Advice** Fail Offside Front Lower Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i)) Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail

CarCheck.co.uk page 4/19



Result

FD07CNC

report date: 2024-03-28

✓ Passed

MOT #21 2023-02-25 11:24

MOT test number 113395657321

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) Advice Advice Offside Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner arch (6.2.2 (d) (i)) Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Nearside Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner arch (6.2.2 (d) (i))

MOT #20 2022-02-24 13:41

MOT test number 180288543344

**Result** 
✓ Passed

**Advice** Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

**Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 5/19



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18		2020-02-13 15:19
MOT test	number	659500402416
Result		✓ Passed
Advice (a) (i))	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive	e movement (5.3.4
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)	))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Advice</b> (5.3.4 (a)	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessi	ve movement
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Steering column universal joint has slight wear or play steering rack end of sha	ft (2.2.2 (c))

CarCheck.co.uk page 6/19



**MOT #17** 

**Advice** 

**MOT** test number

FD07CNC

report date: 2024-03-28

2020-01-30 14:41

615823439089

Result × Failed **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Steering column universal joint has slight wear or play steering rack end of shaft (2.2.2 (c)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) Fail Steering rack has excessive free play detected at the steering wheel to the extent that safe steering is affected (steering rack fitted) (2.3 (a) (ii)) Offside Front Road wheel fixing loose (5.2.1 (a) (i)) Fail

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Offside Play in steering rack inner joint(s)

Fail Power steering malfunctioning stiff steering (2.1.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #16** 2018-08-07 15:46

MOT test number 160907994207


Result \( \sqrt{Passed} \)


Advice Slight wear n/s/r anti roll bar bushes

CarCheck.co.uk page 7/19



report date: 2024-03-28





CarCheck.co.uk page 8/19



Fail

FD07CNC

report date: 2024-03-28

**MOT #13** 2017-06-03 10:13 **MOT** test number 630392035216 Result × Failed Fail Offside rear parking brake recording little or no effort (3.7.B.6a) Fail Offside Headlamp aim too high (1.8) Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Offside Rear Shock absorber has an excessively worn bush (2.7.4) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Fail Offside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2) Fail Offside Rear position lamp(s) not working (1.1.A.3b) Fail Nearside rear parking brake recording little or no effort (3.7.B.6a) Fail Nearside Headlamp aim too high (1.8) Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Nearside Rear Shock absorber has an excessively worn bush (2.7.4) Fail Nearside Ball joint has excessive play rack end (2.2.B.1f) Fail Nearside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2) **Advice** Nearside Front floor rusty Fail Offside rear brake binding (3.7.B.1)

MOT #12	2016-05-27 11:01
MOT test number	603291877393
Result	<b>✓</b> Passed

Offside Seat belt anchorage prescribed area is excessively corroded floor under seat (5.2.6)

CarCheck.co.uk page 9/19



report date: 2024-03-28

**MOT #11** 2016-05-23 14:18 **MOT** test number 328381854291 Result × Failed Fail Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2) Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Parking brake: efficiency below requirements (3.7.B.7) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Nearside rear parking brake recording little or no effort (3.7.B.6a) Fail Offside Rear Shock absorber has an excessively worn bush (2.7.4) Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2) Fail Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Nearside Rear Shock absorber has an excessively worn bush (2.7.4)

MOT #10	2015-05-16 09:02
MOT test number	839296235106
Result	✓ Passed
MOT #9	2015-05-16 09:02
MOT test number	238296935131
Result	<b>★</b> Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #8	2014-05-13 11:37
MOT test number	687983534153
Result	<b>✓</b> Passed

CarCheck.co.uk page 10/19



**MOT #7** 

Fail

Advice

**Advice** 

Fail

FD07CNC

report date: 2024-03-28

2013-05-24 14:24

MOT test number	756144843156
Result	✓ Passed
MOT #6	2012-05-17 12:08
MOT test number	488278832181
Result	<b>✓</b> Passed
MOT #5	2011-11-02 16:55
MOT test number	177266101386
Result	✓ Passed
MOT #4	2011-11-02 10:31
MOT test number	677346901320
Result	<b>×</b> Failed

Fail Nearside Front Headlamp aim too high (1.8)

Nearside Front Direction indicator not working (1.4.A.2c)

Nearside Rear Direction indicator not working (1.4.A.2c)

Exhaust has part of the system slightly deteriorated (7.1.1a)

Offside Front Front wheel bearing has slight play (2.5.A.3c)

**Fail** Nearside Side repeater not working (1.4.A.2c)

**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)

Fail Offside Front Headlamp aim too high (1.8)

MOT #3	2011-05-19 09:13
MOT test number	707369431167
Result	✓ Passed

CarCheck.co.uk page 11/19



Result

FD07CNC

report date: 2024-03-28

× Failed

MOT #2 2010-05-11 08:06

**MOT test number** 273841430415

**Result** ✓ Passed

MOT #1 2010-05-06 14:11

MOT test number 264696720187

**Fail** Parking brake lever has no reserve travel (3.1.6b)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Nearside Rear Direction indicator incomplete (1.5.A1b)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Nearside Side repeater missing (1.4.A.2b)

CarCheck.co.uk page 12/19



report date: 2024-03-28

9 April 2025





**MOT** expiry date

**Full MOT history** See MOT history

CarCheck.co.uk page 13/19



report date: 2024-03-28

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 14/19



FD07CNC report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 15/19



report date: 2024-03-28

$\sim$		h:a	+
-C)V	vner	mis	$\mathbf{I}$

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		
manners and the same of the sa		
***************************************		
***************************************		
*********		
***************************************		
	More info >	
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	OK ON THE PROPERTY OF THE PROP	
Plate since		
	More info >	

CarCheck.co.uk page 16/19



report date: 2024-03-28

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 17/19



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-04-30
Last registration	2024-04-10
Complete history	See info



Registration #1	2007-04-30	27 mi
Registration #2	2010-05-06	15.214 mi
Registration #3	2010-05-11	15.220 mi
Registration #4	2011-05-19	19.003 mi
Registration #5	2011-11-02	21.090 mi
Registration #6	2011-11-02	21.090 mi
Registration #7	2012-05-17	25.800 mi
Registration #8	2013-05-24	36.420 mi
Registration #9	2014-05-13	45.990 mi
Registration #10	2015-05-16	55.567 mi
Registration #11	2016-05-23	64.585 mi
Registration #12	2016-05-27	64.603 mi
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		77,777 au
Registration #23		11.777 66

More info >



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Dimensions & weight

Width	2265 mm
Height	2122 mm
Length	4545 mm
Kerb weight	1879 kg
Max. allowed weight	3400 kg

### Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	795019

CarCheck.co.uk page 19/19