



Mercedes-Benz

DG05RVF

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VITO 111 CDI COMPACT P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	290 Nm at 1.600 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-20
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #17	2021-11-22 17:07
MOT test number	938458801442
Result	✓ Passed
Next expiry date	2022-11-21
Advice	Front Lower to rear lower all weldiing repairs heavily undersealed

MOT #16	2020-10-07 14:05
MOT test number	470775211307
Result	✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

Advice Offside Front Subframe mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Nearside Front Subframe mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

**MOT #15**

2020-10-05 11:20

MOT test number

577900588272

Result**✗ Failed**

Advice Offside Front Subframe mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Advice Nearside Front Subframe mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Fail Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Exhaust has a major leak of exhaust gases intermediate pipe to silencer broken (6.1.2 (a))

**MOT #14**

2019-10-01 14:21

MOT test number

205943003871

Result

✓ Passed

- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Rear crossmember corroded not in proscribed areas
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5 mm (5.2.3 (e))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Nearside Front inner sill corroded not in proscribed areas
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))



MOT #13

2018-09-24 15:47

MOT test number

186676418423

Result

✓ Passed

- Advice

Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Rear crossmember has slight corrosion not in proscribed areas
- Advice

Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

N/S/F +O/S/F inner sills corroded not in proscribed areas
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #12**

2018-09-24 15:47

MOT test number

679032588554

Result**✗ Failed**

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear crossmember has slight corrosion not in proscribed areas

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice N/S/F +O/S/F inner sills corroded not in proscribed areas

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #11

2017-09-21 15:44

MOT test number

532352507291

Result**✓ Passed**

Advice Brake pipes greased

MOT #10

2016-09-22 15:17

MOT test number

111782372208

Result**✓ Passed**

Advice Oil leak

Advice All steel brake pipes showing slight corrosion

**MOT #9** 2016-09-20 09:03**MOT test number** 874851466452**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** All steel brake pipes showing slight corrosion**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear Rear wheel bearing has excessive play (2.6.2)**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Rear wheel bearing has excessive play (2.6.2)**Advice** Oil leak**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2015-09-04 14:40**MOT test number** 123042574295**Result** ✓ Passed**MOT #7** 2014-09-27 10:15**MOT test number** 896760374206**Result** ✓ Passed**MOT #6** 2013-09-11 14:15**MOT test number** 785104753268**Result** ✓ Passed

**MOT #5** 2012-08-10 14:55**MOT test number** 367583722212**Result** ✓ Passed**MOT #4** 2011-08-12 10:54**MOT test number** 658104521257**Result** ✓ Passed**MOT #3** 2010-08-13 15:21**MOT test number** 312205420290**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-07-28 14:59**MOT test number** 560459509216**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #1** 2008-02-14 10:47**MOT test number** 110755948471**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-01
Last registration	2021-11-22
Complete history	See info



Registration #1	2005-03-01	23 mi
Registration #2	2008-02-14	43.063 mi
Registration #3	2009-07-28	55.750 mi
Registration #4	2010-08-13	64.509 mi
Registration #5	2011-08-12	73.652 mi
Registration #6	2012-08-10	85.943 mi
Registration #7	2013-09-11	94.406 mi
Registration #8	2014-09-27	100.801 mi
Registration #9	2015-09-04	108.906 mi
Registration #10	2016-09-20	128.154 mi
Registration #11	2017-09-20	151.377 mi
Registration #12	2018-09-20	171.377 mi
Registration #13	2019-09-20	191.377 mi
Registration #14	2020-09-20	211.377 mi
Registration #15	2021-09-20	231.377 mi
Registration #16	2022-09-20	251.377 mi
Registration #17	2023-09-20	271.377 mi
Registration #18	2024-09-20	291.377 mi
Registration #19	2025-09-20	311.377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	64698250107897