



report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA VVT +
Colour	Blue
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	145 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	32.5 mpg





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history****MOT #13**

2022-09-02 08:19

**MOT test number**

313383059087

**Result****✗ Failed**

- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Headlamp aim too low body damage (4.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12**

2021-08-25 14:20

**MOT test number**

387484473282

**Result****✓ Passed**

- Advice** Central Oil leak, but not excessive transmission oil leak (8.4.1 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2021-08-23 16:11

**MOT test number**

965163679149

**Result****✗ Failed**

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Rear Stop lamp(s) likely to become detached (4.3.1 (c) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Central Oil leak, but not excessive transmission oil leak (8.4.1 (a) (i))
- Fail** Battery leaking (4.13 (b))

**MOT #10**

2021-07-31 12:52

**MOT test number**

700450049735

**Result****✗ Failed**

- Fail** Supplementary restraint system warning lamp indicates a fault air bag light (7.1.6 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Windscreen washer bottle leaking
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and slightly perished (5.2.3 (e))
- Fail** Offside Rear Position lamp likely to become detached (4.2.1 (c) (ii))
- Advice** Near side front bumper and wing slight damage

**MOT #9**

2020-08-06 09:25

**MOT test number**

868006904067

**Result**

✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material o/s n/s (1.1.11 (c))**Advice** Corroded underneath / suspension corroded**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing o/s n/s (5.2.3 (d) (ii))**MOT #8**

2020-08-05 16:28

**MOT test number**

236819438446

**Result**

✗ Failed

**Fail** Front Windscreen wiper does not clear the windscreen effectively o/s n/s (3.4 (b) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material o/s n/s (1.1.11 (c))**Advice** Rear Tyre slightly damaged/cracking or perishing o/s n/s (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Rear Parking brake efficiency below requirements o/s n/s (1.4.2 (a) (i))**Advice** Corroded underneath / suspension corroded**Fail** Front Brake pad(s) less than 1.5 mm thick o/s n/s (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**MOT #7**

2019-04-30 12:34

**MOT test number**

781033748423

**Result**

✓ Passed

**Advice** Underneath corroded partly undersealed suspension corroded**Advice** Front Brake pad(s) wearing thin o/s n/s (1.1.13 (a) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing o/s n/s (5.2.3 (d) (ii))

**MOT #6** 2018-05-29 10:15**MOT test number** 995078764287**Result** ✓ Passed**Advice** Nearside Rear Slight cracking around tread pattern (perished)**MOT #5** 2016-08-12 10:27**MOT test number** 112534513335**Result** ✓ Passed**Advice** Underbody rust**MOT #4** 2016-08-02 10:32**MOT test number** 134203763878**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Underbody rust**MOT #3** 2015-08-11 12:58**MOT test number** 158892380596**Result** ✓ Passed**MOT #2** 2014-08-19 15:07**MOT test number** 289631334281**Result** ✓ Passed**MOT #1** 2014-08-19 13:14**MOT test number** 159381034220**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>WV55FTY</b>
Plate since	2019-09-29
Current registration	<b>WV55FTY</b>
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2005-10-11
Last registration	2022-09-02
Complete history	<a href="#">See info</a>



Registration #1	2005-10-11	15 mi
Registration #2	2014-08-19	34.493 mi
Registration #3	2014-08-19	34.493 mi
Registration #4	2015-08-11	39.914 mi
Registration #5	2016-08-02	41.282 mi
Registration #6	2016-08-12	41.282 mi
Registration #7	2018-05-29	43.544 mi
Registration #8	2019-04-30	45.465 mi
Registration #9	2020-05-20	50.277 mi
Registration #10	2020-05-20	50.277 mi
Registration #11	2020-05-20	50.277 mi
Registration #12	2020-05-20	50.277 mi
Registration #13	2020-05-20	50.277 mi
Registration #14	2020-05-20	50.277 mi
Registration #15	2020-05-20	50.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4005 mm
Wheel base	2440 mm
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M16A-1102296