





General information

Make	HYUNDAI
Model	COUPE S
Colour	Red
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	143 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg





Internet history

Entry 1

Date Pictures

Listing price

2021-08-31

View report

9



source: autotrader.co.uk



MOT history

MOT #17		2022-09-23 14:11
MOT test num	ber	142904916253
Result		✓ Passed
Next expiry da	ote	2023-09-22
Advice From	nt Coil spring corroded Both (5.3.1 (b) (i))	
Advice Nea	arside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rea	r Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Rea	r Fuel Pipe/s corroded	
Advice Rea	r Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Minor Offsi	de Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #16	2023	1-09-23 15:41
MOT test	number 4	11420147983
Result		🗸 Passed
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c)) (i))
Advice	Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Coil spring corroded both sides (5.3.1 (b) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	



MV56BBO report date: 2024-03-28

MOT #15	2021-09-22 11:16
MOT test number	702905507885
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Front Coil spring corroded both sides (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduced	(6.1.1 (c) (i))
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2020-09-23 14:46
MOT test number	593421242086
Result	✓ Passed

MOT #13	2018-05-15 10:41	
MOT test number	743575160541	
Result	✓ Passed	
MOT #12	2017-05-22 09:41	
MOT test number 810662238941		
Result	✓ Passed	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		



MV56BBO
report date: 2024-03-28

MOT #11		2016-05-31 18:01
MOT test	number	829475018440
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin both (3.5.1g)	
Advice	Exhaust rusty	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
MOT #10		2016-05-31 08:56

MOT test number
499031904584

Result
× Failed

Advice
Offside Front Brake pad(s) wearing thin (3.5.1g)

Fail
Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

Fail
Parking brake: efficiency below requirements (3.7.B.7)

Advice
Rear Brake pad(s) wearing thin both (3.5.1g)

Advice
Exhaust rusty

МОТ #9	2015-06-09 12:30
MOT test number	945290265150
Result	✓ Passed

MOT #8	2014-12-01 09:55
MOT test number	859685834301
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #7	2013-11-30 14:05
MOT test number	496474733487
Result	✓ Passed



MV56BBO report date: 2024-03-28

MOT #6	2013-11-29 14:41
MOT test number	235133433366
Result	🗙 Failed
FailOffside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)FailNearside Rear Tyre has ply or cords exposed (4.1.D.1b)	
MOT #5	2012-11-29 10:22

	2012-11-29 10.22
MOT test number	905124032394
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #4	2011-11-25 10:00
MOT test number	139459621365
Result	✓ Passed

MOT #3	2010-11-30 14:35
MOT test number	282934930396
Result	✓ Passed

MOT #2	2010-11-29 13:06
MOT test number	973483530352
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #1	2009-08-13 11:25
MOT test number	473485829233
Result	✓ Passed





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

And a second sec	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



MV56BBO report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-04
Last registration	2022-09-23
Complete history	See info



Registration #1	2006-09-04	17 mi
Registration #2	2009-08-13	25.907 mi
Registration #3	2010-11-29	36.832 mi
Registration #4	2010-11-30	36.832 mi
Registration #5	2011-11-25	44.488 mi
Registration #6	2012-11-29	53.060 mi
Registration #7	2013-11-29	63.076 mi
Registration #8	2013-11-30	63.114 mi
Registration #9	2014-12-01	72.960 mi
Registration #10	2015-06-09	77.276 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi





Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1332 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED6382478