



Mercedes-Benz

DF54DKX

report date: 2024-03-29

General information

Make	MERCEDES
Model	SPRINTER 311 CDI P/V
Colour	White
Year of manufacture	2005
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	270 Nm at 1.400 rpm
Engine capacity	2.151 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2020-12-16
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	117
Total items failed	39

MOT #19	2019-12-11 14:56
---------	------------------

MOT test number	513856623524
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2020-12-16
------------------	------------

- Advice** Nearside inner of outer sill corroded in several places
- Advice** Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security outrigger (6.2.2 (d) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced several places (6.1.1 (c) (i))
- Advice** Offside inner of outer sill corroded in several places
- Advice** Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security outrigger (6.2.2 (d) (i))

**MOT #18**

2018-12-14 10:52

MOT test number

446577367711

Result

✓ Passed

- Advice** Nearside Rear outer sill holed/corroded but not in prescribed area
- Advice** Nearside Front inner sill/step holed/corroded but not in prescribed area
- Advice** Nearside Brake pipe corroded, covered in grease or other material front section of front to rear (1.1.11 (c))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Offside Front outer sill corroded into door edge
- Advice** Oil leak
- Advice** Both sills front to back inner and outers corroded and in poor condition
- Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive door edge just below catch (7.1.1 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Nearside Front outer sill corroded
- Advice** Engine as blowing noise sounding like injector

**MOT #17**

2018-12-03 14:50

MOT test number

792779453780

Result**✗ Failed****Advice** Engine as blowing noise sounding like injector**Advice** Nearside Brake pipe corroded, covered in grease or other material front section of front to rear (1.1.11 (c))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer quarter sill (5.3.6 (a) (i))**Advice** Nearside Front inner sill/step holed/corroded but not in prescribed area**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength out rigger to inner sill next to rear spring hanger (5.3.6 (a) (i))**Advice** Offside Front outer sill corroded into door edge**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Both sills front to back inner and outers corroded and in poor condition**Fail** Parking brake lever has excessive movement indicating incorrect adjustment no reserve travel (1.1.6 (c))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer quarter sill (5.3.6 (a) (i))**Advice** Oil leak**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))**Advice** Nearside Front outer sill corroded**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength out rigger to inner sill next to rear spring hanger (5.3.6 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear outer sill holed/corroded but not in prescribed area**Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive door edge just below catch (7.1.1 (a) (i))

**MOT #16**

2017-12-11 16:06

MOT test number

153919505525

Result

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer rear quarter sills (2.4.A.3)
- Advice** Oil leak
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer sills including out riggers and spring hangers corroded (2.4.A.3)
- Advice** Offside inner and outer sill corroded
- Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer step (5.2.6)
- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive B pillar to outer step and sill (5.2.6)
- Advice** Nearside Front Lower Ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer rear quarter sills (2.4.A.3)
- Advice** Nearside inner and outer sill corroded
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer sills including out riggers and spring hangers corroded (2.4.A.3)



MOT #15	2017-12-04 10:52
MOT test number	466287001921
Result	✗ Failed

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer sills including out riggers and spring hangers corroded (2.4.A.3)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside inner and outer sill corroded

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Nearside Seat belt anchorage prescribed area is corroded but not considered excessive B pillar to outer step and sill (5.2.6)

Fail Offside Front Seat belt anchorage prescribed area is excessively corroded panel just rear of B pillar (5.2.6)

Advice Nearside Front Lower Ball joint has slight play (2.2.B.1f)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Fail Offside Front Body has a sharp edge caused by corrosion door (6.1.C.1)

Advice Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer rear quarter sills (2.4.A.3)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Oil leak

Advice Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer sills including out riggers and spring hangers corroded (2.4.A.3)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside inner and outer sill corroded

Fail Offside Front Seat belt anchorage prescribed area is excessively corroded B pillar (5.2.6)

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer step (5.2.6)

Advice Offside Front Lower Ball joint has slight play (2.2.B.1f)

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive inner and outer rear quarter sills (2.4.A.3)



MOT #14

2016-11-29 15:30

MOT test number

120163450383

Result

✓ Passed

- Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice

Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive B pillar heavily corroded (5.2.6)
- Advice

Both outer sills and sill lips are heavily corroded and in need of attention
- Advice

Offside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill heavily corroded (5.2.6)
- Advice

Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice

Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice

Offside Front shocker weak
- Advice

Nearside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill heavily corroded (5.2.6)
- Advice

Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice

Number 2 injector chuffing

**MOT #13**

2016-11-21 10:25

MOT test number

158437800486

Result**✗ Failed**

- Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill heavily corroded (5.2.6)
- Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Fail** Central Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Offside Front shocker weak
- Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Offside Rear Leaf spring to axle securing bolt insecure (2.4.B.7b)
- Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive B pillar heavily corroded (5.2.6)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill heavily corroded (5.2.6)
- Advice** Number 2 injector chuffing
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Brake cable has wires broken and is significantly weakened (3.5.1b)
- Advice** Both outer sills and sill lips are heavily corroded and in need of attention

**MOT #12**

2015-11-30 10:45

MOT test number

621197976538

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases at various points (7.1.2)

Advice

Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive B pillar (5.2.6)

Advice

Brake pedal slightly spongy

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Oil leak

MOT #11

2014-12-12 16:39

MOT test number

176506744301

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #10

2014-12-08 12:30

MOT test number

888502844395

Result

✗ Failed

Fail

Nearside Front Headlamp aim too low (1.8)

Fail

Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Fail

Parking brake lever has no reserve travel (3.1.6b)

Fail

Offside Front Headlamp aim too low (1.8)

Fail

Nearside Rear Stop lamp not working (1.2.1b)



MOT #9	2013-12-09 14:37
MOT test number	527793943377
Result	✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #8	2012-12-06 16:44
MOT test number	219341342364
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Brake pipe slightly corroded (3.6.B.2c)

**MOT #7**

2012-11-29 14:47

MOT test number

756914132383

Result**✗ Failed**

- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Fail** Parking brake lever ratchet mechanism is broken (3.1.5)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Inner Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside rear brake binding (3.7.B.1)
- Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)

MOT #6

2011-12-13 15:28

MOT test number

145587841339

Result**✓ Passed**

- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive (5.2.6)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #5**

2011-12-05 15:04

MOT test number

229389731358

Result**✗ Failed**

- Advice** Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Fail** Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive (5.2.6)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Parking brake lever has no reserve travel (3.1.6b)

MOT #4

2010-12-06 15:46

MOT test number

344110940316

Result**✓ Passed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



MOT #3	2009-12-14 11:51
MOT test number	820358349309
Result	✓ Passed
Advice	Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Travel in park brake cable not too the top but over half way to top

MOT #2	2008-12-08 14:49
MOT test number	593823348315
Result	✓ Passed
Advice	Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #1	2007-12-17 15:55
MOT test number	914911657328
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 DF54DKX
Plate since	2019-06-29
Current registration	 DF54DKX
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-02-02
Last registration	2019-12-11
Complete history	See info



Registration #1	2005-02-02	24 mi
Registration #2	2007-12-17	45.054 mi
Registration #3	2008-12-08	54.361 mi
Registration #4	2009-12-14	63.891 mi
Registration #5	2010-12-06	72.750 mi
Registration #6	2011-12-05	81.040 mi
Registration #7	2011-12-13	81.052 mi
Registration #8	2012-11-29	88.937 mi
Registration #9	2012-12-06	89.065 mi
Registration #10	2013-12-09	97.228 mi
Registration #11	2014-12-09	97.228 mi
Registration #12	2015-12-09	97.228 mi
Registration #13	2016-12-09	97.228 mi
Registration #14	2017-12-09	97.228 mi
Registration #15	2018-12-09	97.228 mi
Registration #16	2019-12-09	97.228 mi
Registration #17	2020-12-09	97.228 mi
Registration #18	2021-12-09	97.228 mi
Registration #19	2022-12-09	97.228 mi
Registration #20	2023-12-09	97.228 mi

More info >



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	61198151011238