



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE ECO
Colour	White
Year of manufacture	-
Top speed	94 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	7
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT #13	2022-05-05 13:19
MOT test number	473467629909
Result	✓ Passed
Next expiry date	2023-05-04
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement saddle bush (5.3.4 (a) (i))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed starting to fray (7.1.2 (b) (ii))

MOT #12	2021-01-15 11:39
MOT test number	946314513376
Result	✓ Passed
Minor	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11	2020-02-17 14:42
MOT test number	470308682880
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))



MOT #10 2020-02-06 13:12

MOT test number 732542866919

Result ✗ Failed

- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Rear Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

**MOT #9** 2018-06-25 15:41**MOT test number** 751928160344**Result** ✓ Passed**Advice** Rear shox bushs split**Advice** Offside Front Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**MOT #8** 2018-06-23 10:24**MOT test number** 419510122625**Result** ✗ Failed**MAJOR** Central Front Exhaust has a major leak of exhaust gases flex (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**Advice** Rear shox bushs split**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**MOT #7** 2017-06-15 10:08**MOT test number** 641040423079**Result** ✓ Passed**Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2017-06-14 13:51

**MOT test number**

197276437990

**Result**

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5**

2016-05-07 10:32

**MOT test number**

354916078144

**Result**

✓ Passed

- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4**

2016-05-06 14:47

**MOT test number**

713505151374

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Rear Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3**

2015-05-06 14:46

**MOT test number**

507086425124

**Result****✓ Passed**

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)



MOT #2

2015-04-30 12:05

MOT test number

498510725179

Result

✗ Failed

- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Nearside Headlamp aim too high (1.8)
- Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)
- Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail

Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Fail

Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail

Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail

Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Fail

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)





MOT #12013-08-07 14:09

MOT test number376509313258

Result

✓ Passed

- Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)
- Notice

Oil leak
- Advice

Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-18
Last registration	2022-05-05
Complete history	<a href="#">See info</a>



Registration #1	2010-06-18	29 mi
Registration #2	2013-08-07	45.564 mi
Registration #3	2015-04-30	61.061 mi
Registration #4	2015-05-06	61.061 mi
Registration #5	2016-05-06	69.685 mi
Registration #6	2016-05-07	69.685 mi
Registration #7	2017-06-14	77.837 mi
Registration #8	2017-06-15	77.837 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	5718881