



**M77XKB**


report date: 2024-03-28

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Red
Year of manufacture	1997
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.980 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg







Internet history

Entry 1

Date	2021-10-02
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	37
Total items failed	22

MOT #20	2023-06-16 10:49
MOT test number	861449126683
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #19	2022-06-23 08:25
MOT test number	863382336541
Result	✓ Passed

MOT #18	2021-05-20 09:57
MOT test number	617849609059
Result	✓ Passed
Advice	Front tyres starting to perish

MOT #17	2017-12-23 11:00
MOT test number	736345781178
Result	✓ Passed

**MOT #16**

2017-12-23 10:46

**MOT test number**

804706319141

**Result**

✗ Failed

- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

**MOT #15**

2016-11-14 14:58

**MOT test number**

387427894428

**Result**

✓ Passed

- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded in wheel arch (3.6.B.2c)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #14**

2016-11-04 16:13

**MOT test number**

728885512730

**Result****✗ Failed**

- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Offside Rear Subframe mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Front Brake pipe excessively corroded across front of car (mark in yellow chalk) (3.6.B.2c)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Rear Subframe mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Shock absorber insecure lower bolt loose (2.7.2b)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Nearside Front Brake pipe slightly corroded in wheel arch (3.6.B.2c)

**MOT #13**

2015-09-09 15:25

**MOT test number**

372738516529

**Result****✓ Passed**

**MOT #12**

2014-09-04 09:25

**MOT test number**

266447544242

**Result**

✓ Passed

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Notice** Welding has been carried out to the underside of the vehicle
- Advice** Offside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

**MOT #11**

2013-06-17 09:15

**MOT test number**

269898363172

**Result**

✓ Passed

**MOT #10**

2013-06-05 10:52

**MOT test number**

766436053127

**Result**

✗ Failed

- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Nearside Front Lower Shock absorber has an excessively worn bush (2.7.4)
- Fail** Offside Rear Anti-roll bar linkage rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Notice** Both rear tyres heavily perished

**MOT #9** 2012-05-16 14:52**MOT test number** 457767232148**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #8** 2011-05-24 12:33**MOT test number** 566354041141**Result** ✓ Passed

- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2011-05-12 10:11**MOT test number** 916902831155**Result** ✗ Failed

- Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #6** 2010-05-14 09:19**MOT test number** 383054330159**Result** ✓ Passed**MOT #5** 2010-05-05 10:15**MOT test number** 991615820100**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #4** 2009-05-01 12:48**MOT test number** 421081629159**Result** ✓ Passed**MOT #3** 2008-05-07 16:28**MOT test number** 622308228117**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-04-17 10:41**MOT test number** 793227007155**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-06-19 12:33**MOT test number** 401540176165**Result** ✓ Passed





Tax & MOT check

✗  
Untaxed

Tax expired:  
8 September 2023

✓  
MOT

Expires:  
22 June 2024

Tax status	Expired at 8 September
Days left	235 days too late
MOT expiry date	22 June 2024
Full MOT history	<a href="#">See MOT history</a>



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	M77XKB
Plate since	2024-03-28
Current registration	M77XKB
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1997-02-26
Last registration	2023-06-16
Complete history	<a href="#">See info</a>



Registration #1	1997-02-26	11 mi
Registration #2	2006-06-19	50.238 mi
Registration #3	2007-04-17	53.290 mi
Registration #4	2008-05-07	58.907 mi
Registration #5	2009-05-01	64.375 mi
Registration #6	2010-05-05	69.304 mi
Registration #7	2010-05-14	69.401 mi
Registration #8	2011-05-12	75.262 mi
Registration #9	2011-05-24	75.778 mi
Registration #10	2012-05-16	83.232 mi
Registration #11	2013-06-05	89.690 mi
Registration #12	2014-06-05	95.148 mi
Registration #13	2015-06-05	100.606 mi
Registration #14	2016-06-05	106.064 mi
Registration #15	2017-06-05	111.522 mi
Registration #16	2018-06-05	116.980 mi
Registration #17	2019-06-05	122.438 mi
Registration #18	2020-06-05	127.896 mi
Registration #19	2021-06-05	133.354 mi
Registration #20	2022-06-05	138.812 mi
Registration #21	2023-06-05	144.270 mi
Registration #22	2024-06-05	149.728 mi

More info >



Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	CE9701071248