





General information

Make	HONDA
Model	LOGO 8V
Colour	Red
Year of manufacture	2000
Top speed	90 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	64 BHP	0 < 101 A
Max. torque	108 Nm at 2.500 rpm	101 - 120 B
Engine capacity	1.343 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Petrol	166 - 185
Consumption city	32.5 mpg	186 - 225
Consumption extra urban	46.3 mpg	225+ L
Consumption combined	40.4 mpg	





Internet history

Entry 1

Date

2021-08-31

Pictures

Listing price

View report

8



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	40
Total items failed	4

MOT #21	2023-08-08 11:25
MOT test number	664821018167
Result	✓ Passed
Next expiry date	2024-08-07
Advice Offside Front Cab or chassis corroded within 30cm of a mounting, overall security (6.2.2 (d) (i))	, but not seriously affecting
Advice Offside Rear Cab or chassis corroded within 30cm of a mounting, overall security (6.2.2 (d) (i))	but not seriously affecting
Advice Nearside Front Cab or chassis corroded within 30cm of a mountin overall security (6.2.2 (d) (i))	g, but not seriously affecting
Advice Nearside Rear Cab or chassis corroded within 30cm of a mounting overall security (6.2.2 (d) (i))	g, but not seriously affecting

МОТ #20	2022-01-31 09:33
MOT test number	890533366795
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	



MOT #19		2022-01-27 09:48
MOT test	number	600947623960
Result		🗙 Failed
MAJOR	Front Track rod end ball joint has excessive play n/s and o/s (2.1.3 (b) (i))	
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR significant	Nearside Outer Integral body structure corroded to the extent that the rigio ly reduced (6.1.1 (c) (i))	dity of the assembly is
MAJOR significant	Nearside Rear Integral body structure corroded to the extent that the rigid ly reduced inner arch (6.1.1 (c) (i))	ity of the assembly is
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
MAJOR significant	Offside Outer Integral body structure corroded to the extent that the rigidit ly reduced (6.1.1 (c) (i))	ty of the assembly is

MOT #18	2021-01-29 13:38
MOT test number	208076842498
Result	✓ Passed
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2020-01-29 14:33
MOT test number	749877655916
Result	✓ Passed

MOT #16	2018-11-09 10:31
MOT test number	893773493438
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Slight blow from rear exhaust	
Advice Body sills are corroded	

X564ADM

report date: 2024-03-28





MOT #15		2017-11-07 09:29
MOT test	number	725831139694
Result		✓ Passed
Advice	Cat heat shield is insecure	
Advice	Off side inner brake pad is wearing low	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.	3.1d)
Advice	Front tyres are scrubbed on edges	

MOT #14	2016-09-01 15:48
MOT test number	512814215436
Result	✓ Passed
Advice Idle is poor	

MOT #13	2016-09-01 09:33
MOT test number	495999722822
Result	🗙 Failed
Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Advice Idle is poor	

MOT #12		2015-10-15 13:31
MOT test	number	396435999164
Result		✓ Passed
Advice	Off side front wing and door badly dented	
Advice	Nearside Rear tyre is wearing out of shape	
Advice	Slight leak from power steering rack area	



-00-		report date: 2024-03-28
MOT #11		2015-10-12 08:51
MOT test num	ber	177039789009
Result		🗙 Failed
Advice Slig	ght leak from power steering rack area	
Advice Cer	ntre exhaust mount is broken	
Advice Nea	arside Rear tyre is wearing out of shape	
	e Rear Body or chassis has excessive corrosion, seriously affectin tings outer body sill (6.1.B.2)	ig its strength within 30cm of
Advice Off	side front wing and door badly dented	

MOT #10	2014-10-13 09:35
MOT test number	138966784215
Result	✓ Passed

MOT #9	2013-09-27 09:32
MOT test number	108510973259
Result	✓ Passed
NoticeNearside front tyre wearing on inner edgeAdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Holic Tyre worn close to the legal limit (4.1.L.1)	

МОТ #8	2012-10-11 11:01
MOT test number	716635582209
Result	✓ Passed
Notice Both ft tyres wearing on the edges	

MOT #7	2011-10-13 09:57
MOT test number	385856781292
Result	✓ Passed

X564ADM





MOT #6	2010-10-25 09:36
MOT test number	204108490257
Result	✓ Passed
MOT #5	2009-11-10 11:30
MOT test number	693534119300
Result	✓ Passed
MOT #4	2008-11-25 10:35
MOT test number	643210938347

Result		×	Failed
Advice N	learside Rear T	yre worn close to the legal limit (4.1.E.1)	
Pass with	rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)			

MOT #3		2008-11-25 10:35
MOT test	number	182040738399
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2		2007-11-13 14:58
MOT test	number	920947217380
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #1	2006-11-16 15:27
MOT test number	720650226396
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





Tax & MOT check

X Untaxed	√ MOT
Tax expired: 27 March 2024	Expires: 7 August 2024
Tax status	Expired at 27 March 2024
Days left	33 days too late
MOT expiry date	7 August 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-10-26
Last registration	2023-08-08
Complete history	See info



Registration #1	2000-10-26	20 mi
Registration #2	2006-11-16	18.607 mi
Registration #3	2007-11-13	21.348 mi
Registration #4	2008-11-25	23.941 mi
Registration #5	2009-11-10	26.381 mi
Registration #6	2010-10-25	28.719 mi
Registration #7	2011-10-13	30.489 mi
Registration #8	2012-10-11	32.333 mi
Registration #9	2013-09-27	33.593 mi
Registration #10	2014-10-13	36.124 mi
Registration #11	2015-10-12	42.487 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.117 esi
Registration #18		11.777 est
Registration #18 Registration #19		11.277 est 21.277 est
-		01,000 est 01,000 est 01,000 est
Registration #19		01,000 est 01,000 est 01,000 est 01,000 est

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1645 mm
Height	1524 mm
Length	3785 mm
Kerb weight	880 kg
Additional information	
Fuel tank capacity	40 I
Fuel tank capacity Fuel delivery	40 I Multi-Point Injection
Fuel delivery	Multi-Point Injection