



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





MOT history

MOT expiry date	2024-10-02
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	35
Total items failed	15

MOT #15	2023-09-28 09:55
---------	------------------

MOT test number	846605756267
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-02
------------------	------------

- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm on inner edge (5.2.3 (e))
- Advice** Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity lights tinted both sides (4.2.3 (b) (ii))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes worn & splitting both sides (5.3.4 (a) (i))
- Advice** Offside Front Upper Shock absorbers has a slightly worn bush top mount slight play (5.3.2 (c))

**MOT #14**

2023-09-27 12:59

**MOT test number**

249746198202

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm on inner edge (5.2.3 (e))**Fail** Front Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt boot split (2.1.3 (g) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split (6.1.7 (g) (ii))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Coolant leak coolant low**Fail** Front Suspension arm pin or bush excessively worn lower arm rear bushes excessively split & worn both sides (5.3.4 (a) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush top mount slight play (5.3.2 (c))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split (6.1.7 (g) (ii))**Fail** Rear Anti-roll bar linkage ball joint excessively worn both sides (5.3.4 (a) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes worn & splitting both sides (5.3.4 (a) (i))**Advice** Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity lights tinted both sides (4.2.3 (b) (ii))

**MOT #13**

2022-09-30 16:19

**MOT test number**

662174481276

**Result**

✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2021-10-02 07:35

**MOT test number**

669606524145

**Result**

✓ Passed

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #11** 2020-09-10 08:38**MOT test number** 459633485764**Result** ✓ Passed**Advice** Tyre slightly damaged all (5.2.3 (d) (ii))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-10-03 09:09**MOT test number** 263146116974**Result** ✓ Passed**MOT #9** 2019-10-02 11:20**MOT test number** 844064130460**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low and too far to the right. (4.1.2 (a))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Rear Registration plate incorrect (0.1 (c))**Pass with rectification** Offside Headlamp aim too far to the left (4.1.2 (a))**Fail** Front Registration plate missing (0.1 (a))**MOT #8** 2018-01-20 12:09**MOT test number** 371598847374**Result** ✓ Passed

**MOT #7** 2017-02-06 11:18**MOT test number** 670195834898**Result** ✓ Passed**Advice** Both rear tyres slightly worn on inner edge**MOT #6** 2016-02-05 14:41**MOT test number** 370169037022**Result** ✓ Passed**MOT #5** 2015-02-09 11:19**MOT test number** 129380045444**Result** ✓ Passed**MOT #4** 2014-05-13 16:11**MOT test number** 216703834172**Result** ✓ Passed**MOT #3** 2014-05-13 11:23**MOT test number** 258133034180**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-05-15 11:03**MOT test number** 578555333112**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-06-02 09:19
MOT test number	375604152188
Result	✓ Passed
Advice	Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
2 October 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>KN09BVZ</b>
Plate since	2019-09-29
Current registration	<b>KN09BVZ</b>
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-05-28
Last registration	2023-09-28
Complete history	<a href="#">See info</a>



Registration #1	2009-05-28	15 mi
Registration #2	2012-06-02	23.001 mi
Registration #3	2013-05-15	29.997 mi
Registration #4	2014-05-13	36.585 mi
Registration #5	2014-05-13	36.590 mi
Registration #6	2015-02-09	42.470 mi
Registration #7	2016-02-05	53.860 mi
Registration #8	2017-02-06	65.162 mi
Registration #9	2018-05-28	76.557 mi
Registration #10	2019-05-28	88.000 mi
Registration #11	2020-05-28	99.500 mi
Registration #12	2021-05-28	111.000 mi
Registration #13	2022-05-28	122.500 mi
Registration #14	2023-05-28	134.000 mi
Registration #15	2023-09-28	145.500 mi
Registration #16	2023-09-28	157.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	8C35715