





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD5 COUNTY DOUBLE CAB
Colour	Green
Year of manufacture	2000
Top speed	132 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	315 Nm at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg



CarCheck.co.uk page 1/21



Internet history

Entry 1

Date 2021-09-20

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/21



MOT history

MOT expiry date	2024-08-06
MOT pass rate	57 %
MOT passed	16
Failed MOT tests	12
Total advice items	105
Total items failed	30

MOT #28		2023-08-07 10:16
MOT test	number	802882285230
Result		✓ Passed
Next exp	ry date	2024-08-06
Advice	Oil leak, but not excessive transfer box (8.4.1 (a) (i))	
Advice	Offside Front swivel hub seal leaking	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))		
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front floor corroded	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/21



MOT #27 2023-08-01 16:15

MOT test number 742558640180

Result **X** Failed **MAJOR** Offside Headlamp aim too low (4.1.2 (a)) Advice Offside Front swivel hub seal leaking Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Front Registration plate missing (0.1 (a)) MAJOR Service brake is causing the vehicle to swerve to the offside (1.2.1 (b) (i)) MAJOR **MAJOR** Nearside Headlamp aim too high (4.1.2 (a)) Advice Offside Front floor corroded Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) Advice Oil leak, but not excessive transfer box (8.4.1 (a) (i)) **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Advice Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

CarCheck.co.uk page 4/21



MOT #26 2023-04-11 18:35

MOT test number 186569229390

Result X Failed

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))

MAJOR Headlamp aim projected beam image is obviously incorrect both lamps (4.1.2 (c))

MAJOR Exhaust gas recirculation valve missing where one was fitted as standard (8.2.2.1 (a))

Advice Offside Brake pipe clips or supports missing, pipe adequately supported front to rear on chassis (1.1.11 (d) (i))

MAJOR Offside Front Seat belt retracting mechanism defective (7.1.2 (e))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MAJOR Side repeater missing not fitted both sides (4.4.1 (a) (ii))

Advice Offside Front steering knuckle seal has slight leak

Advice Drag link end ball joint has slight play both ends (2.1.3 (b) (i))

MAJOR Exhaust catalytic converter missing where one was fitted as standard (8.2.2.1 (a))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced middle both sides & cross member (6.1.1 (c) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources one of two bulbs not operating (4.7.1 (b) (i))

MAJOR Nearside Front Seat belt retracting mechanism defective (7.1.2 (e))

MAJOR Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

MAJOR Rear Seat belt buckle missing all are hidden under the seat & not readily accessible to test (7.1.2 (d))

DANGEROUS Nearside Front Electrical wiring likely to touch hot or rotating parts heavy cable loose next to the exhaust (4.11 (a) (iii))

Advice Oil leak, but not excessive gear box (8.4.1 (a) (i))

MAJOR Front Registration plate missing (0.1 (a))

Advice Handbrake lever travel would benefit from adjustment

CarCheck.co.uk page 5/21



MOT #25 2022-02-04 11:43

MOT test number 327149440365

MOT #24 2021-01-25 17:05

MOT test number 644425733028

Result

Passed

MOT #23 2020-01-17 14:49

MOT test number 519875256406

Result
✓ Passed

MOT #22 2020-01-09 10:12

MOT test number 724951266835

Result × Failed

MAJOR Front Windscreen washer not working (3.5 (a))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Chassis/out rigger (5.3.6 (a) (i))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Chassis (5.3.6 (a) (i))

MAJOR Front Registration plate inscription illegible (0.1 (b))

MAJOR Front Windscreen wiper not working (3.4 (a))

MAJOR Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded

significantly reducing structural strength Chassis (5.3.6 (a) (i))

CarCheck.co.uk page 6/21



MOT #21 2018-05-03 13:04 802470935299 **MOT** test number Result ✓ Passed **Advice** Front brake pads worn Advice Front tie bar bushes worn Advice Drop arm worn Advice Corrosion rear chassis **Advice** Slight corrosion around offside rear seat belt anchor

 MOT #20
 2017-04-26 10:29

 MOT test number
 120153939320

 Result
 ✓ Passed

MOT #19

MOT test number

Result

Advice Corrosion rear chassis

Advice Both front and nearside rear tyres cracking

MOT test number

Result

Advice Corrosion rear chassis

Fail Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)

Advice Both front and nearside rear tyres cracking

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 7/21



MOT #17 2015-01-07 12:25

MOT test number 699547605025

Result × Failed

Fail Offside Front Brake pipe inadequately clipped (3.6.B.1)

Notice Prop shaft flange bolt loose and cut

Fail Offside Rear Upper Shock absorber has an excessively worn shock absorber pivot (2.7.4)

Notice Wiper arms worn

Fail Intermediate drop arm insecure (2.2.B.1a)

Notice Offside rear door inner corrosion and cracked

Fail Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Notice Offside front axle end ball seal leaking

MOT #16 2014-01-16 14:53

MOT test number 186946814056

Result

Passed

Notice All tyres cracking in tread

Advice Track rod end ball joint has slight play (2.2.B.1f)

Notice Oil leak

CarCheck.co.uk page 8/21



MOT #15 2013-12-17 17:50 **MOT** test number 487221053309 Result × Failed Fail Steering box has a significant oil leak (2.2.D.2e) Notice Oil leak Fail Brake pipe excessively corroded (3.6.B.2c) Notice Offside rear brake pads low **Advice** Track rod end ball joint has slight play (2.2.B.1f) Fail Ball joint has excessive play (2.2.B.1f) **Notice** All tyre sidewalls cracking and in the treads Fail Nearside Rear Lower Shock absorber insecure (2.7.2b)

MOT test number

785975132377

Result

Notice

Nearside front tyre has slight wear on inner edge

Advice

Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Notice

Offside front tyre has slight wear on inner edge

Advice

Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

CarCheck.co.uk page 9/21



MOT #13 2012-11-30 15:01 **MOT** test number 499985032324 Result **X** Failed Pass with rectification Offside Front Steering locking device missing (2.2.C.1g) **Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4) Notice Offside front tyre has slight wear on inner edge Pass with rectification Nearside Front Steering locking device missing (2.2.C.1g) **Advice** Offside Drag link end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c) Notice Nearside front tyre has slight wear on inner edge

MOT test number

185889831328

Result

Notice Corrosion on all brake pipes and dirty

Advice Drag link end ball joint has slight play (2.2.B.1f)

Notice Nearside and offside swivel housing's leaking slightly

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11		2010-12-17 09:01
MOT test	number	383431050315
Result		✓ Passed
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Brake pipe slightly corroded (3.6.B.2c)	
Notice	Bulb out nuber plate lamp	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 10/21



MOT #10 2010-12-13 11:14

MOT test number 181337340303

Result X Failed

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Nearside Rear Lower Shock absorber insecure (2.7.2b)

Fail Ball joint has excessive play (2.2.B.1f)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Centre Brake pipe slightly corroded (3.6.B.2c)

Notice Bulb out nuber plate lamp

Fail Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Fail Nearside Axle swivel joint has excessive play (2.5.A.3b)

MOT #9 2009-12-08 16:08

MOT test number 871092549375

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 11/21



MOT #8 2009-12-07 13:35

MOT test number 922411449303

Result X Failed

Fail Nearside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)

Fail Offside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Offside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2008-12-19 14:30

MOT test number 574314858337

Result ✓ Passed

Advice Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Notice Front hubs damp

Advice Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 12/21



MOT #6 2008-12-09 11:56
MOT test number 751464248355

Result X Failed

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Fail Nearside Front Axle swivel joint has excessive play (2.5.A.3b)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Horn not working (1.6.2a)

Advice Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Seat belt has a cut which has significantly weakened the webbing (5.2.2a)

Fail Nearside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Notice Front hubs damp

MOT #5 2007-12-12 10:31

MOT test number 393346547363

Result

✓ Passed

MOT #4 2007-12-11 14:09

MOT test number 892315347376

Result X Failed

Fail Nearside Drag link end ball joint has excessive play (2.2.B.1f)

CarCheck.co.uk page 13/21



MOT test number

Result

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

580519935391

Result

✓ Passed

MOT #1 2005-12-05 09:22

MOT test number 173119435332

Result X Failed

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 14/21



Tax & MOT check



Tax status Expired at 1 September

Days left 241 days too late

MOT expiry date 6 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 15/21



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 16/21



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 17/21



Owner history

e when mistery	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 18/21



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 19/21



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2000-10-31
Last registration	2023-08-07
Complete history	See info



Registration #1	2000-10-31	17 mi
Registration #2	2005-12-05	48.556 mi
Registration #3	2005-12-05	48.556 mi
Registration #4	2006-12-09	61.021 mi
Registration #5	2007-12-11	70.333 mi
Registration #6	2007-12-12	70.338 mi
Registration #7	2008-12-09	79.715 mi
Registration #8	2008-12-19	80.024 mi
Registration #9	2009-12-07	87.604 mi
Registration #10	2009-12-08	87.621 mi
Registration #11	2010-12-13	94.377 mi
Registration #12	2010-12-17	94.393 mi
Registration #13	2011-12-05	100.014 mi
Registration #14	2012-11-30	102.925 mi
Registration #15	2013-12-17	107.167 mi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		71.777 66
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		0.00 44
CarCheck.co.uk		page 20/21

Registration #27	11.00 40
Registration #28	71,777 66
Registration #29	11.777 es

More info >



		_	
- Duma	ancior	וכ ג.	Woldht
	-113101	אט כו	weight

Width	1790 mm
Height	2181 mm
Length	4625 mm
Wheel base	2794 mm
Kerb weight	2000 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of axles	2
Engine number	10P99209A

CarCheck.co.uk page 21/21