





General information

| Make | MAZDA |
|---------------------|-----------------|
| Model | RX-8 RX-8 192PS |
| Colour | Grey |
| Year of manufacture | 2007 |
| Top speed | 139 mph |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 189 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 5.000 rpm |
| Engine capacity | 2.616 cc |
| Cylinders | 2 |
| Fuel type | Petrol |
| Consumption city | 18.7 mpg |
| Consumption extra urban | 34.0 mpg |
| Consumption combined | 26.2 mpg |
| CO2 emission | 267 g/km |
| CO2 label | М |





MOT history

| MOT expiry date | 2021-09-23 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 16 |
| Total items failed | 12 |

| MOT #15 | 2020-09-23 12:49 |
|---|--------------------------|
| MOT test number | 482382486016 |
| Result | ✓ Passed |
| Next expiry date | 2021-09-23 |
| Advice (i)) Front Upper Suspension arm pin or bush worn but not resulting in exces | sive movement (5.3.4 (a) |

| MOT #14 | 2020-09-23 09:13 | |
|---|-------------------------|--|
| MOT test number | 290800415544 | |
| Result | 🗙 Failed | |
| Advice Front Upper Suspension arm pin or bush worn but not resulting in excess (i)) | ive movement (5.3.4 (a) | |
| Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) | | |

| MOT #13 | 2019-09-23 11:24 |
|-----------------|------------------|
| MOT test number | 918572082316 |
| Result | ✓ Passed |
| | |
| MOT #12 | 2018-09-22 09:35 |
| MOT test number | 942738003275 |
| Result | ✓ Passed |

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))





| MOT #11 | 2018-09-22 09:35 | |
|---|---|--|
| MOT test number | 774222610364 | |
| Result | × Failed | |
| Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) | | |
| Pass with rectification | Offside Front Headlamp aim too high (4.1.2 (a)) | |

| MOT #10 | 2017-09-23 12:59 |
|-----------------|------------------|
| MOT test number | 364731818391 |
| Result | ✓ Passed |

| MOT #9 | | 2016-09-24 13:58 |
|----------|---|------------------|
| MOT test | number | 648601620036 |
| Result | | ✓ Passed |
| Advice | Parking brake lever has little reserve travel (3.1.6b) | |
| Advice | Rear Tyre worn close to the legal limit both (4.1.E.1) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Shock absorber has a light misting of oil (2.7.3) | |

| MOT #8 | 2015-08-15 13:28 |
|-----------------|------------------|
| MOT test number | 117679746220 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2014-08-27 14:13 |
| MOT test number | 125519734227 |

Result

✓ Passed





| MOT # | 6 | 2013-07-05 13:06 |
|---|--|-----------------------|
| MOT te | est number | 526816483117 |
| Result | | ✓ Passed |
| Advid | Nearside Rear Road wheel slightly damaged (4.2.A.1a) | |
| MOT # | 5 | 2013-07-03 15:01 |
| MOT te | est number | 977034683171 |
| Result | | 🗙 Failed |
| Fail | Nearside Front Road wheel cracked (4.2.A.1a) | |
| Fail | Offside Front Lower Anti-roll bar has excessive play in a ball joint (2.4.G.2) | |
| FailNearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) | | |
| Pass | with rectification Nearside Windscreen wiper does not clear the windscree | n effectively (8.2.2) |
| Fail Nearside Front Lower Anti-roll bar has excessive play in a ball joint (2.4.G.2) | | |
| Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) | | |
| Fail | Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) | |

| MOT #4 | | 2012-07-04 07:32 |
|----------|--|------------------|
| MOT test | number | 607176682166 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Brake pad(s) wearing thin (3.5.1g) | |





| MOT #3 | 2012-06-29 16:07 |
|---|--|
| MOT test number | 827781182187 |
| Result | × Failed |
| Advice Rear Brake pad(s) wearing thi | n (3.5.1g) |
| Fail Nearside Front Tyre tread depth I | below requirements of 1.6mm (4.1.E.1) |
| Notice Items removed from driver's view prior to test | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Brake pad(s) wearing thin (3.5.1g) | |
| Pass with rectification Front Winds | creen washer provides insufficient washer liquid (8.2.3) |
| Pass with rectification Front registr | ration plate missing (6.3.1a) |

| MOT #2 | 2011-03-01 09:49 |
|-----------------|------------------|
| MOT test number | 707160461024 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2010-03-11 12:32 |
| MOT test number | 100700170444 |
| Result | ✓ Passed |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | ASMPL |
| Date | |
| Category | AMPL |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2007-03-29 |
| Last registration | 2020-09-23 |
| Complete history | See info |



| Registration #1 | 2007-03-29 | 15 mi |
|------------------|------------|------------|
| Registration #2 | 2010-03-11 | 9.227 mi |
| Registration #3 | 2011-03-01 | 10.868 mi |
| Registration #4 | 2012-06-29 | 25.106 mi |
| Registration #5 | 2012-07-04 | 25.118 mi |
| Registration #6 | 2013-07-03 | 30.818 mi |
| Registration #7 | 2013-07-05 | 30.852 mi |
| Registration #8 | 2014-08-27 | 40.783 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 est |

More info \rightarrow



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1340 mm |
| Length | 4425 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1345 kg |
| Max. allowed weight | 1820 kg |

Additional information

| Fuel tank capacity | 61 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 13B 520932 |