





## General information

Make	PEUGEOT
Model	1007 DOLCE
Colour	Silver
Year of manufacture	-
Top speed	103 mph
Gearbox	5 speed Semi-Automatic

# Engine & fuel consumption

Power	75 BHP	0 < 101 A	LAB
Max. torque	118 Nm at 3.300 rpm	101 - 120 <sup>B</sup> <sub>C</sub>	
Cylinders	4	121 - 140 E	
Fuel type	Petrol	141 - 165 F G	
Consumption city	35.8 mpg	166 - 185 H	
Consumption extra urban	54.3 mpg	186 - 225	
Consumption combined	45.6 mpg	225+	L



## MOT history

MOT #19	2022-02-12 14:43
MOT test number	832642834970
Result	✓ Passed
Next expiry date	2023-02-24
Advice Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #18	2021-02-25 17:28
MOT test number	692988601676
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Outer Suspension component mounting prescribed area is corroded but no n/s and o/s sills (5.3.6 (a) (i))	ot considered excessive
<b>Advice</b> Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Brake hose has slight corrosion to ferrule front and rear (1.1.12 (f) (i))	
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
<b>Advice</b> Suspension component mounting prescribed area is corroded but not consand rear o/s and n/s (5.3.6 (a) (i))	sidered excessive front
Advice Rear Exhaust mounting defective backbox, also outer skin corroded (6.1.2	2 (a))
<b>Advice</b> Front Lower Vehicle structure is corroded but structural rigidity is not sign subframe (6.1.1 (c) (i))	ificantly reduced



SM55MWZ report date: 2024-03-28

MOT #17	2021-02-23 12:19
MOT test	number 945871745008
Result	× Failed
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice and rear o	Suspension component mounting prescribed area is corroded but not considered excessive front /s and n/s (5.3.6 (a) (i))
MAJOR	Front Anti-roll bar linkage ball joint excessively worn n/s and o/s (5.3.4 (a) (i))
DANGER	<b>Front Tyre has ply or cords exposed n/s and o/s (5.2.3 (d) (ii))</b>
Advice	Rear Exhaust mounting defective backbox, also outer skin corroded (6.1.2 (a))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice subframe	Front Lower Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Horn not working (7.7 (a) (ii))
Advice	Outer Suspension component mounting prescribed area is corroded but not considered excessive s sills (5.3.6 (a) (i))
MAJOR	Front Track rod end ball joint has excessive play n/s and o/s (2.1.3 (b) (i))
Advice	Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Brake hose has slight corrosion to ferrule front and rear $(1.1.12 (f) (i))$



<b>OT #16</b> 2021-02-0	1 12:12
OT test number 899382	657159
esult >	<b>&lt;</b> Failed
<b>DANGEROUS</b> Nearside Front Track rod end ball joint worn to the extent there is a serious risk of etachment (2.1.3 (b) (ii))	
Advice Offside Front Suspension component mounting prescribed area is corroded but not considerative Chassis area (5.3.6 (a) (i))	ed
Advice Both rear shocks are corroded but not excessively	
MAJOR Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))	
<b>DANGEROUS</b> Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considerexcessive (5.3.6 (a) (i))	ed
Advice Middle exhaust box is corroded on outer skin .	
Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Nearside & offside front inner wings are corroded but full inspection is not possible due to pl nderwing covers fitted .	astic
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Integral body structure is corroded but structural rigidity is not significantly reduced Bulkhea ffside front (6.1.1 (c) (i))	ad on
<b>DANGEROUS</b> Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))	
Advice Nearside Front Suspension component mounting prescribed area is corroded but not conside xcessive Chassis area (5.3.6 (a) (i))	ered
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
MAJOR Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))	
<b>DANGEROUS</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Rear Suspension component mounting prescribed area is corroded but not conside xcessive (5.3.6 (a) (i))	red
Advice Rear exhaust box corroded & support bracket broken but still supported by other bracket.	
MAJOR Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i)) Check.co.uk	bage 4/13

Advice	Tyre slightly damaged/cracking or perishing Both rear tyres (5.2.3 (d) (ii))
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Slight oil leak on engine
MAJOR pipe (1.1.1	Offside Front Brake pipe excessively corroded On connection point to brake hose , nut on rigid L1 (c))
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice Nearside &	Suspension component mounting prescribed area is corroded but not considered excessive $\hat{k}$ offside rear outer sill area's (5.3.6 (a) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Direction indicator slightly discoloured Both sides on front (4.4.3 (a))





MOT #15	2019-07-25 09:40
MOT test number	743537491788
Result	✓ Passed
Result	V rasseu
MOT #14	2018-06-19 15:49
MOT test number	889703065639
Result	✓ Passed
MOT #13	2017-06-21 09:34
MOT test number	157632640262
Result	✓ Passed
MOT #12	2016-07-18 08:30
MOT test number	397433294596
Result	✓ Passed
MOT #11	2015-07-17 11:03
MOT test number	707908695153
Result	Passed
MOT #10	2015-07-17 09:49
MOT test number	769068395144
Result	× Failed
Fail Offside Stop lamp not working (1.2.1b)	
MOT #9	2014-07-30 16:59
MOT test number	827271014277

Result

🗸 Passed



SM55MWZ
report date: 2024-03-28

MOT #8	2014-07-30 13:00
MOT test number	365801414213
Result	🗙 Failed
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excess	ive movement (2.4.G.2)
<b>Fail</b> Nearside Rear Tyre has a cut in excess of the requirements deep enough to (4.1.D.1a)	reach the ply or cords
Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive	e movement (2.4.G.2)

MOT #7	2013-08-06 15:56
MOT test number	537508513241
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Both rear tyres perished	

МОТ #6	2013-08-06 12:09
MOT test number	189828813235
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Front wipers smearing	
Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Notice Both rear tyres perished	

MOT #5	2012-08-06 12:59
MOT test number	415109912220
Result	✓ Passed
<ul><li>Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</li><li>Advice Offside Track rod end ball joint has slight play (2.2.B.1f)</li></ul>	
Advice Offside Track fod end ball joint has slight play (2.2.B.11)	





MOT #4	2011-08-24 10:30
MOT test number	265306231286
Result	✓ Passed
MOT #3	2010-08-21 13:38
MOT test number	202093130264
Result	✓ Passed
Advice Nearside Front coil spring worn (2.4.C.1b)	
MOT #2	2009-09-18 11:44
MOT test number	823591469265
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2008-09-25 13:56
MOT test number	474459468216
Result	✓ Passed





### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	
**********	
********	
NUMBER OF TAXABLE PARTY	
**********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 



SM55MWZ
report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-30
Last registration	2022-02-12
Complete history	See info



Registration #1	2005-09-30	15 mi
Registration #2	2008-09-25	13.802 mi
Registration #3	2009-09-18	15.358 mi
Registration #4	2010-08-21	16.959 mi
Registration #5	2011-08-24	18.264 mi
Registration #6	2012-08-06	19.561 mi
Registration #7	2013-08-06	20.544 mi
Registration #8	2013-08-06	20.544 mi
Registration #9	2014-07-30	21.500 mi
Registration #10	2014-07-30	21.500 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.227 mi
D		
Registration #20		11.117 mil

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1662 mm
Height	1610 mm
Length	3731 mm
Wheel base	2315 mm
Kerb weight	1140 kg
Max. allowed weight	1559 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	FSV25156725