



report date: 2024-03-29

General information

Make	MAZDA
Model	6 TS
Colour	Grey
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	184 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	168 g/km
CO2 label	H





## MOT history

MOT expiry date	2021-08-24
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	35
Total items failed	18

MOT #16 2020-08-18 15:48

MOT test number 344089911441

Result ✓ Passed

Next expiry date 2021-08-24

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm tread & light perishing (5.2.3 (e))
- Advice** Several suspension components, rear sub frame & exhaust system rusty
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread & light perishing (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases both rear back box joints (6.1.2 (a))

MOT #15 2020-08-18 10:08

MOT test number 324549241309

Result ✗ Failed

- Advice** Several suspension components, rear sub frame & exhaust system rusty
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm tread & light perishing (5.2.3 (e))
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Exhaust has a minor leak of exhaust gases both rear back box joints (6.1.2 (a))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread & light perishing (5.2.3 (e))
- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

**MOT #14**

2019-08-15 08:11

**MOT test number**

366783954243

**Result**

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front and rear suspension components rusty
- Advice** Headlamp has a product on the lens but not seriously reducing light output nearside and offside (4.1.4 (b))

**MOT #13**

2019-08-15 08:11

**MOT test number**

345478772409

**Result**

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output nearside and offside (4.1.4 (b))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front and rear suspension components rusty

**MOT #12**

2018-08-07 15:30

**MOT test number**

193004969568

**Result**

✓ Passed

- Advice** Headlamp has a product on the lens but not seriously reducing light output both front (4.1.4 (b))
- Advice** Several front & rear suspension bushes perishing
- Advice** Exhaust has a minor leak of exhaust gases both rear back box joints (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Suspension arm corroded but not seriously weakened both front (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Suspension component pin or bush slightly worn rear trailing armbushes (5.3.4 (a) (i))

**MOT #11**

2018-08-07 11:59

**MOT test number**

661324021702

**Result**

✗ Failed

- Fail** Nearside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))
- Advice** Exhaust has a minor leak of exhaust gases both rear back box joints (6.1.2 (a))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Advice** Suspension arm corroded but not seriously weakened both front (5.3.3 (b) (i))
- Advice** Suspension component pin or bush slightly worn rear trailing armbushes (5.3.4 (a) (i))
- Advice** Several front & rear suspension bushes perishing
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output both front (4.1.4 (b))

**MOT #10** 2017-08-25 10:07**MOT test number** 217132847690**Result** ✓ Passed**MOT #9** 2017-08-25 10:07**MOT test number** 632603764346**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2017-01-10 12:32**MOT test number** 148005255754**Result** ✓ Passed**MOT #7** 2017-01-05 10:59**MOT test number** 450405037624**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #6** 2015-12-29 13:09**MOT test number** 852035191475**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-01-13 09:30**MOT test number** 217263315037**Result** ✓ Passed**MOT #4** 2015-01-08 13:19**MOT test number** 598828305022**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside rear brake binding (3.7.B.1)**MOT #3** 2014-01-04 09:15**MOT test number** 649184004073**Result** ✓ Passed**MOT #2** 2013-01-05 09:15**MOT test number** 169595703061**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #1** 2012-01-05 15:23**MOT test number** 229195802006**Result** ✓ Passed**Notice** Traction light stays on the dash seems faulty**Notice** Dsc warning flashing on dash seems faulty



Tax & MOT check

×

Untaxed

Tax expired:  
14 November 2020

×

MOT

Expired:  
24 August 2021

Tax status

Expired at 14 November 2020

Days left

1262 days too late

MOT expiry date

24 August 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YC58UNU
Plate since	2019-03-29
Current registration	YC58UNU
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-09
Last registration	2020-08-18
Complete history	<a href="#">See info</a>



Registration #1	2009-01-09	22 mi
Registration #2	2012-01-05	19.549 mi
Registration #3	2013-01-05	30.735 mi
Registration #4	2014-01-04	42.595 mi
Registration #5	2015-01-08	55.251 mi
Registration #6	2015-01-13	55.385 mi
Registration #7	2015-12-29	65.452 mi
Registration #8	2017-01-05	75.788 mi
Registration #9	2017-01-10	75.887 mi
Registration #10	2019-01-01	75.887 mi
Registration #11	2019-01-01	75.887 mi
Registration #12	2019-01-01	75.887 mi
Registration #13	2019-01-01	75.887 mi
Registration #14	2019-01-01	75.887 mi
Registration #15	2019-01-01	75.887 mi
Registration #16	2019-01-01	75.887 mi
Registration #17	2019-01-01	75.887 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10466189