



W929VLP

report date: 2024-03-29

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Blue
Year of manufacture	2000
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.996 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-03-29
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	119
Total items failed	27

MOT #232022-03-30 12:40

MOT test number981069944671

Result✓ Passed

Next expiry date2023-03-29

- AdviceOffside Front Wheel bearing has slight play (5.1.3 (a) (i))
- AdviceCorrosion in brake pipes and pipe ferrules [multiple]
- AdviceSome movement /wear in drivers seat
- AdviceSome wear/play in steering rack
- AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceO/s mirror deteriorated
- AdviceCorrosion in inner sills/ rear subframe/rear chassis



MOT #22

2021-03-02 15:01

MOT test number

745461588059

Result		✓ Passed
Advice	Offside rear inner diff bearing has slight play	
Advice	Nearside Rear Suspension component mounting repair covered in underseal chassis rail (5.3.6 (a) (i))	
Advice	Offside floor slightly corroded	
Advice	Nearside rear inner diff bearing has slight play	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside floor slightly corroded	
Advice	Offside Rear Suspension component mounting repair covered in underseal chassis rail (5.3.6 (a) (i))	
Advice	Exhaust catalytic converter bracket deteriorated but system not insecure	
Advice	Coolant leak	

**MOT #21**

2021-02-12 09:05

MOT test number

839195536544

Result**✗ Failed**

- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))
- Advice** Nearside exhaust bracket deteriorated but system not insecure
- Fail** Nearside Front Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside rear inner diff bearing has slight pay
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))
- Advice** Nearside rear inner diff bearing has slight pay
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #20

2020-03-04 12:16

MOT test number

140368716697

Result**✓ Passed**



MOT #19	2019-11-26 10:45
MOT test number	444766162079
Result	✗ Failed

- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Exhaust cats corroded
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Nearside Non obligatory mirror damaged
- Advice** Nearside Rear Lower Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Fail** Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Fail** Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Engine trims fitted
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Non obligatory mirror damaged
- Advice** Offside Rear Lower Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Fail** Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Under trays fitted



MOT #18

2018-11-23 15:25

MOT test number

623944535184

Result

✓ Passed

- Advice

Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2018-11-02 09:32

MOT test number

386377564205

Result**✗ Failed**

- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced front to rear (6.1.1 (c) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16

2017-11-29 12:00

MOT test number

905802995636

Result**✓ Passed**

- Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Both door mirrors damaged
- Advice** Brake pipes corroded
- Advice** N/s/r and o/s/r chassis heavily corroded by the rear sub frame mounts
- Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Movement in the rear driveshafts
- Advice** Inner and outer sills and areas of the underside corroded

**MOT #15**

2016-12-08 12:13

MOT test number

225073962718

Result

✓ Passed

- Advice** Both door mirrors damaged
- Advice** Nearside Front Brake pipe slightly corroded Across front x member (3.6.B.2c)
- Advice** Movement in rear suspension u/js
- Advice** Rear outer and inner sills and areas of the underside corroded

MOT #14

2016-12-07 10:25

MOT test number

930104922710

Result

✗ Failed

- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Missfire at idle
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Advice** Movement in rear suspension u/js
- Advice** Rear outer and inner sills and areas of the underside corroded
- Advice** Nearside Front Brake pipe slightly corroded Across front x member (3.6.B.2c)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Both door mirrors damaged

**MOT #13**

2015-12-17 11:23

MOT test number

976795068645

Result

✓ Passed

- Advice** Front fog lamp tell tale in-op
- Advice** Front brake pipes across front axle corroded
- Advice** Both front floors and o/s/r outer sill weak due to corrosion
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Passenger door mirror glass damaged
- Advice** Drivers side door mirror glass deteriorated
- Advice** Areas of the underside corroded
- Advice** Movement in rear driveshaft u/js.

MOT #12

2014-12-09 11:11

MOT test number

705553644364

Result

✓ Passed

- Notice** Areas of corrosion on the underside
- Notice** Movement in both rear deiveshaft u/js
- Notice** Front fog lamp tell tale in-op
- Notice** Brake pipes across front crossmember rusty
- Notice** N/s door mirror glass broken

**MOT #11**

2013-12-03 12:36

MOT test number

323614714270

Result

✓ Passed

- Notice** N/s/r park brake slow on take-up
- Notice** Areas of corrosion on the underside
- Notice** Brake pipes across front cross member rusty.
- Notice** Front fog lamp tell tale in-op
- Notice** Movement in rear driveshaft u/js
- Notice** Movement in the front anti roll bar
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #10

2012-12-11 10:16

MOT test number

266446242387

Result

✓ Passed

- Notice** Front fog lamp tell tale in-op.
- Notice** Both front floors, n/s/r and o/s/r chassis by suspension mounts weak.
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Some movement in both rear driveshaft u/js and output shafts.
- Notice** N/s/r parking brake slow on take-up.
- Notice** Air bag light on
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brake hose ferules rusty.

**MOT #9** 2011-12-14 11:45**MOT test number** 196218241303**Result** ✓ Passed**Notice** Air bag light on**MOT #8** 2010-12-10 12:31**MOT test number** 401534040449**Result** ✓ Passed**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2010-12-09 11:26**MOT test number** 513243840370**Result** ✗ Failed**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2009-12-15 16:30**MOT test number** 133039649369**Result** ✓ Passed**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2008-11-25 11:56**MOT test number** 350180938353**Result** ✓ Passed**Notice** Nearside and offside front floor areas showing signs of corrosion but not holed at time of test**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-11-25 11:56**MOT test number** 431230038338**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nearside and offside front floor areas showing signs of corrosion but not holed at time of test**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-11-29 11:27**MOT test number** 960223037314**Result** ✓ Passed**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #2** 2006-12-14 12:46**MOT test number** 324428246377**Result** ✓ Passed



MOT #1	2005-12-10 14:36
MOT test number	462934345390
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	W929VLP
Plate since	2019-03-29
Current registration	W929VLP
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2000-05-31
Last registration	2022-03-30
Complete history	See info



Registration #1	2000-05-31	19 mi
Registration #2	2006-12-14	73.659 mi
Registration #3	2007-11-29	78.321 mi
Registration #4	2008-11-25	80.268 mi
Registration #5	2009-12-15	82.320 mi
Registration #6	2010-12-09	85.516 mi
Registration #7	2010-12-10	85.520 mi
Registration #8	2010-12-10	85.520 mi
Registration #9	2010-12-10	85.520 mi
Registration #10	2010-12-10	85.520 mi
Registration #11	2010-12-10	85.520 mi
Registration #12	2010-12-10	85.520 mi
Registration #13	2010-12-10	85.520 mi
Registration #14	2010-12-10	85.520 mi

More info >



Dimensions & weight

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	NB0012020817