



report date: 2024-03-28

General information

Make	SUZUKI
Model	SPLASH GLS
Colour	Turquoise
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	29
Total items failed	12

MOT #17 2024-02-22 15:46

MOT test number 491442517683

Result ✓ Passed

Next expiry date 2025-02-23

**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both sides lower arms rear bushes (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))

MOT #16 2023-02-17 13:08

MOT test number 516228201894

Result ✓ Passed

MOT #15 2023-02-11 10:38

MOT test number 795346026925

Result ✗ Failed

**Fail** Offside Front Brake pipe excessively corroded brake pipe corroded going to flexy brake hose (1.1.11 (c))

**Fail** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**MOT #14** 2022-02-23 16:15**MOT test number** 564568044804**Result** ✓ Passed**MOT #13** 2021-02-24 13:57**MOT test number** 865727170508**Result** ✓ Passed**MOT #12** 2020-04-23 15:56**MOT test number** 749673560676**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material over axle covered (1.1.11 (c))**MOT #11** 2020-04-22 16:56**MOT test number** 140494835882**Result** ✗ Failed**Fail** Front Suspension arm pin or bush excessively worn both sides rear bushes debonding (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material corroding over axle (1.1.11 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm edge heavily worn (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn drop link (5.3.4 (a) (i))**MOT #10** 2019-05-10 12:15**MOT test number** 489466769825**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play drop link (5.3.4 (a) (i))

**MOT #9** 2018-05-14 16:12**MOT test number** 813513612486**Result** ✓ Passed**MOT #8** 2017-06-20 14:40**MOT test number** 208835886374**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear wishbone bush (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear wishbone bush (2.4.G.2)

**MOT #7** 2017-06-20 14:40**MOT test number** 820686895653**Result** ✗ Failed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear wishbone bush (2.4.G.2)

**Pass with rectification** Windscreen washer provides insufficient washer liquid Both front (8.2.3)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear wishbone bush (2.4.G.2)

**MOT #6** 2016-06-25 09:48**MOT test number** 419908529319**Result** ✓ Passed

**Advice** Body work damaged in places

**Advice** Brake pipes surface corroded adv to clean / grease

**Advice** Exhaust becoming corroded

**Advice** Both front lower arms rear bushes becoming unbonded / adv to replace

**MOT #5**

2016-06-24 15:00

**MOT test number**

368263418827

**Result****✗ Failed**

**Fail** Windscreen wiper does not clear the windscreen effectively both w/blades split / smearing 18" - 21" (8.2.2)

**Advice** Brake pipes surface corroded adv to clean / grease

**Advice** Exhaust becoming corroded

**Fail** Windscreen washer provides insufficient washer liquid washers inop (8.2.3)

**Advice** Both front lower arms rear bushes becoming unbonded / adv to replace

**Fail** Offside Front coil spring broken coil spring broken at bottom section (2.4.C.1a)

**Advice** Body work damaged in places

**MOT #4**

2015-04-10 09:24

**MOT test number**

268730105495

**Result****✓ Passed**

**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Notice** Slight damage to o/s/r bumper cover

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3**

2014-01-16 15:33

**MOT test number**

815066114086

**Result****✓ Passed**

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-01-16 09:49
MOT test number	128136514403
Result	✗ Failed
Fail	Offside Rear Body has a projection caused by damage (6.1.C.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front coil spring broken (2.4.C.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-01-24 17:12
MOT test number	618584723062
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>FE59HKG</b>
Plate since	2024-03-28
Current registration	<b>FE59HKG</b>
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-01
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2009-09-01	11 mi
Registration #2	2013-01-24	15.723 mi
Registration #3	2014-01-16	22.346 mi
Registration #4	2014-01-16	22.346 mi
Registration #5	2015-04-10	49.985 mi
Registration #6	2016-06-24	34.862 mi
Registration #7	2016-06-25	34.862 mi
Registration #8	2017-06-20	39.999 mi
Registration #9	2017-06-20	39.999 mi
Registration #10	2018-05-14	47.704 mi
Registration #11	2019-05-20	55.557 mi
Registration #12	2019-05-20	55.557 mi
Registration #13	2019-05-20	55.557 mi
Registration #14	2019-05-20	55.557 mi
Registration #15	2019-05-20	55.557 mi
Registration #16	2019-05-20	55.557 mi
Registration #17	2019-05-20	55.557 mi
Registration #18	2019-05-20	55.557 mi
Registration #19	2019-05-20	55.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1097438