



report date: 2024-03-29

General information

Make	SUZUKI
Model	JIMNY JLX PLUS
Colour	Grey
Year of manufacture	2006
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-06
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	37
Total items failed	11

MOT #20	2024-01-15 14:33
---------	------------------

MOT test number	907822092968
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-14
------------------	------------

- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #19**

2023-12-05 10:09

MOT test number

240074662007

Result**✗ Failed**

Fail Offside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting body mount to rear chassis/ crossmember excessively corroded (6.2.2 (d) (i))

Advice Nearside Front Upper Coil spring mounting corroded but not seriously weakened suspension bump stop mounting corroded (5.3.1 (b) (i))

Fail Nearside Front Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting chassis and floor excessively corroded at body mounting (6.2.2 (d) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis rail inner face corroded adjacent to suspension arm forward mounting (5.3.6 (a) (i))

Fail Offside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting chassis body mount bracket & floor & inner sill excessively corroded (6.2.2 (d) (i))

Fail Nearside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting body mount to rear chassis/crossmember excessively corroded (6.2.2 (d) (i))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis bracket excessively corroded within 30cms of suspension panhard rod/diagonal link mounting (5.3.6 (a) (i))

Advice Offside Front Upper Coil spring mounting corroded but not seriously weakened suspension bump stop mounting corroded (5.3.1 (b) (i))

Fail Offside Front Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting chassis & floor excessively corroded at body mounting (6.2.2 (d) (i))

Fail Nearside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting chassis body mount bracket & floor excessively corroded (6.2.2 (d) (i))

MOT #18

2022-12-05 12:21

MOT test number

876051382000

Result**✓ Passed**

Advice Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security body mounting area corroded within 30cms of attachment to front of chassis (6.2.2 (d) (i))

Minor Windscreen damaged but not adversely affecting driver's view damage to windscreen on offside (3.2 (a) (i))

MOT #17

2021-12-03 13:15

MOT test number

5782358632815

Result

✓ Passed

Advice Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security body mounting area corroded within 30cms of attachment to front of chassis (6.2.2 (d) (i))

Minor Windscreen damaged but not adversely affecting driver's view damage to windscreen on offside (3.2 (a) (i))

**MOT #16**

2021-12-03 13:15

MOT test number

868205838231

Result

✗ Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security body mounting area corroded within 30cms of attachment to front of chassis (6.2.2 (d) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view damage to windscreen on offside (3.2 (a) (i))**MOT #15**

2020-12-10 14:41

MOT test number

446396995588

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14**

2019-08-21 13:33

MOT test number

683350126927

Result

✓ Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13**

2018-08-22 09:28

MOT test number

733582010119

Result

✓ Passed

Advice LEAK FROM N/S/F ROSE BOWL OUTER DRIVESHAFT JOINT**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2017-08-01 10:36**MOT test number** 405533106667**Result** ✓ Passed**Advice** Rear silencer deteriorated.**Advice** O/s/f brake binding slightly.**Advice** Exhaust bracket broken/missing but exhaust still secure.**MOT #11** 2016-08-08 12:50**MOT test number** 791514659656**Result** ✓ Passed**Advice** Exhaust bracket broken but exhaust still secure.**MOT #10** 2015-08-05 14:41**MOT test number** 417531389014**Result** ✓ Passed**MOT #9** 2015-02-28 11:11**MOT test number** 517549155082**Result** ✓ Passed**Notice** Oil leak**Notice** Advisery; plastic sill covers**MOT #8** 2014-02-21 12:35**MOT test number** 938802854032**Result** ✓ Passed**Notice** Advisery; engine management lamp staying on**Notice** Oil leak**Notice** Advisery; plastic oversills fittedf

**MOT #7** 2013-02-28 15:33**MOT test number** 447419453029**Result** ✓ Passed**MOT #6** 2013-02-26 15:54**MOT test number** 716987953074**Result** ✗ Failed**Fail** Brake pipe excessively corroded (3.6.B.2c)**Notice** Front brake discs corroded on edges**MOT #5** 2012-03-29 14:53**MOT test number** 519469182089**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-29 11:59**MOT test number** 125619482475**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside front brake application uneven (3.7.B.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pipe slightly corroded (3.6.B.2c)



MOT #3	2011-04-20 11:34
MOT test number	966280911154
Result	✓ Passed
Advice	Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #2	2010-04-26 12:29
MOT test number	182416810193
Result	✓ Passed

MOT #1	2009-04-29 12:33
MOT test number	750959219120
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-26
Last registration	2024-01-15
Complete history	See info



Registration #1	2006-04-26	28 mi
Registration #2	2009-04-29	22.665 mi
Registration #3	2010-04-26	28.215 mi
Registration #4	2011-04-20	34.064 mi
Registration #5	2012-03-29	39.365 mi
Registration #6	2012-03-29	39.365 mi
Registration #7	2013-02-26	43.507 mi
Registration #8	2013-02-28	43.507 mi
Registration #9	2014-02-21	49.168 mi
Registration #10	2015-02-28	54.773 mi
Registration #11	2015-08-05	56.090 mi
Registration #12	2016-01-29	56.277 mi
Registration #13	2016-05-29	56.277 mi
Registration #14	2016-09-29	56.277 mi
Registration #15	2016-12-29	56.277 mi
Registration #16	2017-03-29	56.277 mi
Registration #17	2017-06-29	56.277 mi
Registration #18	2017-09-29	56.277 mi
Registration #19	2017-12-29	56.277 mi
Registration #20	2018-03-29	56.277 mi
Registration #21	2018-06-29	56.277 mi
Registration #22	2018-09-29	56.277 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	M13A-1809534