





General information

Make	ΤΟΥΟΤΑ
Model	AVENSIS D-4D T4
Colour	Grey
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	310 Nm at 3.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg





Internet history

Entry 4	
Date	2021-06-19
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 3	
Date	2021-06-09
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-06-04
Pictures	5
Listing price	View report



source: autotrader.co.uk

Pictures

Listing price

5

View report



source: autotrader.co.uk



MOT history

МОТ #20	2021-09-15 10:52
MOT test number	704209993472
Result	✓ Passed
Next expiry date	2022-09-14
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Side repeater lens defective which has no effect on emitted light offside &	a nearside (4.4.1 (b) (i))

MOT #19	2021-09-15 10:52
MOT test number	964938104848
Result	× Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor Side repeater len	s defective which has no effect on emitted light offside & nearside (4.4.1 (b) (i))
Advice Oil leak, but not	excessive (8.4.1 (a) (i))
Advice Brake disc worn	, pitted or scored, but not seriously weakened front $\&$ rear (1.1.14 (a) (ii))
Pass with rectification	Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))
Advice Offside Front Sh	ock absorbers has light misting of oil (5.3.2 (b))

MOT #18	2020-09-05 14:	26
MOT test	number 9567942567	99
Result	✓ Pass	ed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	





MOT #17	2019-09-09 13:38
MOT test number	934738224398
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge (both) - both front tyres close to limit (5.2.3 (e))	, inner wall worn, really
MOT #16	2018-08-25 10:54
MOT test number	571046547391
Result	✓ Passed
MOT #15	2017-09-04 09:39
MOT test number	424506090822
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #14	2016-09-05 13:46
MOT test number	986728260468
Result	✓ Passed

MOT #13	2015-09-02 13:06
MOT test number	272003769615
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #12	2014-09-02 14:31
MOT test number	417425244230
Result	✓ Passed
	ictuating, but not excessively (3.7.B.3)
Advice Offside Front coil s	pring corroded (2.4.C.1b)



MOT #11	2014-09-02 13:05
MOT test number	255105244242
Result	🗙 Failed
Advice Front front brake fluctuating, but not excessively (3.7.B.3)	
Fail Offside Brake pipe excessively corroded (3.6.B.2c)	
Advice Offside Front coil spring corroded (2.4.C.1b)	

MOT #102013-09-10 15:00MOT test number866173353275Result✔ PassedNoticeNail in nearside rear tyreAdviceNearside Outer Front Tyre worn close to the legal limit (4.1.E.1)NoticeEngine covers fitted obscuring some components in the engine bayAdviceNearside Inner Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2013-06-04 17:01
MOT test number	675995553187
Result	✓ Passed

МОТ #8		2013-06-04 17:01
MOT test number		606885053195
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #7	2012-06-19 10:27
MOT test number	399581172159
Result	✓ Passed

YS55DFP

report date: 2024-03-29





MOT #6	201	11-06-24 14:38
MOT test	number	797695671108
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Oil leak	
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3	3.1a)

MOT #5	2011-06-20 09:59	
MOT test number	928321471157	
Result	🗙 Failed	
Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structu	ure (4.1.D.1b)	
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)		
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)		
Notice Oil leak		
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
FailNearside Front Headlamp not working on dipped beam (1.7.5a)		
Fail Offside Rear Registration plate lamp not working (1.1.C.1d)		
Advice Front Windscreen has damage to an area less than a 10mm circle within zone '	A' (8.3.1a)	

MOT #4		2010-06-24 14:55
MOT test	number	230255270154
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Nail in offside rear tyre	
Notice	N/s/f and o/s/f discs wearing low	





MOT #3		2009-06-25 16:53
MOT test	number	344826579181
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

МОТ #2	2009-02-06 09:42
MOT test number	634697239061
Result	✓ Passed
Notice Front tyres worn below 3mm.	
Notice Brake pads worn.	

MOT #1	2008-12-03 10):39
MOT test	number 471488038	324
Result	✓ Pas	sed
Notice	N/s inner cv boot damp	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice adjustmer	Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Slight oil leak from gearbox	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lamp
Туре	
Damage 2	AMPL
Date	Nº I
Category	ANNY.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-12-28
Last registration	2021-09-15
Complete history	See info



Registration #1	2005-12-28	20 mi
Registration #2	2008-12-03	48.726 mi
Registration #3	2009-02-06	51.087 mi
Registration #4	2009-06-25	51.156 mi
Registration #5	2010-06-24	62.695 mi
Registration #6	2011-06-20	74.412 mi
Registration #7	2011-06-24	74.469 mi
Registration #8	2012-06-19	82.571 mi
Registration #9	2013-06-04	92.126 mi
Registration #10	2013-09-10	94.079 mi
Registration #11	2014-09-02	96.799 mi
Registration #12	2014-09-02	96.799 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		
Registration #15		
Registration #16		11.777 est
5		0.777 es
Registration #16		0.000 es
Registration #16 Registration #17		0.000 es
Registration #16 Registration #17 Registration #18		0.000 es
Registration #16 Registration #17 Registration #18 Registration #19		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1760 mm
Height	1480 mm
Length	4630 mm
Wheel base	2700 mm
Kerb weight	1455 kg
Max. allowed weight	1970 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	2AD5001917