



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-19
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date 2023-06-29**MOT pass rate** 55 %**MOT passed** 11**Failed MOT tests** 9**Total advice items** 35**Total items failed** 22**MOT #20** 2022-06-30 10:32**MOT test number** 542580796363**Result** Passed**Next expiry date** 2023-06-29**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2022-06-21 11:45**MOT test number** 909179658503**Result** Failed**Fail** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18** 2020-12-16 17:29**MOT test number** 121818887125**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Unable to check brake pads as wheel trims fitted**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2020-12-16 12:18**MOT test number** 188258857422**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Unable to check brake pads as wheel trims fitted**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-05-22 13:29**MOT test number** 152986529904**Result** ✓ Passed**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**MOT #15**

2019-05-18 10:06

MOT test number

681548537447

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Coolant leak**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**MOT #14**

2018-05-23 07:51

MOT test number

507275969640

Result**✓ Passed****MOT #13**

2017-06-08 14:39

MOT test number

951717968771

Result**✓ Passed****MOT #12**

2017-06-08 12:47

MOT test number

840885915891

Result**✗ Failed****Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** N/s front tyre is wearing on the inner shoulder**Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #11** 2016-06-14 11:01**MOT test number** 810000202504**Result** ✓ Passed**Advice** Clutch pedal rubber missing**Advice** Offside Front tyre wearing thin on very inner edge**MOT #10** 2016-06-13 09:09**MOT test number** 178428427320**Result** ✗ Failed**Advice** Coolant level very low**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Clutch pedal rubber missing**Advice** Offside Front tyre wearing thin on very inner edge**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Lower Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**MOT #9** 2015-06-30 17:23**MOT test number** 359691285189**Result** ✓ Passed**MOT #8** 2015-06-30 17:23**MOT test number** 206201085402**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #7** 2014-07-04 15:36**MOT test number** 727435784140**Result** ✓ Passed**MOT #6** 2014-07-02 09:52**MOT test number** 228393784161**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-06-17 17:06**MOT test number** 168888363100**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2013-06-17 13:10**MOT test number** 956388463116**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Gearbox mounting defective**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** (unable to see front and rear pads)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2012-07-05 11:12**MOT test number** 556287382134**Result** ✓ Passed**MOT #2** 2012-07-05 08:31**MOT test number** 768577482154**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Rear position lamp(s) excessively damaged so that it is not visible from a reasonable distance (1.1.A.3d)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #1** 2011-06-21 16:01**MOT test number** 267382571456**Result** ✓ Passed




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-28
Previous owner since	2019-09-28
Number of owners	1
Current owner since	2019-09-28
Previous owner since	2019-09-28

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 HN08YJU
Plate since	2019-09-28
Current registration	 HN08YJU
Plate since	2019-09-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-14
Last registration	2022-06-30
Complete history	See info



Registration #1	2008-07-14	9 mi
Registration #2	2011-06-21	51.138 mi
Registration #3	2012-07-05	66.098 mi
Registration #4	2012-07-05	66.078 mi
Registration #5	2013-06-17	78.895 mi
Registration #6	2013-06-17	78.895 mi
Registration #7	2014-07-02	32.126 mi
Registration #8	2014-07-04	92.126 mi
Registration #9	2015-06-30	102.634 mi
Registration #10	2016-06-13	109.807 mi
Registration #11	2016-06-14	109.087 mi
Registration #12	2016-06-14	109.087 mi
Registration #13	2016-06-14	109.087 mi
Registration #14	2016-06-14	109.087 mi
Registration #15	2016-06-14	109.087 mi
Registration #16	2016-06-14	109.087 mi
Registration #17	2016-06-14	109.087 mi
Registration #18	2016-06-14	109.087 mi
Registration #19	2016-06-14	109.087 mi
Registration #20	2016-06-14	109.087 mi
Registration #21	2016-06-14	109.087 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1252 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	1736147