



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD VTEC SE EXECUTIVE
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	184 Nm at 4.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	39.8 mpg
Consumption combined	31.0 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-13
Pictures	20
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #25** 2020-12-16 14:28**MOT test number** 328178480829**Result** ✓ Passed**Next expiry date** 2021-12-15

Advice Suspension component mounting prescribed area is corroded but not considered excessive o/s/f & n/s/f (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Drive shaft damaged but serviceable o/s/f & n/s/f corroded (6.1.7 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Windscreen wiper blade defective o/s/f & n/s/f (3.4 (b) (i))

Advice Brake pipe corroded, covered in grease or other material o/s/r & n/s/r (1.1.11 (c))

**MOT #24**

2020-12-10 16:02

MOT test number

452405159304

Result

✗ Failed

- Advice** Drive shaft damaged but serviceable o/s/f & n/s/f corroded (6.1.7 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps o/s/r & n/s/r (4.7.1 (b) (ii))
- Minor** Windscreen wiper blade defective o/s/f & n/s/f (3.4 (b) (i))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Brake pipe corroded, covered in grease or other material o/s/r & n/s/r (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen o/s/f & n/s/f (3.5 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive o/s/f & n/s/f (5.3.6 (a) (i))

MOT #23

2019-11-26 12:23

MOT test number

946452673323

Result

✓ Passed

- Advice** Engine oil level low
- Minor** Offside Front Headlamp reflector slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Headlamp reflector slightly defective (4.1.1 (b) (i))

**MOT #22**

2019-11-22 09:06

MOT test number

499162099030

Result**✗ Failed**

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Front Headlamp reflector slightly defective (4.1.1 (b) (i))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Engine oil level low
- Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Minor** Nearside Front Headlamp reflector slightly defective (4.1.1 (b) (i))

MOT #21

2018-12-11 10:15

MOT test number

720127423116

Result**✓ Passed**

- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20**

2018-12-07 16:58

MOT test number

968962136888

Result**✗ Failed**

- Fail** Front Exhaust has a major leak of exhaust gases & rear exhaust missing (6.1.2 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Engine oil level very low
- Fail** Offside Front Outer Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Emissions not tested engine oil very low (8.2.1.2 (d))
- Fail** Exhaust catalytic converter missing where one was fitted as standard (8.2.1.1 (a))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #19

2018-02-14 14:58

MOT test number

512716665078

Result**✓ Passed**

- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)

**MOT #18**

2018-02-06 09:17

MOT test number

295953243835

Result**✗ Failed****Advice**

Offside Front Road wheel slightly damaged (4.2.A.1a)

Fail

Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail

Front registration plate letter/figure incomplete (6.3.1c)

Fail

Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)

Fail

Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail

Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail

Rear registration plate letter/figure incomplete (6.3.1c)

Advice

Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #17

2017-02-02 15:34

MOT test number

376471440015

Result**✓ Passed****Advice**

Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice

Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #16**

2017-02-02 13:28

MOT test number

652932419751

Result**✗ Failed**

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #15

2016-02-03 16:56

MOT test number

521141964137

Result**✓ Passed**

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Both front floor pans & o/s/r metal brake corrosion

**MOT #14**

2016-02-02 09:29

MOT test number

430918893894

Result**✗ Failed**

- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Both front floor pans & o/s/r metal brake corrosion
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)

MOT #13

2015-02-16 17:00

MOT test number

177417645439

Result**✓ Passed**

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Both front floor pans rusty
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #12**

2015-02-16 09:31

MOT test number

817057145002

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Both rear tyres cracking**Fail** Battery insecure (1.9.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Both front floor pans rusty**MOT #11**

2014-02-18 16:25

MOT test number

176929744463

Result**✓ Passed****Notice** Corrosion on front floors o/s and n/s

**MOT #10** 2014-02-18 09:14**MOT test number** 566579244088**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Side repeater incorrect colour (1.4.A.2f)**Notice** Corrosion on front floors o/s and n/s**Fail** Nearside Side repeater incorrect colour (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-02-06 12:57**MOT test number** 577647833028**Result** ✓ Passed**Notice** Corrossion on o/s and n/s front floors**MOT #8** 2013-02-06 09:07**MOT test number** 919897733080**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Corrossion on o/s and n/s front floors**MOT #7** 2012-02-09 09:25**MOT test number** 105470342420**Result** ✓ Passed**Notice** Corrossion on o/s front floor**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Low effort from o/s handbrake

**MOT #6** 2011-02-14 13:55**MOT test number** 886565741019**Result** ✓ Passed**MOT #5** 2010-02-17 11:26**MOT test number** 250078340043**Result** ✓ Passed**Notice** Noise from o/s rear brake**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-02-19 09:21**MOT test number** 800090559099**Result** ✓ Passed**Notice** Low effort from o/s hand brake**MOT #3** 2008-03-12 16:39**MOT test number** 133382978406**Result** ✓ Passed**Notice** Low effort from o/s handbrake**MOT #2** 2007-06-11 10:42**MOT test number** 523292667114**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2006-06-06 15:13
MOT test number	161507156158
Result	✓ Passed



Damage history


Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2002-04-23
Last registration	2020-12-16
Complete history	See info



Registration #1	2002-04-23	15 mi
Registration #2	2006-06-06	25.883 mi
Registration #3	2007-06-11	28.543 mi
Registration #4	2008-03-12	31.073 mi
Registration #5	2009-02-19	35.382 mi
Registration #6	2010-02-17	40.410 mi
Registration #7	2011-02-14	45.153 mi
Registration #8	2012-02-09	49.749 mi
Registration #9	2013-02-06	54.260 mi
Registration #10	2013-02-06	54.260 mi
Registration #11	2014-02-18	61.809 mi
Registration #12	2014-02-18	61.809 mi
Registration #13	2015-02-16	68.402 mi
Registration #14	2015-02-16	68.402 mi
Registration #15	2016-02-09	75.277 mi
Registration #16	2016-02-09	75.277 mi
Registration #17	2016-02-09	75.277 mi
Registration #18	2016-02-09	75.277 mi
Registration #19	2016-02-09	75.277 mi
Registration #20	2016-02-09	75.277 mi
Registration #21	2016-02-09	75.277 mi
Registration #22	2016-02-09	75.277 mi
Registration #23	2016-02-09	75.277 mi
Registration #24	2016-02-09	75.277 mi
Registration #25	2016-02-09	75.277 mi
Registration #26	2016-02-09	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1750 mm
Height	1430 mm
Length	4595 mm
Kerb weight	1380 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	F20B6E405697