





### General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Black
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg



MK05YLX report date: 2024-03-28

Entry 1			
Date	2021-06-26		
Pictures	6		
Listing price	View report		
	Video viewing with one of our team.   Book a video viewing with one of our team.   See the car from the confect of your own home.	EXEMPTIONS (CONTRACTOR) CONTRACTOR CONTRACTOR) CONTRACTOR C	<b>Cicce waits terrors</b>

source: autotrader.co.uk





MOT history





OT #20	2022-11-02 14:38
OT test number	736862420891
esult	🗙 Failed
<b>Fail</b> Offside Rear Suspension component mounting prescribed area excessively conducting structural strength inner sill (5.3.6 (a) (i))	prroded significantly
Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
<b>Fail</b> Nearside Rear Suspension component mounting prescribed area excessively educing structural strength outer sill (5.3.6 (a) (i))	corroded significantly
Fail   Offside Front Headlamp aim projected beam image is obviously incorrect (4.3)	L.2 (c))
Advice Hand brake cable linkage seized	
<b>Fail</b> Offside Rear Suspension component mounting prescribed area excessively conducing structural strength outer sill (5.3.6 (a) (i))	orroded significantly
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
<b>Fail</b> Nearside Front Suspension component mounting prescribed area excessively educing structural strength inner sill (5.3.6 (a) (i))	<sup>,</sup> corroded significantly
Advice Nearside Rear light reflector damaged	
Fail   Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> Offside Front Suspension component mounting prescribed area excessively c educing structural strength inner sill (5.3.6 (a) (i))	orroded significantly
Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))	
Fail   Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Nearside Front Suspension component mounting prescribed area excessively educing structural strength outer sill (5.3.6 (a) (i))	<sup>,</sup> corroded significantly
Advice Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	
Advice Oil leak	
<b>Fail</b> Offside Front Suspension component mounting prescribed area excessively c educing structural strength outer sill (5.3.6 (a) (i))	orroded significantly
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Centre stop light inop	
Advice Offside Front Lower ball joint nut no locking pin	
Fail Offside Rear Suspension component mounting prescribed area excessively co Check.co.uk	orroded significantly page 4/1

Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly structural strength inner sill (5.3.6 (a) (i))
Advice	Nearside Rear arch corroded
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))





MOT #19		2021-10-21 08:52
MOT test	number	538129091925
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
MOT #18		2020-11-05 13:20

MOT #18	2020-11-05 13:20
MOT test number	433742160617
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Rear Seat belt anchorage prescribed area is corroded but not consisil (7.1.1 (a) (i))	dered excessive under





MOT #17	2020-11-02 14:16
MOT test number	202303302777
Result	🗙 Failed
<b>Fail</b> Nearside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))	
Fail Nearside Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii	))
Fail Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Seat belt anchorage prescribed area is corroded but not considered sill (7.1.1 (a) (i))	ed excessive under
<b>Fail</b> Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Rear Anti-roll bar pin or bush excessively worn d bush (5.3.4 (a) (i))	
Fail Brake pipe excessively corroded both front to rear (1.1.11 (c))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
FailNearside Track rod end ball joint dust cover insecure so that it no longer prevents(2.1.3 (g) (ii))	the ingress of dirt
<b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i))	
MOT #16	2019-04-18 10:59
MOT test number	568526400411

HOT LEST HUMBEN	500520400411
Result	✓ Passed
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #2	15	2018-04-23 14:23
MOT te	st number	489584222725
Result		✓ Passed
<b>MOT</b> #3	14	2018-04-23 08:19
MOT te	st number	259272110850
Result		🗙 Failed
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail	Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Registration plate lamp not working (1.1.C.1d)	
Fail	Nearside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #13		2017-05-02 13:16
MOT test number		614229805948
Result		✓ Passed
MOT #12		2016-04-27 11:33
MOT test number		384833438103
Result		✓ Passed
MOT #11		2016-04-27 11:33
MOT test number		609365731406
Result		🗙 Failed
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)	





MOT #10		2015-04-27 11:14
MOT test	number	107947115179
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
<b>Advice</b> (2.4.G.2)	Nearside Rear Anti-roll bar synthetic bush deteriorated but not resulting in	excessive movement
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Acc damage o/s/r	
Advice	Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
<b>Advice</b> (2.4.G.2)	Offside Rear Anti-roll bar synthetic bush deteriorated but not resulting in e	xcessive movement
Advice	Offside Front Power steering pipe(s) or hose(s) has slight seepage from a s	seal (2.3.3b)
Notice	Oil leak from clutch slave	

MOT #9		2014-04-25 10:29
MOT test	number	885365014129
Result		✓ Passed
<b>Advice</b> (2.4.G.2)	Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in exces	ssive movement
<b>Advice</b> (2.4.G.2)	Nearside Rear Anti-roll bar synthetic bush deteriorated but not resulting in e	excessive movement
Advice	Front Power steering component(s) has slight seepage from a component (2	.3.3b)





MOT #8	2014-04-25 10:29
MOT test number	537985314137
Result	× Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Front Power stee	ering component(s) has slight seepage from a component (2.3.3b)
Advice Offside Rear Ant (2.4.G.2)	i-roll bar rubber bush deteriorated but not resulting in excessive movement
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Nearside Rear A (2.4.G.2)	nti-roll bar synthetic bush deteriorated but not resulting in excessive movement

MOT #7		2013-04-24 12:39
MOT test	number	258664013450
Result		✓ Passed
Notice	Rear brake pads very low and binding on the nearside	
Notice	Front brake pads very low	

MOT #6		2012-05-01 12:00
MOT test	number	416022822177
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	



MOT #5		2011-04-23 12:18
MOT test	number	436723511149
Result		✓ Passed
Notice	Osf tyre inside and outside edges worn	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in ex	cessive movement
(2.4.G.2)		
Notice	Nsf tyre inside and outside edges worn	
Notice	Oil leak	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
<b>Advice</b> (2.4.G.2)	Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in e	excessive movement

МОТ #4	2010-04-28 14:51
MOT test number	622808510167
Result	✓ Passed

МОТ #3		2009-04-25 10:10
MOT test number		332545019174
Result		🗙 Failed
Pass with rectification	Registration plate lamp not working (1.1.5c)	
Pass with rectification	Offside Stop lamp not working (1.2.1b)	

MOT #2	2009-04-25 10:10
MOT test number	761505419121
Result	✓ Passed

MOT #1	2008-05-01 09:51
MOT test number	444702428117
Result	✓ Passed

MK05YLX

report date: 2024-03-28





#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	le l	
Category		Appropriate
Туре		
Damage 2		AMPLE
	K	
Date		1.E
Category		AMP.
Туре		

#### Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-03-02
Last registration	2022-11-02
Complete history	See info



Registration #1	2005-03-02	25 mi
Registration #2	2008-05-01	31.063 mi
Registration #3	2009-04-25	42.638 mi
Registration #4	2010-04-28	51.281 mi
Registration #5	2011-04-23	54.446 mi
Registration #6	2012-05-01	57.318 mi
Registration #7	2013-04-24	60.471 mi
Registration #8	2014-04-25	64.052 mi
Registration #9	2015-04-27	67.197 mi
Registration #10	2016-04-27	70.146 mi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.707 mi
Registration #19		11.777 mi
Registration #20		11.117 mi





### Car features

S0225	Air conditionin
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg
Additional information	
Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 16/16

Number of axles	2
Engine number	D4CB5851164