



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SE
Colour	Red
Year of manufacture	2006
Top speed	124 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-30
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-01-12
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	45
Total items failed	10

MOT #202022-01-13 09:57

MOT test number715569200735

Result✓ Passed

Next expiry date2023-01-12

- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

All suspension components and sub frames corroded
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2022-01-07 17:19

MOT test number

312686520663

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice All suspension components and sub frames corroded

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2021-01-13 15:35

MOT test number

948959804376

Result**✓ Passed**

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2021-01-11 16:57

MOT test number

817687190971

Result**✗ Failed****MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Nearside Front Electrical wiring likely to touch hot or rotating parts ABS sensor (4.11 (a) (iii))**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MAJOR** Nearside Front Brake insecure brake back plate (1.1.21 (c))**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))**MAJOR** Oil leaking excessively from engine @ filter (8.4.1 (a) (i))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #16**

2019-07-23 14:24

MOT test number

241494444143

Result**✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2018-07-19 11:17

MOT test number

856535538028

Result**✓ Passed**

**MOT #14** 2018-07-19 11:17**MOT test number** 554302831065**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2017-06-27 12:32**MOT test number** 663605162438**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit Tyre on legal limit (4.1.E.1)**MOT #12** 2017-06-26 08:43**MOT test number** 893634911235**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit Tyre on legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Emissions not tested (7.3.A.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #11** 2016-06-20 14:44**MOT test number** 374203557062**Result** ✓ Passed

**MOT #10** 2015-06-09 11:07**MOT test number** 389910265159**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight bind on n/s rear brake**Notice** O/s front tyre rubbed on outer wall**MOT #9** 2014-06-28 11:32**MOT test number** 667029974149**Result** ✓ Passed**MOT #8** 2013-07-01 12:47**MOT test number** 167442083153**Result** ✓ Passed**MOT #7** 2012-10-23 12:47**MOT test number** 537757792291**Result** ✓ Passed**MOT #6** 2012-10-23 12:47**MOT test number** 335777492478**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2011-10-13 15:31**MOT test number** 937196781265**Result** ✓ Passed**Notice** Rear heat shield insecure

**MOT #4** 2011-10-13 11:03**MOT test number** 378456781430**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Front discs worn**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Rear heat shield insecure**MOT #3** 2010-10-28 13:19**MOT test number** 903051400398**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-10-28 11:07**MOT test number** 264701600354**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-10-16 14:58**MOT test number** 724859889299**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-11-21
Last registration	2022-01-13
Complete history	See info



Registration #1	2006-11-21	27 mi
Registration #2	2009-10-16	7.626 mi
Registration #3	2010-10-28	14.910 mi
Registration #4	2010-10-28	14.910 mi
Registration #5	2011-10-13	23.025 mi
Registration #6	2011-10-13	23.027 mi
Registration #7	2012-10-23	31.157 mi
Registration #8	2013-07-01	31.208 mi
Registration #9	2014-06-28	35.843 mi
Registration #10	2015-06-09	39.416 mi
Registration #11	2016-06-20	44.388 mi
Registration #12	2016-06-20	44.388 mi
Registration #13	2016-06-20	44.388 mi
Registration #14	2016-06-20	44.388 mi
Registration #15	2016-06-20	44.388 mi
Registration #16	2016-06-20	44.388 mi
Registration #17	2016-06-20	44.388 mi
Registration #18	2016-06-20	44.388 mi
Registration #19	2016-06-20	44.388 mi
Registration #20	2016-06-20	44.388 mi
Registration #21	2016-06-20	44.388 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1412 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC5426630