





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Grey
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date	2021-01-31	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/15



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-01-12
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	43
Total items failed	25

MOT #19	2024-01-13 12:29
MOT test number	837153097908
Result	✓ Passed
Next expiry date	2025-01-12

MOT #18	2023-01-11 10:01
MOT test	number 229174627097
Result	✓ Passed
Advice	Rear Wiper torn
Advice	High level brake light innoperative
Advice	Front Tyre worn close to legal limit/worn on edge Both worn on outer edges 215/60/16 (5.2.3 (e))
Advice	Exhaust flexi deteriorating
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Inner face's (1.1.14 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)

CarCheck.co.uk page 3/15



Advice

Rear Wiper torn

AJ57WZU report date: 2024-03-29

MOT #17 2023-01-10 10:57 **MOT** test number 982636781114 Result **X** Failed Fail Stop lamp(s) all not working (4.3.1 (a) (iii)) Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Front Tyre worn close to legal limit/worn on edge Both worn on outer edges 215/60/16 (5.2.3 (e)) Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) Fail **Advice** Offside Front Play in steering rack inner joint(s) Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Advice **Advice** Exhaust flexi deteriorating **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Inner face's (1.1.14 (a) (ii)) Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Fail Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

MOT #16	2022-01-13 1	13:43
MOT test	number 33755258	6817
Result	✓ Pa	assed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Exhaust flexi deteriorated	
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) ((i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Shock absorbers has light misting of oil both (5.3.2 (b))	

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #15 2021-01-12 14:33

262574081948 **MOT** test number

Result Passed

Advice Exhaust silencer slightly loose tailpipe (8.1.1 (b) (i))

Minor Offside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14 2018-03-15 13:23

MOT test number 679269333929

Result ✓ Passed

Advice Offside Rear tyre worn, inner edge

MOT #13 2017-11-10 14:09

595575136787 **MOT** test number

Result ✓ Passed

2017-11-09 10:49 **MOT #12**

MOT test number 840837729286

Result × Failed

Fail Emissions not tested (7.4.B.1)

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

Fail Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

Fail Central Exhaust has a major leak of exhaust gases (7.1.2)

Fail Front registration plate deteriorated (6.3.1d)

Fail Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 5/15



MOT #11 2016-11-29 13:40

MOT test number 933492957166

Result ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice Nearside Rear tyre has nails stuck in

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2016-11-29 09:14

MOT test number 569530733726

Result X Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Nearside Rear tyre has nails stuck in

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Rear registration plate deteriorated (6.3.1d)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



Result

(2.4.G.2)

(2.4.G.2)

Advice

AJ57WZU report date: 2024-03-29

× Failed

MOT #9 2015-10-27 14:46

MOT test number 175718416402

Result ✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #8 2015-10-27 09:57

MOT test number 874520248479

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #7 2014-10-29 10:07

MOT test number 409712504356

Result \(\sqrt{Passed} \)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #6 2013-10-29 17:31

MOT test number 375232203371

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/15



AJ57WZU

report date: 2024-03-29

MOT #5 2012-11-06 16:29

MOT test number 675511712328

MOT #4 2012-11-06 14:38

MOT test number 919221712356

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #3 2011-11-16 17:19

MOT test number 755660821316

Result ✓ Passed

MOT #2 2011-11-10 11:20

MOT test number 926934811328

Result ★ Failed

Fail Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

Fail Centre Exhaust has a major leak of exhaust gases (7.1.2)

Fail Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

Fail Emissions not tested (7.0)

MOT #1 2010-11-19 09:47

MOT test number 624533620308

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-


CarCheck.co.uk page 9/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



O	history
IWADAL	
	IIISLUIV

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-04
Last registration	2024-01-13
Complete history	See info



Registration #1	2008-01-04	19 mi
Registration #2	2010-11-19	31.043 mi
Registration #3	2011-11-10	43.164 mi
Registration #4	2011-11-16	43.331 mi
Registration #5	2012-11-06	55.900 mi
Registration #6	2012-11-06	55.911 mi
Registration #7	2013-10-29	69.037 mi
Registration #8	2014-10-29	82.291 mi
Registration #9	2015-10-27	94.890 mi
Registration #10	2015-10-27	94.890 mi
Registration #11	2016-11-29	109.390 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		
Registration #18		1.77 m
Registration #18 Registration #19		1.77 m
-		1.77 m

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/1

Number of axles 2

Engine number 8R43181