



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML 270 CDI
Colour	Green
Year of manufacture	-
Top speed	115 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	370 Nm at 1.800 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	23.2 mpg
Consumption extra urban	35.3 mpg
Consumption combined	29.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-04
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #20 2021-12-10 08:25

MOT test number 319625184461

Result ✗ Failed

- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- MAJOR** Brake performance not tested (1.2.1 (g))
- MAJOR** Nearside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Towbar component excessively damaged wiring plug (6.1.6 (a))
- MAJOR** Offside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))



MOT #192020-11-04 11:11

MOT test number406834088766

Result

✓ Passed

- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Oil leak
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18**

2020-10-29 11:58

MOT test number

524927224517

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Oil leak
- MAJOR** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))

MOT #17

2019-11-06 17:04

MOT test number

454283213358

Result**✓ Passed**

- Advice** Brake disc worn, but not excessively front & rear (1.1.14 (a) (i))

**MOT #16**

2019-11-06 11:52

MOT test number

160857005976

Result**✗ Failed**

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Brake disc worn, but not excessively front & rear (1.1.14 (a) (i))

MOT #15

2016-06-01 09:04

MOT test number

356974675112

Result**✓ Passed**

- Advice** Trays and covers fitted
- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Both rear disc's corroding
- Advice** Brake pipe slightly corroded both front to rears (3.6.B.2c)
- Advice** Rear Suspension arm has slight play in a ball joint both (2.4.G.2)

**MOT #14**

2016-05-27 08:41

MOT test number

461685805362

Result**✗ Failed****Fail** Offside Rear Anti-roll bar missing (2.4.G.1)**Advice** Trays and covers fitted**Advice** Brake pipe slightly corroded both front to rears (3.6.B.2c)**Advice** Rear Suspension arm has slight play in a ball joint both (2.4.G.2)**Fail** Headlamp excessively deteriorated so that the light output is severely reduced both (1.7.5a)**Advice** Both rear disc's corroding**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**MOT #13**

2015-06-09 14:08

MOT test number

207660965120

Result**✓ Passed****Notice** O/s/f brake pipe starting to rust**Notice** Rear brake pipes greased**Notice** Rear discs corroding

**MOT #12**

2015-06-06 09:04

MOT test number

666447355130

Result**✗ Failed****Fail**

Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice

Rear discs corroding

Fail

Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)

Notice

O/s/f brake pipe starting to rust

Fail

Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Fail

Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Notice

Rear brake pipes greased

MOT #11

2014-06-06 16:56

MOT test number

149127954149

Result**✓ Passed****Advice**

Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2014-06-03 09:43

MOT test number

385684454175

Result**✗ Failed**

- Fail** Offside Front Anti-roll bar synthetic mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Offside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Steering rack gaiter split (2.2.D.2d)
- Fail** Nearside Front Anti-roll bar synthetic mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Advice** Headlamp deteriorated but light output not reduced (1.7.5a)
- Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)
- Fail** Offside Rear coil spring broken (2.4.C.1a)

MOT #9

2013-06-05 14:32

MOT test number

139156453122

Result**✓ Passed**



MOT #8	2012-05-01 10:41
MOT test number	428192622192
Result	✓ Passed
Advice	Offside Steering rack gaiter deteriorated (2.2.D.2d)
Advice	Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #7	2011-05-12 14:16
MOT test number	845542431110
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2010-10-18 10:48
MOT test number	830591490265
Result	✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #5	2009-10-31 10:55
MOT test number	712024009333
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.2.B.1f)



MOT #4	2008-10-06 16:27
MOT test number	391500788283
Result	✓ Passed
MOT #3	2008-10-01 15:50
MOT test number	394715778463
Result	✗ Failed
<div><div>Advice</div> Brake disc slightly pitted (3.5.1h)</div> <div><div>Fail</div> Offside Front Track rod end ball joint has excessive play (2.2.B.1f)</div>	
MOT #2	2007-10-08 14:49
MOT test number	472811787263
Result	✓ Passed
MOT #1	2007-04-05 14:48
MOT test number	761005097078
Result	✓ Passed




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	W608XAX
Plate since	2019-03-29
Current registration	W608XAX
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-03-23
Last registration	2021-12-10
Complete history	See info



Registration #1	2000-03-23	17 mi
Registration #2	2007-04-05	72.078 mi
Registration #3	2007-10-08	75.667 mi
Registration #4	2008-10-01	82.129 mi
Registration #5	2008-10-06	82.129 mi
Registration #6	2009-10-31	89.597 mi
Registration #7	2010-10-18	96.647 mi
Registration #8	2011-05-12	100.880 mi
Registration #9	2012-05-01	106.889 mi
Registration #10	2013-06-05	107.046 mi
Registration #11	2014-06-03	117.266 mi
Registration #12	2015-06-03	121.277 mi
Registration #13	2016-06-03	125.288 mi
Registration #14	2017-06-03	129.299 mi
Registration #15	2018-06-03	133.310 mi
Registration #16	2019-06-03	137.321 mi
Registration #17	2020-06-03	141.332 mi
Registration #18	2021-06-03	145.343 mi
Registration #19	2022-06-03	149.354 mi
Registration #20	2023-06-03	153.365 mi
Registration #21	2024-06-03	157.376 mi
Registration #22	2025-06-03	161.387 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2190 mm
Height	1820 mm
Length	4710 mm
Wheel base	2820 mm
Kerb weight	1970 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	61296330020471